

MOOREBANK LOGISTICS PARK

Moorebank Precinct East: Six-Monthly Operations Compliance Report

Report: #5

Period: May 2022 - November 2022

16 FEBRUARY 2023

SYDNEY INTERMODAL TERMINAL ALLIANCE

May 2022 - November 2022

Author	██████████	██████████
Checker	██████████	██████████
Approver	██████████	██████████

Date 24/02/2023
Revision Text 00

Author Details

Author Details	Qualifications and Experience
██████████	BSc Environmental Science

REVISIONS

Revision	Date	Description	Prepared by	Approved by
00	Friday, 24 February 2023	Final	Tactical Group	██████████

KEY TERMS AND ACRONYMS

Acronym/Term	Meaning
CNBMP	Container Noise Barrier Management Plan
CoC	Conditions of Consent
DPIE	Department of Planning, Industry and Environment (previously Department of Planning and Environment)
DPI&E	Department of Planning, Industry and Environment
EPBC Act	Environmental Protection and Biodiversity Conservation Act 1999
ERP	Emergency Response Plan which includes the Bushfire Emergency and Evacuation Plan (BEEP), Bushfire Management Plan (BMP) and Flood Emergency Management Plan (FEMP)
IMEX	Import Export
MLP	Moorebank Logistics Park
OAQMP	Operational Air Quality Management Plan
OCR	Six Monthly Operational Compliance Report
OCCS	Operational Community Communication Strategy
OEMP	Operational Environmental Management Plan
ONVMP	Operational Noise and Vibration Management Plan
OTAMP	Operational Traffic and Access Management Plan
OWRMP	Operational Waste and Resource Management Plan
POCR	Pre-operations Compliance Report
POPD	Program for Operational Phase Delivery
SIOMP	Operational Stormwater Infrastructure and Operation and Maintenance Plan
SSD	State Significant Development
UDLP	Urban Design and Landscape Plan
WTP	Workplace Travel Plan
SSD 6766	Stage 1 of the MPE Concept Approval (MP 10_0193) as approved under SSD 6766. It involves the construction and operation of an IMEX terminal and associated Rail Link.
SSD 7628	Stage 2 of the MPE Concept Approval (MP 10_0193) as approved under SSD 7628. It involves the construction and operation of warehousing and distribution facilities on the MPE site and upgrades to approximately 1.5 kilometres of Moorebank Avenue from approximately 35 metres south of the northern boundary of the MPE site to approximately 185 metres south of the southern MPE site boundary.

TABLE OF CONTENTS

REVISIONS	II
KEY TERMS AND ACRONYMS	III
LIST OF TABLES	V
1 EXECUTIVE SUMMARY	6
1 INTRODUCTION	7
1.1 Project Overview	7
1.2 Project Approvals	7
1.3 Scope and Purpose	7
2 PROJECT DESCRIPTION	8
2.1 Site Location	8
2.2 Scope of Works	9
2.3 Operational activities undertaken	9
2.4 Environmental Monitoring	10
2.4.1 Air Quality Monitoring	10
2.4.2 Noise Monitoring	11
2.4.3 Water Quality Monitoring	12
2.4.4 Storm Water Infrastructure	12
2.4.5 Biodiversity Monitoring	12
2.4.6 Biannual Trip and Origin Destination Report	14
2.5 Previous Report Actions	14
2.6 Incidents	14
2.7 Complaints Management	14
APPENDIX A - SSD 6766 CONDITIONS OF CONSENT	15
APPENDIX B - SSD 7628 CONDITIONS OF CONSENT	16
APPENDIX C – AIR QUALITY MONITORING COMPLIANCE REPORT	17
APPENDIX D – NOISE MONITORING REPORTS	18
APPENDIX E - B106/B43 REPORT	19
APPENDIX F – MPE OPERATIONS INCIDENT REGISTER	20
APPENDIX G - COMPLIANCE REPORT DECLARATION FORM	21



LIST OF FIGURES

Figure 1 - MLP East Precinct Layout – sourced SIMTA MPE OEMP Rev 15..... 8
Figure 2 - Air quality monitoring locations..... 11

LIST OF TABLES

Table 1 - MLP East Precinct Biodiversity Recommended actions.....12

1 EXECUTIVE SUMMARY

In accordance with SSD 7628 Condition of Consent (CoC) C21(c)(iii), a Six-monthly operational compliance report (OCR) must be prepared.

The Department approved the Program for Operational Phase Delivery (POPD) on 21 May 2019 which outlined the staged submission of operational documents under condition A14 of SSD 7628. The Department also considered the combining of strategies, plans or programs to be acceptable, provided that all relevant conditions across both SSD 6766, and SSD 7628 are met.

Regular reviews of compliance against the *Environmental Protection and Biodiversity Conservation Act 1999* (EPBC 2011/6229) Conditions of Approval are undertaken but are not the subject of this compliance report.

This OCR has been prepared in accordance with the requirements of the *Compliance Reporting Post Approval Requirements (NSW DP&E, June 2018)* and has been prepared to outline the progress of compliance for all operational requirements against the Project Approvals from May 2022 - November 2022

–.

1 INTRODUCTION

1.1 Project Overview

Application Number	
Project name:	Moorebank Logistics Park – Operational Area 1 and 2
Proponent	Sydney Intermodal Terminal Alliance (SIMTA) as Logos Property
Site Address	MLP East Precinct site, Moorebank Avenue, Moorebank
Project Phase	Six Monthly Operation Compliance Report (OCR)
Project Activity	Operation of an import-export terminal, rail link and warehouse and distribution facilities and associated infrastructure.
Report date	Friday, 24 February 2023

1.2 Project Approvals

Approval for the construction and operation of the MLP East Precinct was obtained progressively as follows:

- SIMTA Moorebank Intermodal Terminal Facility dated 6 March 2014 (EPBC 2011/6229)
- Moorebank Precinct East (MPE) Concept Approval – 10_0193
- MPE Stage 1 – SSD 6766
- MPE Stage 2 – SSD 7628
- MPE Stage 2 – SSD 7628 – Subdivision partial development consent
- MPE Stage 2 – SSD 7628_MOD 1 – Modification 1
- MPE Stage 2 – SSD 7628_MOD 2 – Modification 2 boundary adjustment and basin 9 design adjustment
- MPE Stage 2 – SSD 7628_MOD 3 – Modification 3
- MPE Stage 2 – SSD 7628_MOD 3 – Modification 4

1.3 Scope and Purpose

In accordance with SSD 7628 Condition C21 (c) (iii), a Six-Monthly Operation Compliance Report (OCR) is required to outline progress of compliance for all operation requirements against the MPE Stage 1 and Stage 2 approval.

There is no specific requirement under SSD 6676 for the submission of an OCR, however this report has been prepared to address the operational requirements for both SSD 6766 and SSD 7628 and has been prepared in accordance with the requirements of the *Compliance Reporting Post Approval Requirements* (NSW DP&E, June 2018).

2 PROJECT DESCRIPTION

2.1 Site Location

The Moorebank Logistic Park (MLP) is an integral component of the Freight, Ports and Transport strategies of both the NSW and Commonwealth governments to help manage the challenges of an expected tripling of freight volumes at Port Botany by 2031.

The MLP aims to streamline the freight logistics supply chain from port to store, deliver savings to businesses and consumers, and help service the rapidly growing demand for imported goods in south-west Sydney. It is located approximately 27 kilometres (km) south-west of the Sydney Central Business District and approximately 26 km west of Port Botany within the Liverpool Local Government Area. The MLP is divided into an East Precinct and a West Precinct, located east and west of Moorebank Avenue, respectively.

The MLP East Precinct commenced operations in May 2020 and is the subject of this Operation Compliance Report (OCR), while the MLP West Precinct is still currently under construction.



Figure 1 MLP East Precinct Layout – sourced SIMTA MPE OEMP Rev 1

2.2 Scope of Works

The main features of the MLP East Precinct include:

- The Import Export (IMEX) Terminal. The IMEX Terminal comprises:
 - Truck processing, holding, and loading areas with an entrance and exit from Moorebank Avenue.
 - Rail loading and container storage areas serviced by container handling equipment
 - An Administration facility and associated car parking with light vehicle access from Moorebank Avenue.
- A Rail Link connecting the IMEX terminal and the Southern Sydney Freight Line (SSFL) traversing Moorebank Avenue, Anzac Creek and Georges River.
- Associated ancillary infrastructure including signage, lighting, landscaping, water management.
- Warehouse and distribution facilities including warehousing up to 21 m in height, typically ranging in size from 20,000 m² to 62,000 m². Individual warehouses typically comprise the following:
 - Office and administration facilities
 - Amenities
 - Car parking
 - Truck loading/unloading docks
 - Internal parking for pick-up and delivery vehicles (PUD)
 - Specialised sortation and conveyor equipment
 - Hardstand areas that provide trailer parking spaces, external PUD parking spaces, vehicle manoeuvring areas and access to the main internal site road
 - Signage for business identification purposes, including backlit illuminated signage on each warehouse
 - Internal fit out, comprising racking and storage.
- A freight village including a mix of retail, commercial and light industrial spaces typically up to 15 m in height and varying in size and design.
- An internal road network to enable efficient movement of vehicles, dispatch of freight from the warehouses and transport of containers between the IMEX Terminal and warehouse and distribution facilities.
- Security and Administration offices and demountable.

2.3 Operational activities undertaken

Documents can be submitted in stages as permitted by CoC A14 and CoC A15. The application of the operational documents will be staged to take progressive effect across the MLP East Precinct site as construction is completed and operations commences was detailed in the POPD approved by the DPIE on 21 May 2019.

This OCR has been prepared in accordance with the requirements of the Compliance Tracking Program (CTP) to outline progress of compliance for all operation requirements against both SSD 6766 and SSD 7628. This OCR covers the period from November 2022 to May 2022.

The following works have been undertaken:

- Movement and storage of containers in and out of the terminal via rail
- Truck processing, holding, and loading areas.
- Primary and secondary container loading/ unloading areas.

- Transfer of containers between terminal and warehouses vis internal transfer vehicles
- Pickup and delivery of goods to warehouses via truck movements
- Warehouses 1, 3a, 3b, 4a, 4b and 5 are occupied and operational.
- Warehousing and Administrative Activities
- Additional Warehouse Construction (6,7,8)
- Security, maintenance and monitoring of all infrastructure and equipment related to the above activities.

Project Compliance Summary

This OCR outlines the progress of compliance for all operational requirements against Project Approvals. Compliance against the project CoC and the Final Compilation of Mitigation Measures (FCMM) are outlined in SSD 6766 Conditions of Consent and SSD 7628 Conditions of Consent, Appendix A and B respectively.

A declaration of compliance is available in **Appendix G**.

2.4 Environmental Monitoring

In accordance with the CoC and OEMP, environmental monitoring activities are required to be undertaken for the operation phase of the MPE Stage 1 and Stage 2 project. These activities include air quality monitoring, noise monitoring, storm water infrastructure and water quality monitoring, Biodiversity Monitoring, and Biannual trip and origin destination reports. A summary of the monitoring results required for this reporting period is addressed in the following sections. The full reports for each of these monitoring requirements are available in the Appendices Section.

2.4.1 Air Quality Monitoring

Results during this reporting period are as follows:

The following summarises the monitoring results for this reporting period:

- No exceedances of the annual average criteria occurred for PM2.5.
- Two exceedances (out of 181 days) of the PM10 24-hour average criteria during the reporting period (about 1%).
 - One exceedance occurred on 11 November 2021 and the other on 6 January 2022.
 - No exceedances corresponded to times when trains were entering/exiting MLP Precinct East.
 - The exceedances coincided with higher readings overnight and during the early morning periods.
 - Investigations at MLP Precinct East upon receipt of the exceedances has not identified significant dust or emissions issues from MLP Precinct East.
 - Both exceedances were recorded at AQM03 which is the monitor located on the western boundary of the site. Causes of the recorded exceedances may be attributed to construction activities relating to MLP Precinct West.
 - No out of hours deliveries for MPW Stage 2 occurred on the observed exceedance days.
- No exceedance of the dust deposition (insoluble solids) 2 g/m²/month (incremental) or 4 g/m²/month (cumulative) criteria was observed during the reporting period.
- AQM03 recorded above the NO₂ 1-hour criteria (0.12 ppm / 120 ppb) every day between 1 November 2021 and 12 November 2021. Recordings fluctuated between 236 ppb and 244 ppb each day. The monitor was taken offsite for maintenance and recalibration after 12 November 2021 and returned on 20 December 2021, where recordings were below criteria. None of the other stations recorded any exceedances between November 2021 and April 2022.
- There were no exceedances of the CO criteria (9.0 ppm) for the period.

The Six-Monthly Compliance Operational Air Quality reports completed during this period are available in **Appendix C** of this report. Actioning requirements and recommendations raised from the report are consistently being addressed as a part of daily operations.

2.4.2 Noise Monitoring

Noise monitoring measurements have been performed, consistent with the requirements of SSD 6766 and SSD 7628 and the Operational Noise and Vibration Management Plan. During this reporting period the following noise measurements were undertaken:

- Continuous Noise Monitoring
- Angle of Attack Rail Noise Report – (Data for the period was unavailable due to monitoring equipment failure refer to DPIE correspondence dated 9/12/22).
- Warehouse Noise Mechanical Plant monitoring occurred for relevant operational warehouses during the period.

No exceedances of the planning approval noise limits were measured during the period. 18 complaints were received in relation to operational noise levels. These complaints were managed in accordance with the complaints reporting procedure.

Annual noise monitoring reports will be located in **Appendix D** of this report in June 2023. Actioning requirements and recommendations raised from the report are consistently being addressed as a part of daily operations.

2.4.3 Water Quality Monitoring

The baseline monitoring forms the basis for the ongoing Biodiversity Monitoring Strategy (BMS) to assess stream health in accordance with CoC B106, to determine any change in stream health or water quality throughout the life of the Project and to ascertain whether these changes can be attributed to the Project works. The BMS outlines monitoring requirements and includes the Stormwater Monitoring Strategy required by CoC B43 and B44.

Examination of the results from the 2022 surveys found no evidence of changes in the indicator variables (bed and bank stability, water quality, assemblages of aquatic macroinvertebrates and fish) that could be attributed to the Project works. Thus, in accordance with the Biodiversity Monitoring Strategy, no adaptive management contingency measure was triggered.

Water quality monitoring report and infrastructure inspection reports are available in **Appendix E** of this report. Actioning requirements and recommendations raised from the report are consistently being addressed as a part of daily operations.

2.4.4 Storm Water Infrastructure

Stormwater infrastructure managed under the Stormwater Infrastructure Operation and Maintenance Plan were inspected and assessed during the period. No significant actions were required for the operation of Stormwater infrastructure at the site.

The annual independent audit was undertaken in July 2022 by a suitably qualified WSUD professional. The audit verified that the condition of the treatment system(s) was compliant and working as intended, verified that the system(s) has been cleaned adequately, verified there was no excessive build-up of material in the system(s) and identified any issues with the treatment system(s) which require rectification for the system(s) to adequately perform its intended function.

2.4.5 Biodiversity Monitoring

The following Biodiversity Monitoring are required to be undertaken in Spring 2021.

- Monitoring of weed cover
- Monitoring of threatened species occurrence
- Monitoring of viability of native vegetation adjoining the rail easement
- Monitoring of feral fauna occurrence
- Monitoring of Nest boxes

The Biodiversity (Flora and Fauna) monitoring report has been provided to the department for information. Actioning requirements and recommendations raised from the report are consistently being addressed as a part of daily operations.

Results during this reporting period:

Lands adjoining the Rail Link (BA341 lands)

- Native vegetation adjoining the Rail Link is in good condition and has a similar condition to what was recorded in last year monitoring event. There has been a minor increase in weeds, however this has been restricted to disturbed areas immediately adjacent to the Rail Link. Weeds are mostly present in areas which were disturbed during construction of the rail link rather than in areas of intact native vegetation that did not experience disturbance. From observations, it is evident that most exotic species within the Rail Link are not able to readily colonise adjacent areas of bushland. This may be due to the low fertility of the naturally occurring sandy soils which are not suitable to exotic species, and high competition from regenerating native species. The weed

species *Senecio madagascariensis* (Fireweed) and *Eragrostis curvula* (African Lovegrass) were recorded on the edges of native vegetation, which have potential to infiltrate natural areas. However, neither of these weed species were observed to be degrading the condition of native vegetation during monitoring.

- The number of individuals of the threatened plant species *Grevillea parviflora* subsp. *parviflora* (Small-flower Grevillea) and *Hibbertia puberula* subsp. *puberula* has increased since last year's monitoring event. Individuals of these species appeared to be in a healthy condition with some bearing flowers and seed. The number of *Acacia bynoeana* (Bynoe's Wattle) within the monitored area has experienced a decline with half the number of individuals re-found (3 individuals) during the monitoring event. The individuals re-found did not appear to be in a healthy condition. It is unknown why this species has experienced decline over the past year. There are no signs to suggest current management practices within the Rail Link (or lack) of has negatively impacted on this species.

Riparian vegetation management (RVMP reporting)

- Anzac Creek management site was not monitored as no bush regeneration works have occurred in this location to date.
- Georges River management site was monitored.
- Revegetated areas continue to grow and colonise bare areas, specifically on the floodplain and lower batters. The high cover of native species in these areas has suppressed the growth of weeds, however some aggressive weed species were observed and present a risk to the future condition of the area. Some aggressive weed species observed which will require control include *Cardiospermum grandiflorum* (Balloon Vine), *Arundo donax* (Giant Reed) and *Ligustrum sinense* (Small-leaved Privet).
- Areas further from the Georges River which had remnant vegetation and were improved through bush regeneration works including weed control are in a moderate condition. A suite of native species area present which contribute to a moderate to high vegetative cover. Weeds are present in these areas however do not comprise infestations.

Koala management & fencing

- The condition of perimeter fencing, separating the Wattle Grove offset area from the MPE operation facility, is similar to what was observed during the previous years monitoring event. Over the 2021/2022 monitoring year a number of sections along the perimeter fence and at access gates, which were identified to have holes or facilitate Koala access to the MPE operational facility, were reinforced with additional lengths of Cyclone fencing. Cyclone fencing was approved by Dr. Phillips for being suitable Koala exclusion fencing at the MLP site (Cumberland Ecology 2020).
- No Koala structures (bridges, culverts, refuge posts) have been installed to prevent the movement of Koalas into the MPE operational facility or facilitate the movement of Koala from the Wattle Grove offset area to adjoining areas of suitable habitat in the Holsworthy defence areas.

Feral animals and weeds

- Four species of feral animal were recorded in Wattle Grove offset area, immediately adjacent to the MPE operational facility including *Lepus europaeus* (Brown Hare), *Felis catus* (Domestic Cat), *Vulpes vulpes* (Red Fox) and *Rattus rattus* (Black Rat). It is expected that these feral animals are using the MPE operational facility when moving around the local landscape.
- *Felis catus* (Domestic Cat) and *Vulpes vulpes* (Red Fox) were captured on camera with prey species (i.e native wildlife). These feral animals are having a direct impact on native wildlife within adjacent bushland areas.

Nest Box Monitoring

- On the 23 and 24 March 2022, a senior ecologist from Arcadis was assisted by two tree climbers from Plateau Trees to relocate and repair nest boxes in the Bootland and Georges River Corridors. Despite the wet conditions, the team were able to assess 29 nest boxes and climbed on 41 occasions to remove and reinstall boxes. Nest boxes that required maintenance were repaired and reinstalled on the same tree at a lower more management height.
- Nest Box Monitoring occurred in Spring 2022.

Fauna connectivity

- Surveys were undertaken in 2022 to assess fauna habitat connectivity, determine feral animal presence and review the effectiveness of fauna habitat features relevant to the operation of the MPE facility.
- Native and feral animals were recorded using the Anzac Creek culvert and moving across the ballast beneath the Rail Link bridge. The fauna furniture at Anzac Creek culverts remains functional.
- The Cyclone mesh fencing beneath the Rail Link bridge is preventing the movement of macropods species and potentially Koala between the Moorebank offset area and riparian vegetation to the south.

Weeds

- Weed cover across the MPE operation facility is generally low and has been effectively managed across the 2021/2022 monitoring year.
- Works are ongoing within the Rail Link to suppress weeds and promote the germination and establishment of native species following a rehabilitation project undertaken by CPB contractors

2.4.6 Biannual Trip and Origin Destination Report

The BTODR addresses the relevant requirements of the Project Approvals and other guidelines and standards applicable during operations of MPE. The BTODR is proposed to keep an accurate record of the shipping containers and vehicle arrivals / departures against approved volumes.

The data provided within this report has been collected in accordance with the BTODR Framework report and enables a comparative assessment of traffic accessing the Site and future growth in operational activities.

All data is a fair and accurate representation of the operational traffic for MPE and its surrounding road network. This data has been collected for the reporting period between May and October 2022 .

The Biannual trip and origin destination report has been completed for this period and has been provided to Secretary for information in accordance with B28.

2.5 Previous Report Actions

The previous Six-Monthly Operational Compliance Report had no actions identified. Ongoing actions being tracked will be reported in the next Six-Monthly Operational Compliance Report.

2.6 Incidents

There were no operational incidents reported in MPE operations in the reporting period.

2.7 Complaints Management

No complaints were received relating to MPE operations in this period.



APPENDIX A - SSD 6766 CONDITIONS OF CONSENT

COMPLIANCE REQUIREMENT	UNIQUE (ID)	COMPLIANCE REQUIREMENT	DEVELOPMENT PHASE	COMPLIANCE STATUS	MONITORING METHODOLOGY	EVIDENCE AND COMMENTS
SSD 6766	A1	The Applicant shall carry out the development generally in accordance with the: a. State Significant Development Application SSD 6766; b. SIMTA Intermodal Terminal Facility – Stage 1 – Environmental Impact Statement (Hyder Consulting Pty Ltd, May 2014); c. SIMTA Intermodal Terminal Facility – Stage 1 – Response to Submissions (Hyder Consulting Pty Ltd, September 2015); and d. The conditions of this consent.	All	Ongoing	Compliance Monitoring	To the extent it relates to MPE Stage 1. All sources referred to are included in the project obligations register and OEMP.
SSD 6766	A2	In the event of an inconsistency between: a. the conditions of this approval and any document listed from condition A1(a) to A1(c) inclusive, the conditions of this approval shall prevail to the extent of the inconsistency; and b. any document listed from condition A1(a) to A1(c) inclusive, and any other document listed from condition A1(a) to A1(c) inclusive, the most recent document shall prevail to the extent of the inconsistency.	All	Ongoing	Monitoring Documentation	
SSD 6766	A3	The Applicant shall comply with any reasonable requirement(s) of the Secretary arising from the Department's assessment of: a. any reports, plans or correspondence that are submitted in accordance with this consent; and b. the implementation of any actions or measures contained within these documents.	All	Ongoing	Compliance Monitoring	
SSD 6766	A4	This approval will lapse ten years from the date of this approval unless works the subject of this approval are physically commenced, on or before that lapse date.	All	Compliant	Compliance Monitoring	
SSD 6766	A5	In the event of a dispute between the Applicant and a public authority, in relation to this approval, either party may refer the matter to the Secretary for resolution. The Secretary's resolution of the matter shall be binding on the parties.	All	N/A	CEMP	There have been no disputes within this reporting period.
SSD 6766	A6	Any advice or notice to the consent authority shall be served on the Secretary	All	N/A	CEMP	There have been no notices or advice within this reporting period.
SSD 6766	A7	The applicant shall ensure that all licences, permits, consents and approvals are obtained and maintained as required throughout the life of the development. No condition of this consent removes the obligation of the Applicant to obtain, renew or comply with such licences, permits or approvals. The Applicant shall ensure that a copy of this consent and all relevant environmental licences, permits, consents and approvals are available on the site that all times during the development and made available on the Project Website.	All	Ongoing	CEMP	Required licences, permits, consents and approvals required prior to construction are being progressively obtained. E25 Report to be uploaded to Website once complete.

SSD 6766	C19	<p>The Applicant shall ensure that the construction and operation of the proposed development will not prevent the existing use of Moorebank Avenue as a public road to a standard commensurate to its current use prior to the development.</p> <p>Note: temporary closures or part closures and changes to the operation of Moorebank Avenue may occur for limited periods during construction as detailed in the Construction Traffic Management Plan</p>	All	Compliant	CTAMP	The OTAMP was approved 6/12/2019
SSD 6766	G1	<p>Within 6 weeks of commencement of operation, unless otherwise agreed by the Secretary, the Applicant shall undertake road pavement deflection testing of the truck routes as defined by Condition E34(a). If the deflection tests show an increase in deflection as a result of the truck routes associated with construction, the Applicant shall undertake pavement rehabilitation of the affected road pavements to achieve the pavement deflection that existing prior to the commencement of works.</p>	operation	Not Triggered	OTMP	Condition Superseded by email 22/2/2019
SSD 6766	G2	<p>Within 3 months of commencement of operation, unless otherwise agreed by the Secretary, the Applicant shall carry out rectification work to the extent of the damage resulting from the construction works at the Applicant's expense and to the reasonable requirements of the owners.</p>	operation	Not Triggered	OTMP	Condition Superseded by email 22/2/2019
SSD 6766	G3	<p>Within 3 months of commencement of operation, the Applicant shall provide to the Certifying Authority evidence that all easements required by this approval, and other licences, approvals and consents, have been lodged for registration or registered at the NSW Land and Property Information.</p>	operation	Not Triggered	OTMP	No easements exist or are required under the MPE Stg 1 footprint. Easements will be required under MPE Stg 2 footprint (separate to this approval). This will not be triggered under MPE Stg 1.
SSD 6766	G4	<p>Signage shall be installed in accordance with Drawing A3001 Issue C (Terminal – Signage Details) dated 14/04/2015, unless otherwise agreed by the Secretary.</p>	operation	Compliant	Road Pavement Deflection Report	Signages with the Terminal are per approved detailed design drawings
SSD 6766	G5	<p>The quantities of Dangerous Goods present at any time on the site or transported from and to the terminal site shall be kept below the screening threshold quantities listed in the Hazardous and Offensive Development Guidelines Applying SEPP 33, (DP&E 2011). The screening threshold quantities for each Dangerous Goods shall be defined in accordance with Table 1: Screening Methods of Applying SEPP 33.</p>	operation	Ongoing	Road Pavement Deflection Report	No Dangerous Goods have been transported during this reporting period

SSD 6766	G6	<p>Port shuttle operations must use:</p> <p>a) Locomotives that incorporate available best practice noise and emission technologies. Prior to the construction of the rail link connecting to the site, the Applicant must submit a report to the Secretary for consideration and approval that has been prepared in consultation with TfNSW and the EPA that justifies the technology proposed and how it meets the objective of best practice noise and emission technologies; and</p> <p>b) Wagons that incorporate available best practice noise technologies such as “one- piece” freight bogies or three-piece freight bogies fitted with cross-bracing or steering arms; and including as a minimum permanently coupled ‘multi-pack’ steering wagons using Electronically Controlled Pneumatic (ECP) braking with a wire based distributed power system (or better practice technology). Prior to the commencement of operation, the Applicant must submit a report to the Secretary for consideration and approval that has been prepared in consultation with TfNSW and the EPA that justifies the technology proposed and how it meets the objective of best practice noise technologies.</p>	operation	Ongoing	N/A	MPE_AQ_Best Practice Progress Review_2022_Final_Rev3 clean submitted on 12/09/2022
SSD 6766	G7	<p>The Applicant shall install and maintain a rail noise monitoring system on the rail link at the commencement of operation to continuously monitor the noise from rail operations on the rail link. The system shall capture the noise from each individual train pass by noise generation event, and include information to identify:</p> <p>a) Time and date of freight train passbys;</p> <p>b) Imagery or video to enable identification of the rolling stock during day and night;</p> <p>c) LAeq(15hour) and LAeq(9hour) from rail operations; and</p> <p>d) LAF(max) and SEL of individual train passbys, measured in accordance with ISO3095; or</p> <p>e) Other alternative information as agreed with the Secretary.</p> <p>The results from the noise monitoring system shall be publicly accessible from a website maintained by the Applicant. The noise results from each train shall be available on the website ideally within 24 hours of it passing the monitor. The LAeq(15hour) and LAeq(9hr) results from each day shall be available on the website within 24 hours of the period ending.</p> <p>Prior to the commencement of operation, the applicant shall submit for the approval of the Secretary, justification supporting the appropriateness of the location for rail noise monitoring including details of any alternative options considered and reasons for these being dismissed. The rail noise monitoring system shall not operate until the Secretary has approved the proposed monitoring location.</p> <p>The Applicant shall provide an annual report to the Secretary with the results of monitoring for a period of 5 years, or as otherwise agreed with the Secretary, from the commencement of operation of the IMEX terminal. The Secretary shall consider the need for further reporting following a review of the results for year 5.</p>	operation	Compliant	N/A	<p>Covered in Annual Noise Review Report</p> <p>Required in next annual review 2023</p>

SSD 6766	G7A	<p>The applicant shall install and maintain a wayside angle of attack monitoring system on the rail link at the commencement of operation to continuously monitor the angle of attack to the rail of rolling stock wheels. The system shall capture the angle of attack from a wheel on each axle of every train, and include information to identify:</p> <p>a) Time and date of each axle pass by; and b) The identification number of each item of rolling stock.</p> <p>The results from the angle of attack monitoring system shall be:</p> <ul style="list-style-type: none"> • access ble by train operators from a website maintained by the Applicant. <p>Angle of attack results from each train shall be available on the website within 24 hours of it passing the monitor, unless unforeseen circumstances have occurred.</p> <ul style="list-style-type: none"> • included in a six-monthly report to the Secretary. The report should at least identify the number of wagons with wheels that exceed the ASA standard angle of attack and the action taken by operators to improve steering performance. <p>Prior to the commencement of operation, the Applicant shall submit for the approval of the Secretary, justification supporting the appropriateness of the location for angle of attack monitoring, the format of the information to be access ble to operators and the format of the public report.</p> <p>The angle of attack monitoring system shall not operate until the Secretary has approved the proposed monitoring location and reporting arrangements.</p>	operation	Compliant	N/A	Covered in Annual Noise Review Report - June 2022
----------	-----	--	-----------	-----------	-----	---

SSD 6766	G7B	<p>The Applicant shall:</p> <p>(a) not less than three months and not more than twelve months from commencement of operation, engage an appropriately qualified and experienced acoustic engineer to undertake a night-time noise survey at Glenfield Farm (or an equivalent location if access is denied).</p> <p>(b) the noise survey shall be conducted in accordance with the EPA's Rail Infrastructure Noise Guideline 2013 to determine:</p> <p>(i) the contribution of any new rail traffic travelling to and from the development; and,</p> <p>(ii) the increase in the total rail traffic noise level caused by any new rail traffic to and from the development.</p> <p>(c) the noise survey shall be conducted for not less than 12 contiguous days in the winter months (July, August or September).</p> <p>(d) if as a result of the noise survey there is a sustained increase in the total rail traffic noise level due to the noise level from rail traffic travelling to and from the development of more than 2dB(A) for more than 30% of nights surveyed, the Applicant shall within twelve months, construct a noise barrier along the relevant sections of rail link in accordance with the specifications provided by an appropriately qualified and experienced acoustic engineer so as to limit the increase in the total rail traffic noise level at Glenfield Farm caused by any new rail traffic to and from the development to not exceed 2dB(A).</p> <p>(e) the report of the noise survey including the results and recommendations shall be provided to the Secretary.</p>	operation	Compliant	Best Practice Review (BPR)	<p>The Locomotive Best Practice Review was developed in consultation with EPA and TfNSW and a final document has been issued, with confirmation from both parties that consultation comments have been closed out in the final report.</p> <p>This was approved by DP&E on 17/09/2017</p> <p>The Moorebank Intermodal Terminal Project Best Practice Wagon Report (Condition G6B) was published on 16 April 2019 by Renzo Tonin and is currently in consultation with TfNSW</p> <p>Report submitted in 12 May 2021</p>
SSD 6766	G8	<p>The following measures must be implemented during operation:</p> <p>a) The use of top of rail friction modifiers and automatic rail lubrication equipment in accordance with ASA Standard T HR TR 00111 ST Rail Lubrication, where required; and</p> <p>b) Measures to ensure the rail cross sectional profile is maintained in accordance with ETN-01-02 Rail Grinding Manual for Plain Track to ensure the correct wheel / rail contact position and hence to encourage proper rolling stock steering.</p>	operation	Ongoing	FCMM Monitoring	Use of Automatic Rail Lubrication Equipment / Maintain Rail Cross Sectional Profile
SSD 6766	G10	Containers must be transferred between the site and Port Botany predominantly by rail, unless where unforeseen circumstances have occurred (e.g. an incident, breakdown, derailment or emergency maintenance on the rail line). The Secretary may at any time request the Applicant to demonstrate that the transport of containers between the site and Port Botany container terminals is by rail. This is to be demonstrated upon request by the Secretary for the prior 12 month period.	operation	Ongoing	N/A	Containers are to be transferred by rail unless there is track maintenance or unforeseen circumstances

SSD 6766	G11	The Applicant shall prepare a six-monthly report to the Secretary with the results of container and vehicle monitoring for a period of 3 years, or as otherwise agreed with the Secretary, from the commencement of operation of the IMEX terminal. The Secretary shall consider the need for further reporting following a review of the results for year 3. The report shall include: a) The number of twenty foot equivalent units dispatched and received during the period; b) A record of heavy vehicle entry by date and approximate time; and c) The number of light vehicles turning right into the terminal site from Moorebank Avenue and turning left from the terminal site onto Moorebank Avenue for a representative day.	operation	Compliant	N/A	Part of BTODR Covered in BTODR report submission August 2022
SSD 6766	G12	All containers handling equipment, purchased after 2019 must meet US EPA Tier 4 or EU Stage IV emission standard or achieve an equivalent emission control performance to those standards listed in this condition.	operation	Ongoing	N/A	
SSD 6766	G13	The Applicant must carry out any activity, or operate any plant, in or on the premises by such practicable means as may be necessary to prevent or minimise air pollution.	operation	Ongoing	N/A	Continuous air monitoring is ongoing
SSD 6766	G14	Heavy road freight vehicles are not permitted to use Moorebank Avenue south of the East Hills Railway corridor. A main gate monitoring system (e.g. CCTV) shall be installed to identify heavy vehicles turning left from the terminal site onto Moorebank Avenue, or turning right from Moorebank Avenue to the terminal site. The Secretary may at any time request the Applicant to provide a heavy vehicle monitoring report for the prior 12 month period.	operation	Compliant	N/A	No heavy road freight vehicle from the project has been identified using the East Hills Railway Corridor

SSD 6766	G15	<p>Within 12 months of the commencement of operation of the project, or as otherwise agreed by the Secretary, the Applicant shall undertake operational noise monitoring to compare actual noise performance of the project against noise performance predicted in the review of noise mitigation measures predicted in documents specified under condition A1 of this approval, and prepare an Operational Noise Report to document this monitoring. The Report shall include, but not necessarily be limited to:</p> <ul style="list-style-type: none"> a) noise monitoring to assess compliance with the operational noise levels predicted in documents specified under condition A1 of this approval; b) a review of the operational noise levels in terms of criteria and noise goals established in the NSW Road Noise Policy (EPA, 2011); c) sleep disturbance impacts compared to those determined in Condition E25; d) methodology, location and frequency of noise monitoring undertaken, including monitoring sites at which project noise levels are ascertained, with specific reference to locations indicative of impacts on sensitive receivers; e) details of any complaints and enquiries received in relation to operational noise generated by the project between the date of commencement of operation and the date the report was prepared; f) any required recalibrations of the noise model taking into consideration factors such as actual traffic numbers and proportions; g) an assessment of the performance and effectiveness of applied noise mitigation measures together with a review and if necessary, reassessment of all feasible and reasonable mitigation measures; and h) identification of additional feasible and reasonable measures to those predicted in the documents specified under condition A1 of this approval, that would be implemented with the objective of meeting the criteria outlined in the NSW Road Noise Policy (EPA, 2011), when these measures would be implemented and how their effectiveness would be measured and reported to the Secretary and the EPA. <p>The Applicant shall provide the Secretary and the EPA with a copy of the Operational Noise Report within 60 days of completing the operational noise monitoring referred to in (a) above or as otherwise agreed by the Secretary.</p>	operation	Compliant		Not triggered
SSD 6766	G16	<p>Within 60 days of commissioning this audit, or as otherwise agreed by the Secretary, the Applicant shall submit a copy of the audit report to the Secretary and relevant public authorities, together with its response to any recommendations contained in the audit report. The audit report and response to any recommendations shall be published on the Project website.</p>	operation	Compliant	N/A	Undertaken on 10 May 2021. Report submitted 28/06/21



APPENDIX B - SSD 7628 CONDITIONS OF CONSENT

COMPLIANCE REQUIREMENT	UNIQUE (ID)	COMPLIANCE REQUIREMENT	DEVELOPMENT PHASE	COMPLIANCE STATUS	MONITORING METHODOLOGY	EVIDENCE AND COMMENTS
SSD 7628	A1	In addition to meeting the specific performance measures and criteria established under this consent all reasonable measures must be implemented to prevent, and if prevention is not reasonable, minimise, any harm to the environment that may result from the construction and operation of the development, and any rehabilitation required under this consent.	All	Ongoing	General - Inspection and Audit	
SSD 7628	A2	The development may only be carried out: (a) in compliance with the conditions of this consent; (b) in accordance with all written directions of the Secretary in relation to this consent; (c) in accordance with the EIS, Submissions Report, Consolidated assessment clarification responses, and updated Biodiversity Assessment Report; (d) in accordance with the amended Development Layout Plans and Design Plans, amended WSUD plans and amended architectural plans to be submitted for the Secretary's approval as part of this consent; and (e) in accordance with the management and mitigation measures at APPENDIX B of this consent.	All	Ongoing	General - Inspection and Audit	
SSD 7628	A3	The Secretary may make written directions to the Applicant: (a) as a result of the Department's assessment of any strategy, plan, program, review, audit, notification, report or correspondence submitted under or in relation to this consent; (b) as a result of the Department's assessment of any review, report or audit undertaken or commissioned by the Department regarding compliance with this consent or in relation to an incident (whether notified to the Department or not); and (c) in relation to the implementation of any actions or measures contained in any of the documents listed in condition A2.	All	N/A	General - Inspection and Audit	No written directions to the Applicant have been made by the secretary

SSD 7628	A4	The conditions of this consent and directions of the Secretary prevail to the extent of any inconsistency, ambiguity or conflict between them and a document listed in condition A2(c) or A2(e). In the event of an inconsistency, ambiguity or conflict between any of the documents listed in condition A2(c) and A2(e), the most recent document prevails to the extent of the inconsistency, ambiguity or conflict. For the purpose of this condition, there will be an inconsistency between documents if it is not possible to comply with both documents, or in the case of a condition of consent or direction of the Secretary and a document, if it is not possible to comply with both the condition or direction and the document.	All	N/A	General - Inspection and Audit	No inconsistencies have been triggered.
SSD 7628	A8	The container freight road volume must not exceed 250,000 TEUs p.a., subject to the exception identified in condition A9, which may only be considered under condition A9 after the facility has been in operation.	Operation	Not triggered		
SSD 7628	A9	The movement of container freight by road may exceed the 250,000 TEU limit p.a. by up to a further 250,000 TEU p.a., if the Secretary is satisfied that traffic monitoring and modelling of the operation of the facility demonstrate that traffic movements resulting from the proposed increase in TEU will achieve the objective of not exceeding the capacity of the transport network.	Operation	Not triggered		
SSD 7628	A10	In determining the TEU limit, the Secretary may take account any roadworks or mitigation measures proposed under a Voluntary Planning Agreement to minimise traffic impacts.	All	Ongoing		
SSD 7628	A11	The maximum GFAs for the following uses apply: (a) 300,000m2 for the warehousing and distribution facilities; and (b) 8,000m2 for the freight village.	Operation	Not triggered	GFA monitoring	
SSD 7628	A12	The warehousing and distribution facilities must only be used for activities associated with freight using the MPE Stage 1 rail intermodal terminal.	Operation	Not triggered		
SSD 7628	A13	Freight village tenants and occupations are restricted to those activities that provide: (a) ancillary support for the development, its tenants, worker population and visitors; (b) a nexus with activities undertaken in relation to the warehouse, logistics functions of the IMT development and/ or; (c) provide aligned services to the intermodal functions. Prior to occupancy of any freight village tenancy, and every subsequent occupation of these tenancies, details of the tenant and occupation activity is to be submitted to the Secretary demonstrating that the proposed activity complies with this condition.	Operation	Not triggered		
SSD 7628	A14	With the approval of the Secretary, the Applicant may submit any strategy, plan or program required by this consent on a staged basis.	All	Compliant	Documentation Monitoring	The CTP (Rev 5) dated 24 May 2018, was approved by DP&E on 8/06/2018 Document Delivery Strategy (DDS)

SSD 7628	A15	If the submission of any strategy, plan or program is to be staged, then the relevant strategy, plan or program must clearly describe the specific stage of the development to which the strategy, plan or program applies, the relationship of the stage to any future stages and the trigger for updating the strategy, plan or program.	All	Compliant	Documentation Monitoring	The CTP (Rev 5) dated 24 May 2018, was approved by DP&E on 8/06/2018 Document Delivery Strategy (DDS)
SSD 7628	A16	With the approval of the Secretary, any strategy, plan or program required by this consent may be combined	All	Ongoing		CERSEDMP and SWMP
SSD 7628	A17	In seeking the Secretary's approval, a clear relationship must be demonstrated between the strategies, plans or programs that are proposed to be combined.	All	Ongoing		All plans
SSD 7628	A19	Where conditions of this consent require a document to be prepared in consultation with an identified party, the Applicant must: (a) consult with the relevant party prior to submitting the subject document to the Secretary for approval; (b) provide evidence that at least two weeks was provided for the relevant party to comment on the document; and (c) include in the document: (i) details of the consultation undertaken; (ii) a description of how matters raised by those consulted have been resolved to the satisfaction of both the Applicant and the party consulted; and (iii) details of any disagreement remaining between the party consulted and the Applicant and how the Applicant has addressed the matters not resolved.	All	Compliant		Stakeholder consultation outcomes addressed within each management plan.
SSD 7628	A20	All licences, permits, approvals and consents as required by law must be obtained and maintained as required for the development. No condition of this consent removes the obligation for the Applicant to obtain, renew or comply with such licences, permits, approvals and consents.	All	Compliant	Compliance Monitoring of all relevant licences, permits, approvals and consents	CEMP (Rev 4) dated 5 April 2018, approved by DP&E 8/06/2018 Specific licence/permit requirements are addressed in each subplan. Compliance Tracker.
SSD 7628	A28	Prior to operation of the development, a compliance certificate for water and sewerage infrastructure servicing of the site under section 73 of the Sydney Water Act 1994 must be obtained.	Pre-operation	Not triggered	Obtain a compliance certificate for water and sewerage infrastructure	EWEMP / CEMP - licences and permits
SSD 7628	A30	Unless the Applicant and the applicable authority agree otherwise, the Applicant must: (a) repair, or pay the full costs associated with repairing any public infrastructure that is damaged by carrying out the development; and (b) relocate, or pay the full costs associated with relocating any infrastructure that needs to be relocated as a result of the development.	All	Not triggered	Monitor any damage or rectification required should activities cause damage to public infrastructure.	Records of damage or rectification required should activities cause damage to public infrastructure.
SSD 7628	A32	All plant and equipment used at the site or to monitor the performance of the development must be: (a) maintained in a proper and efficient condition; and (b) operated in a proper and efficient manner.	All	Compliant	Monitor all plant and equipment used at the site.	CEMP / Maintenance records

SSD 7628	B1	<p>The Applicant must:</p> <p>(a) prepare each plan, program and other documents in consultation with the specified stakeholders;</p> <p>(b) not commence each phase of the project until the plans, programs and other documents required under this consent are approved by or, where not required to be approved, submitted to the Secretary specified within the timeframes; and</p> <p>(c) implement the most recent version of the required plans and programs approved by the Secretary for the duration of the development.</p>	All	Compliant	Records and revisions of consultation and plans.	Record of consultation included in all plans.
SSD 7628	B26	<p>The Applicant must prepare an Operational Traffic and Access Management Plan to the satisfaction of the Secretary. The Plan is to be developed in consultation with the relevant Council, TfNSW and RMS. The plan must be approved by the Secretary prior to the commencement of operation.</p> <p>The Plan must be prepared by a suitably qualified and experienced person(s), and must:</p> <p>(a) demonstrate how the development will be managed during operation to meet the requirements of this development consent;</p> <p>(b) detail numbers and frequency of truck movements, sizes of trucks, vehicle routes and hours of operation;</p> <p>(c) detail access arrangements for the site to ensure road and site safety, and demonstrate there will be no queuing on the road network;</p> <p>(d) detail measures to ensure turning areas and internal access roads are kept clear of any obstacles, including parked cars, at all times;</p> <p>(e) set out procedures for collecting the information required to prepare the Biannual Trip Origin and Destination Report required under condition B28;</p> <p>(f) incorporate the Workplace Travel Plan as required under condition B29;</p> <p>(g) include a driver's code of conduct that requires:</p> <p>(i) compliance with specified travelling speeds;</p> <p>(ii) drivers to adhere to specified transport routes including no access from Cambridge Avenue; and</p> <p>(iii) drivers to implement safe driving practices.</p> <p>(h) include a program to monitor the effectiveness of these measures.</p>	Pre-operation	Not triggered		OEMP
SSD 7628	B27	<p>The Operational Traffic and Access Management Plan required by condition B26 must be implemented by the Applicant for the duration of operations</p>	Pre-operation	Not triggered		OEMP

SSD 7628	B28	<p>The Applicant is to prepare a Biannual Trip Origin and Destination Report each six months following commencement of any operation (in a format agreed with TfNSW and RMS) that advises:</p> <ul style="list-style-type: none"> (a) the number of actual and standard twenty foot equivalent shipping containers despatched and received during the period; (b) the number of days in the period that the truck gate was open for despatching trucks 24 hours a day, 7 days a week and detail any exceptions to this and advise actual hours of operation; (c) records of vehicle numbers accessing the site; and (d) representative vehicle origins and destinations, based on a cordon in the surrounding network. <p>A framework for recording and reporting on the data required for the report, prepared to the satisfaction of TfNSW and RMS, is to be submitted to the Secretary three months prior to the commencement of operation.</p> <p>The report is to be submitted within one month of its preparation throughout operation of the project, starting six months from the commencement of operation, unless otherwise agreed by the Secretary, TfNSW and RMS.</p> <p>The cordon count at (d) above will:</p> <ul style="list-style-type: none"> • apply to all classes of vehicles; and • cover the intermodal terminal, the warehousing facility and any other uses such as the freight village. 	Operation	Compliant		1065r06_BTODR Nov 2022 - May 2022 - November 2022 report lodged in Feb 2023
----------	-----	--	-----------	-----------	--	---

SSD 7628	B29	<p>Prior to issue of any Occupation Certificate, the Applicant must prepare a Workplace Travel Plan to the satisfaction of the Secretary.</p> <p>The Workplace Travel Plan must form part of the Operational Traffic and Access Management Plan required by condition C3, and must:</p> <p>(a) be prepared in consultation with TfNSW;</p> <p>(b) outline facilities and measures to promote public transport usage, such as car share schemes and employee incentives;</p> <p>(c) describe pedestrian and bicycle connections and linkages to and from the site from Moorebank Avenue and within the site including between warehouses and the freight village;</p> <p>(d) describe end of trip facilities available on-site which are to include under cover bike storage, showers and change facilities - the layout, design and security of bicycle facilities must comply with the minimum requirements of Australian Standard AS 2890.3 – 1993 Parking Facilities Part 3: Bicycle Parking Facilities; and</p> <p>(e) include the results of negotiations with the relevant agencies/ authorities as required to facilitate the staged delivery of the public transport infrastructure including:</p> <p>(i) construction of a covered bus drop off/ pick up facility within the site to encourage the use of buses for employees;</p> <p>(ii) review and rationalisation of the locations of Route 901 bus stops in the vicinity of the site to match the proposed northern terminal entry location and enhance accessibility;</p> <p>(iii) peak period and SIMTA shift work responsive express buses to /from the site and Liverpool Station via Moorebank Avenue and Newbridge Roads with frequency dependent on the development of the site;</p> <p>(iv) peak period express buses to/ from the site and Holsworthy rail station via Anzac Road, Wattle Grove Drive and Heathcote Road with frequency dependent on the development of the site;</p> <p>(v) potential to extend the Route 901 bus through the site via the light vehicle road and increasing peak period bus service frequencies to better match the needs of existing and future employees of the locality with frequency dependent on the extent of development of</p>	Pre-operation	Compliant		OEMP
SSD 7628	B30	<p>The Applicant must ensure that the Workplace Travel Plan is implemented for the life of the development.</p>	Operation	Compliant		Approval of the WTP was received by DPIE on 6/12/2019

SSD 7628	B43	A Stormwater Monitoring Program must be prepared in consultation with Council and OEH prior to operation and must be implemented for 5 years following completion of construction to monitor performance of the stormwater treatment system. The Stormwater Monitoring Program must form part of the Biodiversity Monitoring Strategy required by condition B105, prepared with reference to Using the ANZECC Guidelines and Water Quality Objectives in NSW (DEC, 2006).	Pre-operation	Not triggered		CTP
SSD 7628	B44	The Stormwater Monitoring Program must: (a) assess water quality and quantity performance for construction discharges and ongoing stormwater discharges from the development to ensure protection of the desired ecological values of Anzac Creek; and (b) include sampling locations and the frequency of sampling including wet weather sampling.	Pre-operation	Not triggered		CTP CSWMP
SSD 7628	B45	Conversion of any construction stage sediment and erosion control measures into permanent stormwater quality treatment elements must only occur once the civil works (roads and drainage) have been completed for the site to ensure the treatment measure is not compromised by sediment runoff.	Pre-operation	Compliant		CSWMP

SSD 7628	B49	<p>Prior to operation, the Applicant must prepare a Stormwater Infrastructure Operation and Maintenance Plan to manage the operation and maintenance of stormwater infrastructure on-site and off-site, to the satisfaction of the Secretary. The plan must form part of the OEMP required under condition C3 and must be implemented for the life of the assets and include:</p> <p>(a) the entity responsible for management and maintenance of the assets, including evidence that a maintenance contract is in place with a reputable and experienced maintenance contractor;</p> <p>(b) quarterly inspections, and inspections after major rainfall events;</p> <p>(c) schedule for routine checking, cleaning and servicing of all devices/ systems in accordance with the manufacturer's and/or designer's recommendations;</p> <p>(d) records of all maintenance activities undertaken;</p> <p>(e) quarterly maintenance reports, detailing the results of quarterly inspections, inspections after major rainfall events, and maintenance activities;</p> <p>(f) results of water quality monitoring;</p> <p>(g) investigation, management and mitigation of water quality target exceedances;</p> <p>(h) annual independent auditing; and</p> <p>(i) provision for submission of the quarterly maintenance reports and annual independent audit reports to the Secretary, including the results of inspections, management and maintenance actions and water quality monitoring.</p>	Pre-operation	Compliant	OEMP
SSD 7628	B50	<p>Assets to be managed under the Stormwater Infrastructure Operation and Maintenance Plan must include the channel through the MPW site to the Georges River unless the maintenance of this infrastructure is included in an operational environmental management plan approved by the Secretary for the MPW site.</p>	Pre-operation	Compliant	OEMP
SSD 7628	B51	<p>The annual independent audit must be undertaken by a suitably qualified WSUD professional. The audit is to verify the condition of the treatment system(s), verify and document that the system(s) is working as intended, verify the system(s) has been cleaned adequately, verify there is no excessive build-up of material in the system(s) and identify any issues with the treatment system(s) which require rectification for the system(s) to adequately perform its intended function.</p>	Operation	Compliant	<p>Independent WSUD Audit undertaken on 13/07/2022 . Report to be provided to Secretary in August 2022</p> <p>Required in July 2023</p>
SSD 7628	B54	<p>Best practice reactive and proactive management measures must be implemented to minimise dust generated during all works authorised by this consent.</p>	All	Compliant	<p>Monthly internal air quality reports prepared by Arcadis</p>
SSD 7628	B55	<p>Deposited dust must not exceed an increase of 2g/m2/month or maximum of 4g/m2/month at the closest off site sensitive receiver.</p>	All	Compliant	<p>Monthly internal air quality reports prepared by Arcadis</p>

SSD 7628	B59	The Applicant must prepare an Operational AQMP to the satisfaction of the Secretary for the entire precinct (MPE + MPW), unless this has been prepared and approved under an approval for the MPW site. The AQMP must be prepared by a suitably qualified and experienced person(s) and must form part of the OEMP required by condition C3. The AQMP must include: (a) identification of sources and quantify airborne pollutants; (b) best practice reactive and proactive control measures that will be implemented for each emission source; (c) provisions for the implementation of additional mitigation measures in response to issues identified during monitoring and reporting; (d) for all emission sources associated with site operations: (i) key performance indicator(s); (ii) monitoring method(s); (iii) location, frequency and duration of monitoring; (iv) record keeping; (v) complaints register; (vi) response procedures; and (vii) compliance monitoring.	Pre-operation	Not triggered		OAQMP
SSD 7628	B60	The Applicant must ensure the development does not cause or permit the emission of any offensive odour (as defined in the POEO Act).	All	Ongoing		CEMP/ OEMP
SSD 7628	B61	Equipment must be installed and operated in accordance with best practice to ensure that the development complies with all load limits, air quality criteria, air emission limits and air quality monitoring requirements as specified under this consent.	All	Ongoing		CEMP/ CAQMP
SSD 7628	B64	Continuous noise monitoring at sensitive receivers must be undertaken during early works, fill importation, construction and for at least 12 months following occupation of the entire site.	All	Complaint		continuous noise monitoring is ongoing
SSD 7628	B79	The permitted hours of warehouse and distribution operation are detailed in Table 4 .	Operation	Compliant		OEMP
SSD 7628	B80	Noise generated by operation of the development inclusive of MPE Stage 1 operations must not exceed the noise limits in Table 5 .	Operation	Ongoing		OEMP

SSD 7628	B83	<p>An Operational Noise Management Plan must be submitted to the Secretary for approval and form part of the OEMP required under condition C3. The report must be prepared by a suitably qualified and experienced person(s) and include:</p> <p>(a) an outline of management actions to be taken to address any potential non-compliances with the limits specified in Table 5;</p> <p>(b) a description of contingency measures to be implemented in the event management actions do not reduce noise levels to a compliant level; and</p> <p>(c) identification of additional feasible and reasonable measures to those proposed in the documents specified under condition A2, that would be implemented with the objective of meeting the criteria outlined in the NSW RNP (EPA, 2011), when these measures would be implemented and how their effectiveness would be measured and reported to the Secretary and the EPA.</p>	Pre-operation	Compliant		OEMP
----------	-----	---	---------------	-----------	--	------

SSD 7628	B85	The Applicant must carry out noise monitoring of mechanical plant and other noisy equipment for a minimum period of one week where valid data is collected following occupation of each warehouse. The monitoring program must be carried out by a suitably qualified and experienced person(s) and a Monitoring Report for Mechanical Plant must be submitted to the Secretary within two months of occupation or each tenancy to verify predicted mechanical plant and equipment noise levels.	Operation	Compliant		WH1 - New Tenant completed Required for Future Warehouse 6 and 7
----------	-----	---	-----------	-----------	--	---

SSD 7628	B86	<p>Within 12 months of occupation of the first warehouse, 50% occupation of the site and 100% occupation of the site, or as otherwise agreed by the Secretary, the Applicant must undertake operational noise monitoring to compare actual noise performance of the project against predicted noise performance, and prepare an Operational Noise Report to document this monitoring. The Report must include, but not necessarily be limited to:</p> <p>a) noise monitoring to assess compliance with the predicted operational noise levels and the noise limits specified in Table 5;</p> <p>b) a review of the operational noise levels in terms of criteria and noise goals established in the NSW RNP (EPA, 2011);</p> <p>c) sleep disturbance impacts compared to those determined in documents specified under condition A2;</p> <p>d) impacts associated with annoying characteristics such as prominent tonal components, impulsiveness, intermittency, irregularity and dominant low-frequency content;</p> <p>e) methodology, location and frequency of noise monitoring undertaken, including monitoring sites at which project noise levels are ascertained, with specific reference to locations indicative of impacts on sensitive receivers;</p> <p>f) details of any complaints and enquiries received in relation to operational noise generated by the project between the date of commencement of operation and the date the report was prepared;</p> <p>g) any required recalibrations of the noise model taking into consideration factors such as actual traffic numbers and heavy vehicle proportions; and</p> <p>h) an assessment of the performance and effectiveness of applied noise mitigation measures together with a review and if necessary, reassessment of all feasible and reasonable mitigation measures.</p>	Operation	Compliant		<p>Industrial noise assessment report completed as part of 50% occupation of the site submitted 8/6/21</p> <p>Next required 100% occupation</p>
SSD 7628	B87	The Applicant must provide the Secretary and the EPA with a copy of the Operational Noise Report within 60 days of completing the operational noise monitoring referred to in (a) above or as otherwise agreed by the Secretary.	Operation	Compliant	Required by May 2021	50% - submitted on 8/6/21
SSD 7628	B88	<p>To ensure the operational noise impacts are appropriately managed, the following measures apply:</p> <p>a) use of best practice plant; and</p> <p>b) preparation of a risk assessment to determine if non-tonal reversing alarms can be fitted as a condition of site entry. Alternatively, site design may include traffic flow that does not require or precludes reversing of vehicles⁹</p>	Operation	Not triggered		Not required unless identified by B85
SSD 7628	B89	For the duration of operation heavy road freight vehicles are not permitted to use Moorebank Avenue south of the East Hills Railway corridor. A main gate monitoring system (e.g. CCTV) must be installed to identify heavy vehicles turning left from the terminal site onto Moorebank Avenue, or turning right from Moorebank Avenue to the terminal site. The Secretary may at any time request the Applicant to provide a heavy vehicle monitoring report for the prior 12 month period.	Operation	Compliant		No heavy road freight vehicle from the project have been identified using the East Hills Railway corridor

SSD 7628	B90	For the duration of operation, the Applicant must: a) continue to implement all reasonable and feasible best practice noise mitigation measures; b) continue to investigate ways to reduce the noise generated by the development, including maximum noise levels which may result in sleep disturbance; and c) report on these investigations and the implementation and effectiveness of these measures in the Annual Review to the satisfaction of the Secretary.	Operation	Compliant		Ongoing monitoring. To be reported in the Annual Review. Annual review to be submitted to Secretary
SSD 7628	B101	Prior to commencement of operation, the Applicant must prepare a Heritage Interpretation Plan based on the recommendations contained in the Heritage Interpretation Strategy (artefact, 2017) approved under MPE Stage 1. The plan must be prepared for the entire Moorebank Intermodal Precinct (MPE and MPW sites). The plan must form part of the OEMP required by condition C3 and must:	Pre-operation	Ongoing		OEMP
SSD 7628	B102	(a) be prepared by a suitably qualified and experienced person(s); (b) be prepared in consultation with NSW Heritage Division, Council, relevant landowners and stakeholders including the Moorebank Heritage Group (MHG), Department of Defence, as well as the Relevant Aboriginal Parties (RAPs) should themes relating to Aboriginal heritage be included for interpretation; and (c) be approved by the Secretary prior to the commencement of operation.	Pre-operation	Ongoing		OEMP
SSD 7628	B110	Prior to operation, the Applicant must prepare an Operational Flora and Fauna Management Plan (OFFMP) in consultation with OEH. The OFFMP must form part of the OEMP required by condition C3 and must include measures to ensure biodiversity values not intended to be impacted are protected, including but not limited to: (i) weed control; (ii) feral animal control; (iii) pathogen management procedures; (iv) monitoring; and (v) rehabilitation actions.	Pre-operation	Ongoing		OEMP
SSD 7628	B115	Prior to occupation of each premises and in each instance of occupation by a new occupant, a report must be submitted to the Secretary confirming that the premises will be operated so as to comply with the requirements of conditions B112 and B114.	Pre-operation	Not triggered		Address via the WOEMP

SSD 7628	B116	<p>Six months prior to operation, the Applicant must prepare an Emergency Response Plan, in consultation with FRNSW and NSW Police Force.</p> <p>The Emergency Response Plan must include, but not be limited to:</p> <p>(a) protocols and procedures to be followed during emergency situations associated with the operation of the project (including fires and explosions). The protocols and procedures are to take into account the needs of people with a disability or who may experience access problems in emergency situations;</p> <p>(b) details of traffic management measures to be implemented during emergencies, where appropriate, to minimise the potential for escalation of the emergency;</p> <p>(c) design and management measures to address the potential environmental impacts of an emergency situation, including measures for containment of contaminated fire-fighting water, fuel spills and gaseous combustion products; and</p> <p>(d) details of a training and testing program to ensure that all operational staff are familiar with the Emergency Response Plan.</p>	Pre-operation	Ongoing		OEMP
SSD 7628	B120	<p>Prior to the commencement of operation, the Applicant must prepare a Waste Management Plan for the development to the satisfaction of the Secretary. The Waste Management Plan must form part of the OEMP required by condition C3 and be prepared in accordance with condition C7. The Plan must:</p> <p>(a) detail the type and quantity of waste to be generated during operation of the development;</p> <p>(b) describe the handling, storage and disposal of all waste streams generated on site, consistent with the Protection of the Environment Operations Act 1997, Protection of the Environment Operations (Waste) Regulation 2014 and the Waste Classification Guidelines Part 1: Classifying Waste (EPA, 2014) (as may be updated or replaced from time to time);</p> <p>(c) detail the materials to be reused or recycled, either on or off site; and</p> <p>(d) include the Management and Mitigation Measures included in APPENDIX B.</p>	Pre-operation	Ongoing		OEMP
SSD 7628	B121	Waste must be secured and maintained within designated waste storage areas at all times and must not leave the site or be deposited on or otherwise enter neighbouring public or private properties.	Operation	Compliant		No community waste complaints identified. Warehouse tenant have procured Waste Contractor to dispose any waste
SSD 7628	B122	All waste materials removed from the site must only be directed to a waste management facility or premises lawfully permitted to accept the materials.	All	Compliant		
SSD 7628	B123	The Applicant must assess and classify all liquid and non-liquid wastes to be taken off site in accordance with the latest version of EPA's <i>Waste Classification Guidelines Part 1: Classifying Waste</i> (EPA, 2014).	All	Compliant		
SSD 7628	B124	Waste generated outside the site must not be received at the site for storage, treatment, processing, reprocessing, or disposal unless it satisfies these conditions.	All	Compliant		
SSD 7628	B125	The Applicant must retain all sampling and waste classification data for the life of the development in accordance with the requirements of EPA.	All	Compliant		

SSD 7628	B126	The collection of waste generated during operation of the development must be undertaken between 7 am to 10 pm Monday to Friday	Operation	Compliant		Review of Warehouse Waste Registers
SSD 7628	B130	Prior to an occupation certificate being issued, the Applicant must submit to the Secretary a Site Audit Statement, prepared in accordance with the NSW Contaminated Land Management – Guidelines for the NSW Site Auditor Scheme (3rd edition, 2017), which demonstrates that the site is suitable for its intended land use (i.e. Section 'A'). The Site Auditor must consider the most up to date PFAS guidance.	Pre-operation	Not triggered		CTP: 8/06/2018 CEMP: 8/06/2018
SSD 7628	B145	Public road access must comply with section 4.1.3(1) of <i>Planning for Bush Fire Protection 2006</i> except for the requirement for through-access.	All	Compliant		CTP/ BFMP
SSD 7628	B146	The provision of water, electricity and gas must comply with section 4.1.3 of <i>Planning for Bush Fire Protection 2006</i> .	All	Compliant		CTP/ BFMP
SSD 7628	B153	The Applicant must obtain a certificate from a suitable qualified tradesperson, certifying that kitchen, food storage and food preparation areas have been fitted in accordance with Australian Standard AS4674. The Applicant must provide evidence of receipt of the certificate to the satisfaction of the Certifying Authority prior to occupation.	Operation	Not triggered		No Warehouses contain any food stoarge or food prepration areas

SSD 7628	B155	<p>No later than one month before early works and fill importation, a Community Communication Strategy must be prepared and submitted to the Secretary for approval. The Community Communication Strategy is to provide mechanisms to facilitate communication between the Applicant, the Council and the community (including adjoining affected landowners and businesses, and others directly impacted by the development), during the design and construction of the development. The Community Communication Strategy must:</p> <ul style="list-style-type: none"> (a) assign a central contact person to keep the nearby sensitive receivers regularly informed throughout the development; (a) detail the mechanisms for regularly consulting with the local community throughout the development, such as holding regular meetings to inform the community of the progress of the development and report on environmental monitoring results; (b) detail a procedure for consulting with nearby sensitive receivers to schedule high noise generating works or manage traffic disruptions; (c) include contact details for key community groups, relevant regulatory authorities, Registered Aboriginal Parties and other interested stakeholders; and (d) include a complaints procedure for recording, responding to and managing complaints, including: <ul style="list-style-type: none"> (i) email, toll-free telephone number and postal address for receiving complaints; (ii) advertising the contact details for complaints prior to and during operation, via the local newspaper and through on-site signage; (iii) a complaints register to record the date, time and nature of the complaint, details of the complainant and any actions taken to address the complaint; and (iv) procedures for the resolution of any disputes that may arise during the course of the development. 	Pre-operation	Compliant		CCS (Rev 4) dated 7 May 2018, approved by DP&E 01/06/2018
----------	------	--	---------------	-----------	--	---

SSD 7628	C3	<p>Before the commencement of operations, a Precinct Operational Environmental Management Plan (OEMP) must be prepared to the satisfaction of the Secretary. The OEMP must:</p> <p>(a) be prepared by a suitably qualified and experienced expert;</p> <p>(b) provide the strategic framework for environmental management of the development;</p> <p>(c) identify the statutory approvals required to carry out the development;</p> <p>(d) Identify the infrastructure to be managed under the Precinct OEMP which is to include pavements, stormwater detention and water quality treatment structures and devices; and landscaping.</p> <p>(e) describe the role, responsibility, authority and accountability of all key personnel involved in the environmental management of the development including the overall responsibility for the operational environmental management of the freight village;</p> <p>(f) describe the procedures to be implemented to:</p> <p>(i) keep the local community and relevant agencies informed about the operation and environmental performance of the development;</p> <p>(ii) receive, handle, respond to, and record complaints;</p> <p>(iii) resolve any disputes that may arise;</p> <p>(iv) respond to any non-compliance;</p> <p>(v) respond to emergencies; and</p> <p>(g) include the management plans required under this approval, including:</p> <p>(i) Operational Traffic and Access Management Plan;</p> <p>(ii) Workplace Travel Plan;</p> <p>(iii) Stormwater Infrastructure Operation and Maintenance Plan;</p> <p>(iv) Flood Emergency Response Plan;</p> <p>(v) Operational Air Quality Management Plan;</p> <p>(vi) Operational Noise and Vibration Management Plan;</p> <p>(vii) Heritage Interpretation Plan;</p> <p>(viii) Operational Flora and Fauna Management Plan;</p> <p>(ix) Waste Management Plan;</p> <p>(x) Long-term Contamination Management Plan; and</p> <p>(xi) Bushfire Emergency and Evacuation Plan.</p>	Pre-operation	Not triggered	OEMP
SSD 7628	C4	<p>The Applicant must:</p> <p>(a) not commence operation of the development until the OEMP is approved by the Secretary; and</p> <p>(b) operate the development in accordance with the most recent version of the OEMP approved by the Secretary, unless otherwise agreed by the Secretary.</p>	Pre-operation	Not triggered	OEMP
SSD 7628	C5	<p>Overall responsibility of the development, including the freight village environmental management during operation, must be by the entity responsible for the Precinct environmental management.</p>	Operation	Not triggered	OEMP

SSD 7628	C6	<p>Prior to occupation of individual warehouses, a Warehouse OEMP must be submitted to the Secretary for approval and must:</p> <ul style="list-style-type: none"> (a) be generally in accordance with the precinct OEMP required under condition C3; (b) demonstrate compliance with condition B113 regarding maintenance of quantities of dangerous goods below the screening threshold; and (c) include auditing requirements. 	Pre-operation	Not triggered		OEMP
SSD 7628	C7	<p>The Applicant must ensure that the environmental management plans required under this consent are prepared in accordance with any relevant guidelines, and include:</p> <ul style="list-style-type: none"> (a) detailed baseline data; (b) a description of: <ul style="list-style-type: none"> (i) the relevant statutory requirements (including any relevant approval, licence or lease conditions); (ii) any relevant limits or performance measures/criteria; and (iii) the specific performance indicators that are proposed to be used to judge the performance of, or guide the implementation of, the development or any management measures; (c) a description of the management measures to be implemented to comply with the relevant statutory requirements, limits or performance measures/criteria; (d) a program to monitor and report on the: <ul style="list-style-type: none"> (i) impacts and environmental performance of the development; and (ii) effectiveness of any management measures (see (c) above); (e) a contingency plan to manage any unpredicted impacts and their consequences; (f) a program to investigate and implement ways to improve the environmental performance of the development over time; (g) a protocol for managing and reporting any: <ul style="list-style-type: none"> (i) incidents and non-compliances; (ii) complaints; (iii) non-compliances with statutory requirements; and (h) a protocol for periodic review of the plan. <p>Note: The Secretary may waive some of these requirements if they are unnecessary or unwarranted for a particular management plan.</p>	All	Ongoing		All management plans

SSD 7628	C9	<p>Within three months of:</p> <p>(a) the submission of an annual review under condition C10; (b) the submission of an incident or non-compliance notification under condition C13; (c) the submission of an audit under condition C18; (d) the approval of any modification of the conditions of this consent; or (e) the issue of a direction of the Secretary under condition A2; the strategies, plans and programs required under this consent must be reviewed, and if necessary to either improve the environmental performance of the development, cater for a modification or comply with a direction, must be revised, to the satisfaction of the Secretary. Where revisions are required, the revised document must be submitted to the Secretary for approval within six weeks of the review.</p> <p>Note: The purpose of this condition is to ensure that strategies, plans and programs are regularly updated to incorporate any measures recommended to improve the environmental performance of the development.</p>	All	Ongoing		CEMP
SSD 7628	C10	<p>Each year, the Applicant must submit a review the environmental performance of the development (including all tenants and occupants) to the to the Department. The review must:</p> <p>(a) describe the development that was carried out in the previous calendar year, and the development that is proposed to be carried out over the next year; (b) include a comprehensive review of the monitoring results and complaints records from the previous year, including a comparison of these against the: (i) the relevant statutory requirements, limits or performance measures/criteria; (ii) requirements of any plan or program required under this consent; (iii) the monitoring results of previous years; and (iv) the relevant predictions in the EIS, Submissions Report, Consolidated assessment clarification responses; Modification Assessment, or conditions of this consent; (c) identify any non-compliance over the previous year, and describe what actions were (or are being) taken to ensure compliance; (d) identify any trends in the monitoring data over the life of the development; (e) identify any discrepancies between the predicted and actual impacts of the development, and analyse the potential cause of any significant discrepancies; and (f) describe what measures will be implemented over the next year to improve the environmental performance of the development.</p> <p>The Applicant must ensure that copies of the Annual Review are submitted to Council and are available to the CCC and any interested person upon request.</p>	All	Complaint		Covered in Aspect's Annual Review Report

SSD 7628	C11	The Department must be notified in writing to compliance@planning.nsw.gov.au immediately after the Applicant becomes aware of an incident. The notification must identify the development (including the development application number and the name of the development if it has one), and set out the location and nature of the incident.	All	Ongoing		CEMP/OEMP
SSD 7628	C12	A written incident notification addressing all requirements for such notification set out in Appendix D of this consent, must also be emailed to the Department at the following address: compliance@planning.nsw.gov.au within 7 days after the Applicant becomes aware of an incident. Notification is required to be given under this condition even if the Applicant fails to give the notification required under condition or, having given such notification, subsequently forms the view that an incident has not occurred.	All	Ongoing		CEMP/OEMP
SSD 7628	C13	Within 30 days of the date on which the incident occurred or as otherwise agreed to by the Secretary the Applicant must provide the Secretary and any relevant public authorities (as determined by the Secretary) with a detailed report on the incident addressing all requirements for such reporting set out in Appendix D of this consent, and such further reports as may be requested.	All	Ongoing		CEMP/OEMP
SSD 7628	C14	Any written requirements of the Secretary or relevant public authority (as determined by the Secretary) which may be given at any point in time, to address the cause or impact of an incident must be complied with and within any timeframe specified by the Secretary or relevant public authority.	All	Ongoing		CEMP/OEMP
SSD 7628	C15	If statutory notification is provided to EPA as required under the POEO Act in relation to the development, such notification must also be provided to the Secretary within 24 hours after the notification was provided to EPA.	All	Ongoing		CEMP/OEMP
SSD 7628	C16	The Department must be notified in writing to compliance@planning.nsw.gov.au within 7 days after the Applicant becomes aware of any non-compliance.	All	Ongoing		CEMP/OEMP
SSD 7628	C17	The notification must identify the development and the application number for it, set out the condition of consent that the development is non-compliant with, the way in which it does not comply, the reasons for the non-compliance (if known), and what actions have been, or will be, undertaken to address the non-compliance.	All	Ongoing		CEMP/OEMP

SSD 7628	C18	<p>Within one year of the commencement of any development under this consent, and every three years thereafter, unless the Secretary directs otherwise, the Applicant must commission and pay the full cost of an Independent Environmental Audit (Audit) of the development. Audits must:</p> <p>(a) be led and conducted by a suitably qualified, experienced and independent team of experts whose appointment has been endorsed by the Secretary;</p> <p>(b) be carried out in consultation with the relevant agencies and the CCC;</p> <p>(c) assess the environmental performance of the development (and tenancies) and assess whether it is complying with the relevant requirements in this consent, and any strategy, plan or program required under this consent; and</p> <p>(d) review the adequacy of any approved strategy, plan or program required under this consent; and</p> <p>(e) recommend appropriate measures or actions to improve the environmental performance of the development, and/or any strategy, plan or program required under this consent.</p>	All	Compliant		Undertaken on 10/5/21. Report submitted on 28/6/21. Next due in 2024
SSD 7628	C19	<p>Within three months of commencing an Independent Environmental Audit, or unless otherwise agreed by the Secretary, a copy of the audit report must be submitted to the Secretary, and any other NSW agency that requests it, together with a response to any recommendations contained in the audit report, and a timetable for the implementation of the recommendations. The recommendations must be implemented to the satisfaction of the Secretary.</p>	All	Compliant		Undertaken on 10/5/21. Report submitted on 28/6/21

SSD 7628	C20	<p>At least 48 hours before the commencement of construction until the completion of all works under this consent, including demolition and remediation, the Applicant must:</p> <p>(a) make copies of the following publicly available on its website:</p> <ul style="list-style-type: none"> (i) the documents referred to in condition A2 of this consent; (ii) all current statutory approvals for the development; (iii) all approved strategies, plans and programs required under the conditions of this consent; (iv) regular reporting on the environmental performance of the development in accordance with the reporting arrangements in any plans or programs approved under the conditions of this consent; (v) a comprehensive summary of the monitoring results of the development, reported in accordance with the specifications in any conditions of this consent, or any approved plans and programs; (vi) a summary of the current stage and progress of the development; (vii) contact details to enquire about the development or make a complaint; (viii) a complaints register updated on a monthly basis; (ix) the Annual Reviews of the development; (x) audit reports prepared as part of any independent environmental audit of the development and the Applicant's response to the recommendations in any audit report; (xi) any other matter required by the Secretary; and <p>(b) keep such information up to date, to the satisfaction of the Secretary.</p>	All	Compliant		<p>The website is being progressively updated as documents are approved for each stage of the construction activities.</p>
----------	-----	--	-----	-----------	--	--

SSD 7628	<p>The Proponent must prepare and implement a Compliance Tracking Program to track compliance with the requirements of this approval. The Compliance Tracking Program must be submitted to the Secretary for approval prior to the commencement of construction.</p> <p>The Compliance Tracking Program must include, but not be limited to:</p> <ul style="list-style-type: none"> (a) provision for the notification of the Secretary prior to the commencement of construction and prior to the commencement of operation of the development (including prior to each stage, where works are being staged); (b) provision for periodic review of the compliance status of the development against the requirements of this approval and the environmental management measures committed to in the documents referred to in condition A2; (c) provision for periodic reporting of compliance status to the Secretary, including but not limited to: <ul style="list-style-type: none"> (i) a Pre-Construction Compliance Report prior to the commencement of construction, (ii) quarterly Construction Compliance Reports, for the duration of construction, and (iii) a Pre-Operation Compliance Report prior to the commencement of operation, and six monthly operational compliance reports; (d) a program for independent environmental auditing; (e) mechanisms for recording environmental incidents during construction and actions taken in response to those incidents; (f) provision for reporting environmental incidents to the Secretary during construction; (g) procedures for rectifying any non-compliance identified during environmental auditing, review of compliance or incident management; and (h) provision for ensuring all employees, contractors and sub-contractors are aware of, and comply with, the conditions of this approval relevant to their respective activities. 	All	Compliant		This 6 monthly compliance Report
----------	--	-----	-----------	--	----------------------------------

APPENDIX C – AIR QUALITY MONITORING COMPLIANCE REPORT

MOOREBANK LOGISTICS PARK – PRECINCT EAST

Operational Air Quality Six Monthly Compliance Report #5
May 2022 – October 2022

11 JANUARY 2023



CONTACT

[REDACTED]

Environmental Consultant

[REDACTED]

[REDACTED]

[REDACTED]

Arcadis

Level 16

580 George Street

Sydney NSW 2000

MOOREBANK LOGISTICS PARK – PRECINCT EAST

Operational Air Quality Six Monthly Compliance Report #5

May 2022 – October 2022

Author [REDACTED] [REDACTED]

Checker [REDACTED] [REDACTED]

Approver [REDACTED] [REDACTED]

Report No PREC-ARC-EN-RPT-0014

Date 11/01/2023

Revision Text 002

This report has been prepared for Tactical Group in accordance with the terms and conditions of appointment for MLP Precinct East Operational Air Monitoring Program dated 20 December 2019. Arcadis Australia Pacific Pty Limited (ABN 76 104 485 289) cannot accept any responsibility for any use of or reliance on the contents of this report by any third party.

REVISIONS

Revision	Date	Description	Prepared by	Approved by
001	22/12/2022	Submitted draft to client for review	[REDACTED]	[REDACTED]
002	11/01/2023	Submitted final to client	[REDACTED]	[REDACTED]

CONTENTS

1 INTRODUCTION	1
1.1 Background.....	1
1.2 Site operation.....	1
1.3 Purpose of the report.....	2
1.4 Reporting period.....	3
1.5 Limitations	3
2 OVERVIEW OF AIR QUALITY MONITORING	4
2.1 Air quality monitors	4
2.2 Dust deposition gauges.....	4
2.3 Monitoring locations.....	4
2.4 Air quality monitoring station availability	7
3 WEATHER	8
3.1 Meteorological Conditions	8
3.1.1 Prevailing wind conditions	8
3.1.2 Meteorological wind data availability	8
3.1.3 Observed wind data	8
3.1.4 Ambient temperature and rainfall	10
3.2 Ambient Air Quality	10
4 MONITORING RESULTS	12
4.1 Air quality criteria	12
4.1.1 Criteria for PM _{2.5} , PM ₁₀ , NO ₂ and CO	12
4.1.2 Dust deposition	12
4.2 Dust deposition gauge results	13
4.3 Continuous monitor results	13
4.3.1 Annual exceedances.....	13
4.3.2 24-hour exceedances.....	14
4.3.3 NO ₂ 1-hour exceedances	14
4.3.4 CO 8-hour exceedances.....	14
4.4 Complaints	14
4.5 Ad-hoc monitoring	14
5 CONCLUSION	21
APPENDIX A	23

LIST OF TABLES

Table 1-1: Summary of out of standard construction hours activities.....	2
Table 2-1: Monitoring station availability (%).....	7
Table 3-1: Temperature and rainfall recorded at the Bankstown Airport AWS	10
Table 4-1: Monitoring criteria (applied from June 2021)	12
Table 4-2 Dust deposition criteria.....	12
Table 4-3 Dust deposition (insoluble solids g/m ² /month) results from May 2022 to October 2022.....	13
Table 4-4: Summary of exceedances of the PM _{2.5} 25 µg/m ³ /day limit.....	15
Table 4-5: Summary of exceedances of the PM ₁₀ 50 µg/m ³ /day limit.....	17

LIST OF FIGURES

Figure 2-1: Continuous real-time air quality monitors (Source: Arcadis, 2020).....	5
Figure 2-2 Location of Dust Deposition Gauges (Source: SERS, September/October 2022).....	6
Figure 3-1: Wind rose (May 2022)	8
Figure 3-2: Wind rose (June 2022)	8
Figure 3-3: Wind rose (July 2022)	9
Figure 3-2: Air quality categories	11

1 INTRODUCTION

1.1 Background

The Moorebank Logistics Park – Precinct East Operational Air Quality Monitoring Programme Framework (OAQMPF) provides a framework to monitor air quality during operation of the Moorebank Logistic Park (MLP) Precinct East and has been developed to support the implementation of the Operational Air Quality Management Plan (OAQMP) monitoring and reporting requirements. The OAQMP includes requirements of the:

- EPBC Act Approval (2011/6229) Condition of Approval (CoA) 8(f) which requires the implementation of a comprehensive air quality monitoring program (including locations, frequency, and duration)
- Moorebank Precinct East (MPE) Stage 1 (SSD 6766):
 - Condition of Consent (CoC) F4(f)(iv) which requires measurement of air emissions generated by the Facility
 - Final Compilation of Mitigation Measures (FCMM) 2C which requires the implementation of an air quality monitoring programme during operation for nuisance dust and air emissions [PM_{10} ¹ and nitrogen dioxide (NO_2)].
- MPE Stage 2 (SSD 7628):
 - CoC C21(c)(iii) which requires the submission of six-monthly operational compliance reports for the life of the project
 - CoC B59(d)(i), (ii), (iii), (iv) and (vii) which require the identification of air quality monitoring methods and implementation of compliance monitoring for all emissions associated with operations of the Facility
 - FCMM 3C which requires real-time boundary monitoring be undertaken during operation of the Facility.

1.2 Site operation

The MLP Operational Environmental Management Plan (OEMP) and sub-plans are currently applicable to the entire MLP Precinct East². The MLP Precinct East operates 24 hours, 7 days a week, and currently includes operation of the IMEX terminal, Rail Link, Warehouse 1, Warehouse 3, Warehouse 4, and Warehouse 5.

Very little construction occurred on MPE Stage 2 since December 2020, however earthworks have begun at warehouses 6 and 7 at MPE, which commenced on 9 June 2022. Warehouse 8 has been left as a compacted and stabilised earth pad. All construction related activities would be undertaken during standard working hours, unless stated otherwise.

MLP Precinct West³ (MPW) is located west of Moorebank Avenue and is a separate project operating under a different approval (SSD 7709) to MLP Precinct East. MPW Stage 2 is currently under construction and has been granted approval to receive imported material outside of standard construction hours.

¹ PM_{10} - Particles with a diameter of 10 micrometres or less, which are small enough to pass through the throat and nose and enter the lungs

² Comprises the MPE Stage 1 Project as approved by SSD 14-6766 for the development of the intermodal terminal facility (IMT) at Moorebank and MPE Stage 2 as approved under SSD 7628 (as modified) and MPE Concept Approval (MP 10 0193) for the construction and operation of warehousing and distribution facilities and upgrades to approximately 2.1 kilometres of Moorebank Avenue

³ Comprises the MPW Stage 2 Project which is the second stage of development under the MPW Concept Approval (SSD 5066) and SSD 7709. The Project involves the construction and operation of a multi-purpose intermodal terminal facility, Rail link connection, warehousing and upgraded intersection on Moorebank Avenue.

There are also works and activities outside of standard construction hours that occur from time-to-time under specific approvals processes. These can include construction works and activities associated with both MPE and MPW.

Table 1-1 summarises the works, activities and material import undertaken outside of standard construction hours during the reporting period.

Table 1-1: Summary of out of standard construction hours activities

Dates	Activities undertaken
1-3 June 2022	General construction activities
15-16 June 2022	General construction activities
July 2022 over 14 nights	Utility relocation works along Moorebank Avenue
7, 23, 28 and 30 July 2022	Other general construction works
1 August to 12 August 2022	Moorebank Avenue out of hours line marking
6 August 2022	Helicopter lift of materials
8 August 2022 to 9 September 2022	Out of hours service relocation works
21 August 2022	Helicopter lift of materials
26 August 2022 to 25 November 2022	Out of hours fill importation at MPW
5 September 2022	Line marking within MPE
5 September 2022	Road works on Moorebank Avenue
August 2022 and up to 9 September 2022	Service relocation work
12 September 2022 to 22 December 2022	Service relocation work
22 September 2022	Stormwater relocation at MPW
29 September 2022 for approximately 6 months	Traffic control on Bapaume Road
15 October 2022	Moorebank Avenue repairs
23 October 2022	Out of standard construction hours helicopter lifting works

1.3 Purpose of the report

This six-monthly air quality report has been prepared to meet reporting requirements of the CoC as outlined in Section 5 of the OAQMPF.

This six-monthly air quality report includes:

- A background to the air quality monitors and their locations (Section 2)
- Weather data and regional air quality (Section 3)
- Analysis of the raw data and comparison against identified criteria / trigger level, identification of exceedances, complaints or ad hoc monitoring undertaken (Section 4)
- An overview of any investigations undertaken to determine the cause of the exceedance or complaint (Sections 4.2, 4.3, 4.4 and 4.5)
- A high-level overview of the dust deposition data, which is provided by SERS (Section 4.2).
- Conclusions and recommendations based on the 6-month's data (Section 5)
- Summarised data in graphs and tables (Appendix A).

1.4 Reporting period

The MLP Precinct East operations commenced on 13 May 2020.

This six-monthly internal air quality report has been prepared to provide an overview of operational air quality results for the six-month operational period from 1 May 2022 to 31 October 2022 (inclusive) to inform the six-monthly operational compliance reports required for the life of the project.

This report will be the fifth report for MLP Precinct East since operations began in May 2020.

1.5 Limitations

All findings contained in this report are based on downloaded monitoring data at the time of writing the report and information relating to air quality provided by Tactical Group and Environmental and Remediation Services (SERS) who manage the dust deposition gauges (DDG). Arcadis do not take responsibility for the accuracy or limitations of the downloaded and provided data.

2 OVERVIEW OF AIR QUALITY MONITORING

2.1 Air quality monitors

The dust and air quality monitoring system installed at the MLP Precinct East comprises four Cairnet air quality units integrated with Sentinel™ software, which is hosted in the cloud. The system has been provided by EMS Brüel & Kjaer.

The Cairnet unit measures the following dust and air quality parameters:

- NO₂ (range: 0-25 ppb)
- PM₁₀
- PM_{2.5} (range: 0-1000 µg/m³)
- CO (installed since March 2020).

2.2 Dust deposition gauges

Seven DDG which are provided and serviced by SERS, are located around MLP Precinct East.

The gauges consist of 5-litre glass bottles with 150 mm diameter, glass funnels and silicone bungs. The purpose of this sampling is to determine which particles settle from the ambient air over an approximate 31-day sampling period. This equipment is compliant with the Australian Standard AS/NZS 3580.10.1:2016.

From May 2021, the installed DDG were managed and monitored by SERS.

2.3 Monitoring locations

The locations of the continuous air quality monitoring stations are identified on Figure 2-1 and the DDG locations are shown on Figure 2-2.

For this reporting period, the site boundary was considered to be representative of the closest receptors (including the adjacent commercial premises). The locations of the continuous air quality monitors means the construction and operation activities for both MLP Precinct East and MPW Stage 2 have been captured. DDG locations were also chosen so that a true representation of dust generated from site operation activity of MLP Precinct East could be established and to a slightly lesser extent, the construction activities of MPW Stage 2.




Figure 2-1: Continuous real-time air quality monitors (Source: Arcadis, 2020)



Figure 1: Site Layout

Head Office: 281 Newcastle Street Northbridge WA 6003 Postal: PO Box 377 Northbridge Perth WA 6865 T: +61 8 92202000 F: +61 8 92202010 E: admin@sers.net.au W: www.sers.net.au	Job No: 162536 Client: Knight Frank Address: Moorebank Avenue	Scale: 1:7,000 Original size: A3 Imagery from: 15/04/2020 Source: Nearmaps	Date drawn: 10/09/2022 Revision: 1 Drawn by: SP Checked by: BD	Legend ● Dust Trak ● DDG
	© This plan must not be reproduced without the permission of SERS File: N:\A SERS\GIS\Projects\ MXD\			

Figure 2-2 Location of Dust Deposition Gauges (Source: SERS, September/October 2022)

2.4 Air quality monitoring station availability

A summary of availability (time of operation) of the continuous air quality monitoring stations for this reporting period is summarised in Table 2-1, with the most recent calibration date also stated.

Table 2-1: Monitoring station availability (%)

Monitoring station	May 2022	June 2022	July 2022	August 2022	September 2022	October 2022	Average	Calibration [#]
AQM01	100	100	98	100	100	100	100	Nov 2021 [^]
AQM02	100	100	12	95	100	100	85	Nov/Dec 2021
AQM03	0	78 ^{^^}	100	100	100	100	80	Apr 2022 [^]
AQM04	100	100	98	100	97	0	83	Nov/Dec 2021

[#]Latest calibration date. Gauges were not calibrated for particulate matter.

[^]CO was not calibrated, only NO₂.

^{^^}AQM03 stopped recording data from 16 February 2022 to 7 June 2022 due to flood damage.

There has been some variability in monitor availability throughout this reporting period for all locations except for AQM01.

- AQM02 only recorded for a short period in July but was returned to full availability for the rest of the reporting period.
- AQM03 was damaged in Sydney's floods in February 2022 and reinstated on site on 7 June 2022.
- No data was recorded during October 2022 at AQM04. This is currently being investigated.

In order to maintain accurate data for reporting, monitors should be checked regularly for damage or faults and repaired or replaced promptly.

3 WEATHER

3.1 Meteorological Conditions

3.1.1 Prevailing wind conditions

Prevailing winds influence the dispersion of dust, and other air emissions potentially generated by the Facility. The prevailing wind speed and direction is normally obtained from a weather monitor located in Wattle Grove (around 500 metres east of MLP Precinct East). From August 2022 to October 2022 the weather monitor appeared to be faulty, so the Bankstown Airport Automatic Weather Station (AWS) was used as a reference station during this time. The prevailing wind speed and direction is discussed in more detail below.

3.1.2 Meteorological wind data availability

From August 2022 to October 2022 (inclusive), the weather monitor in Wattle Grove appeared to be faulty as records indicated prevailing wind direction and speed for each month was from only one direction and only one speed and appeared misaligned when referenced to the Bankstown Airport AWS. For the purposes of the months where the weather data at Wattle Grove was absent or faulty, the Bankstown Airport AWS data was referenced instead. This weather station is considered representative of conditions at the site.

3.1.3 Observed wind data

3.1.3.1 Wattle Grove weather monitor

The wind roses of recorded wind speed and direction data from the Wattle Grove weather monitor for May 2022, June 2022, and July 2022 are shown in Figure 3-1, Figure 3-2 and Figure 3-3 respectively.




Figure 3-1: Wind rose (May 2022)




Figure 3-2: Wind rose (June 2022)




Figure 3-3: Wind rose (July 2022)

Wind direction:

- Average wind direction during May 2022 was from the southwest
- June 2022 winds were mainly from the east
- July 2022 was dominated by mainly southerly airflows.

Wind Speed:

- Average recorded wind speed during the reporting period were generally low, around 0.4-0.5 m/s, indicating generally “calm” (i.e., winds less than 0.5 m/s) to “light air” conditions (i.e., winds between 0.5-1.5 m/s).

3.1.3.2 Bankstown Airport AWS

The data from the Bankstown Airport AWS for the August 2022 to October 2022 period is summarised below:

Wind direction was variable for the reporting period at both 9am and 3pm:

- At 9 am winds were generally from the west, with the most consistent direction from the west-southwest.
- At 3 pm winds were generally from the east, with the most consistent direction coming from the east-northeast.

Wind speed:

- At 9 am ranged from 0.6 m/s to 6.67 m/s, with an average of 3.14 m/s (light breeze⁴) and
- At 3 pm ranged from 1.67 m/s to 8.33 m/s, with an average of 4.87 m/s (gentle breeze).

⁴ Descriptions are based on the Beaufort Wind Scale <https://www.weather.gov/mfl/beaufort>

Air pollutant	Averaging period	Units	Air quality categories (AQC)				
			GOOD	FAIR	POOR	VERY POOR	EXTREMELY POOR
Ozone O ₃	1-hour	pphm	<6.7	6.7–10.0	10.0–15.0	15.0–20.0	20.0 and above
	4-hour rolling	pphm	<5.4	5.4–8.0	8.0–12.0	12.0–16.0	16.0 and above
Nitrogen dioxide NO ₂	1-hour	pphm	<8	8–12	12–18	18–24	24 and above
Visibility Neph	1-hour	bsp	<1.5	1.5–3.0	3.0–6.0	6.0–18.0	18.0 and above
Carbon monoxide CO	8-hour rolling	ppm	<6.0	6.0–9.0	9.0–13.5	13.5–18.0	18.0 and above
Sulfur dioxide SO ₂	1-hour	pphm	<13.3	13.3–20.0	20.0–30.0	30.0–40.0	40.0 and above
Particulate matter < 10 µm PM ₁₀	1-hour	µg/m ³	<50	50–100	100–200	200–600	600 and above
Particulate matter < 2.5 µm PM _{2.5}	1-hour	µg/m ³	<25	25–50	50–100	100–300	300 and above

Figure 3-4: Air quality categories

The PM₁₀, PM_{2.5}, NO₂, Visibility and CO air quality data from the Liverpool⁶ monitoring station was reviewed for the six-month reporting period. Below is a summary of the review:

- The NO₂ (ppm) maximum 1 hourly average data and CO (ppm) maximum rolling 8 hourly average data remained in the 'Good' category throughout the six-month reporting period.
- The AQC monthly average for particulates (PM₁₀ and PM_{2.5}) is derived from 1 hour average for each month. Based on the AQC metric, the baseline air quality for the Liverpool area between May 2022 and 31 October 2022 was rated as 'Good' every day, except for:
 - Wednesday 15 June 2022 had 'fair' PM₁₀ (36.1 µg/m³)
 - Wednesday 15 June 2022 had 'fair' PM_{2.5} (19.9 µg/m³)
 - Sunday 26 June 2022 had 'fair' PM_{2.5} (21.9 µg/m³)
 - Saturday 16 July 2022 had 'fair' PM_{2.5} (16.8 µg/m³)
 - Thursday 18 August 2022 had 'fair' PM₁₀ (33.5 µg/m³).
- Visibility was reported as 'Good' every day between 1 May 2022 and 31 October 2022, apart from:
 - Saturday 25 June 2022 had 'poor' Visibility (3.06 10⁻⁴m⁻¹)
 - Sunday 26 June 2022 had 'fair' Visibility (1.56 10⁻⁴m⁻¹), which coincided with the "fair" PM_{2.5} rating recorded on the same day.

⁶ Data download facility | NSW Dept of Planning, Industry and Environment

4 MONITORING RESULTS

4.1 Air quality criteria

4.1.1 Criteria for PM_{2.5}, PM₁₀, NO₂ and CO

Monitoring data has been summarised into tables and graphs for PM_{2.5}, PM₁₀, NO₂ and CO and are provided in Appendix A.

The National Environment Protection Measure for Ambient Air (Air NEPM)⁷ has established new national standards for assessment of air quality for NO₂ and CO, which came into effect 13 May 2021. These criteria are detailed in Table 4-1. The air quality data at MLP Precinct East was assessed against the new criteria from June 2021.

Table 4-1: Monitoring criteria (applied from June 2021)

Monitoring focus	Averaging period	Criteria / Trigger
PM _{2.5}	24-hour average	25 µg/m ³
	Annual average	8 µg/m ³
PM ₁₀	24-hour average	50 µg/m ³
	Annual average	25 µg/m ³
NO ₂	1-hour average	0.12 ppm
	Annual average	0.03 ppm
CO	1-hour average	NA
	8 -hour average	9.0 ppm

It is also worth noting that in 2025, the criteria for PM_{2.5} will change to 20 µg/m³ for the 24-hour averaging period and 7 µg/m³ for the annual average.

4.1.2 Dust deposition

Dust deposition data from seven DDGs located around the site is provided by SERS and have been provided for incorporation into the monitoring program since May 2021.

DPE has set the criteria for dust deposition rates, and these are provided in Table 4-2.

Table 4-2 Dust deposition criteria

Averaging Period	Maximum increase in deposited dust* level	Maximum total deposited dust level
Annual	2 g/m ² /month (incremental)	4 g/m ² /month (cumulative)

* Deposited dust is assessed as insoluble solids. This is the mass of the insoluble portion of the deposited matter, as defined under AS 3580.10.1: 2016.

⁷ <https://www.environment.nsw.gov.au/topics/air/understanding-air-quality-data/standards-and-goals>

4.2 Dust deposition gauge results

The results of the collection period 2 May 2022 to 31 October 2022 as provided by SERS is shown in Table 4-3.

Table 4-3 Dust deposition (insoluble solids g/m²/month) results from May 2022 to October 2022

Analysis Insoluble solids (g/m ² /month)	Stage 1 DDG 1	Stage 2 DDG 1	Stage 2 DDG 2	Stage 2 DDG 3	Stage 2 DDG 4	Stage 2 DDG 5	Stage 2 DDG 6
May 2022	0.6	<0.1	<0.1	<0.1	<0.1	0.1	0.2
June 2022	<0.1	<0.1	0.1	<0.1	0.5	<0.1	<0.1
July 2022	<0.1	<0.1	0.1	<0.1	0.5	<0.1	<0.1
August 2022	2.7	0.7	0.8	1.0	1.0	0.7	<0.1
September 2022	0.7	0.1	<0.1	0.4	1.3	<0.1	<0.1
October 2022	0.7	0.1	<0.1	0.4	1.3	<0.1	<0.1

Bold/grey indicates an exceedance of the criteria.

As shown in Table 4-3, there were no exceedances of the dust deposition (insoluble solids) 2 g/m²/month (incremental) and 4 g/m²/month (cumulative) criteria between 2 May 2022 and 31 October 2022.

4.3 Continuous monitor results

4.3.1 Annual exceedances

Continuous air quality monitoring for operations commenced on 13 May 2020 and therefore a full year of data is available to review the annual exceedances. The combined rolling average for monitoring during this reporting period is shown in tables and charts and included in Appendix A.

The following sections summarise the results for this reporting period.

4.3.1.1 PM_{2.5} and PM₁₀ Monitoring

The rolling annual average for all four monitors combined is well below the annual average criteria (8.0 µg/m³ for PM_{2.5} and 25.0 µg/m³ for PM₁₀).

It is noted that the combined rolling annual average for monitor AQM03 has exceeded the annual average criteria for PM_{2.5} and PM₁₀ each month for the reporting period. AQM03 is located on the western extent of MPW Stage 2, therefore the exceedances are potentially related to construction activities being undertaken at the MPW site.

4.3.1.2 NO₂ Monitoring

The 12-month rolling annual average for NO₂ for all four monitors to 31 October 2022 is 0.012 ppm, which is below the annual average criteria of 0.03 ppm.

The annual average criteria for NO₂ (0.03 ppm) was consistently and significantly exceeded from June 2021 to November 2021 (inclusive) at AQM03 and as of 31 October 2022 the rolling 12-month annual average for this monitor is 0.04 ppm. This monitor has been now recording more typical data since December 2021 resulting in the overall 12-month rolling annual average for NO₂ for all four monitors decreasing over the reporting period.

4.3.2 24-hour exceedances

As discussed above, no data was recorded from 16 February 2022 to 7 June 2022 at AQM03 due to damage from flooding.

4.3.2.1 PM_{2.5} Monitoring

Seventeen exceedances of the 25 µg/m³/day limit for PM_{2.5} were recorded during the 6-month reporting period. These are summarised in Table 4-5. The table includes the 24-hour average for PM_{2.5} recorded at the Liverpool monitoring station for comparison and includes analysis of the exceedance.

It should be noted that all the exceedances of the PM_{2.5} 24-hour average occurred at AQM03, located on the western side of MPW and some distance away from the train activity at the IMEX and from MLP Precinct East operation.

4.3.2.2 PM₁₀ Monitoring

Thirty-five exceedances of the 50 µg/m³/day limit for PM₁₀ were recorded during the 6-month reporting period. These are summarised in Table 4-5. The table includes the 24-hour average for PM₁₀ recorded at the Liverpool monitoring station for comparison and includes analysis of the exceedance.

With the exception of the exceedance recorded on 14 May 2022, which occurred at AQM02, all the exceedances of the PM₁₀ 24-hour average occurred at AQM03, located on the western side of MPW and some distance away from the train activity at the IMEX and from MLP Precinct East operation.

4.3.3 NO₂ 1-hour exceedances

No exceedance of NO₂ 1-hour criteria (0.12 ppm/ 120 ppb) were observed during the 6-month reporting period.

4.3.4 CO 8-hour exceedances

No 8-hour criteria exceedances for CO occurred during the 6-month reporting period.

4.4 Complaints

No complaints in relation to air quality were received in the 6-month reporting period.

4.5 Ad-hoc monitoring

No ad-hoc monitoring was undertaken between 1 May 2022 and 31 October 2022.

Table 4-4: Summary of exceedances of the PM_{2.5} 25 µg/m³/day limit

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁸	Analysis of exceedance	Train operation
21/06/2022	-	-	32.59	-	10.4	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
26/06/2022	-	-	29.66	-	21.9	Exceedances occurred mainly between 12 am and 8 am. The exceedance also coincided with a 'fair' value recorded at Liverpool.	Trains arrived/departed the terminal during the times of exceedance.
12/07/2022	-	-	25.07	-	11.2	Exceedances occurred mainly in the morning and late evening periods.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
16/07/2022	-	-	38.44	-	16.8	Exceedances occurred mainly in the morning and evening periods. The exceedance also coincided with a 'fair' value recorded at Liverpool.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
23/07/2022	-	-	52.44	-	4.1	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
24/07/2022	-	-	62.32	-	8.4	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
25/07/2022	-	-	43.21	-	7.6	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
26/07/2022	-	-	41.82	-	10.1	Exceedances occurred mainly between 12 am and 10 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
31/07/2022	-	-	31.17	-	15.0	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.

⁸ Liverpool average: The 24-hour average is the average of the 1-hour averages recorded for the day (i.e. between 01:00 and 24:00)

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁸	Analysis of exceedance	Train operation
28/08/2022	-	-	36.29	-	8.4	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
29/08/2022	-	-	77.78	-	9.8	Exceedances occurred mainly in the morning and late evening periods.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
30/08/2022	-	-	102.75	-	8.9	Exceedances occurred mainly between 12 am and 9 am.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
16/09/2022	-	-	111.51	-	4.2	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
23/09/2022	-	-	33.34	-	6.4	Exceedances occurred throughout the day, however highest in the morning.	Trains arrived/departed the terminal on this day, with six trains arriving/departing during the times of exceedance.
24/09/2022	-	-	61.94	-	6.6	Exceedances occurred mainly in the morning and evening.	Trains arrived/departed the terminal on this day, with four trains arriving/departing during the times of exceedance.
25/09/2022	-	-	96.08	-	6.5	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
08/10/2022	-	-	42.35	-	4.7	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day, with two trains arriving/departing during the times of exceedance.

<https://www.environment.nsw.gov.au/topics/air/monitoring-air-quality/sydney/monitoring-stations/liverpool>

Bold indicates a value other than good at the Liverpool air quality monitoring site

Table 4-5: Summary of exceedances of the PM₁₀ 50 µg/m³/day limit

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁹	Analysis of exceedance	Train operation
14/05/2022	-	60.66	-	-	17.1	Exceedances occurred between 2 am and 6 am.	No trains on this day.
14/06/2022	-	-	80.04	-	25.1	Exceedances occurred mainly in the early morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
16/06/2022	-	-	70.63	-	22.7	Exceedances occurred between 12 am and 7 am.	Trains arrived/departed the terminal during the times of exceedance.
20/06/2022	-	-	279.42	-	15.0	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
21/06/2022	-	-	275.50	-	19.1	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
22/06/2022	-	-	180.29	-	17.2	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
23/06/2022	-	-	94.99	-	19.2	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal during the times of exceedance.
24/06/2022	-	-	194.35	-	24.3	Exceedances occurred mainly between 7 pm and midnight.	Trains arrived/departed the terminal during the times of exceedance.
25/06/2022	-	-	88.12	-	21.8	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal during the times of exceedance.
26/06/2022	-	-	158.47	-	23.0	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal during the times of exceedance.
27/06/2022	-	-	148.22	-	10.5	Exceedances occurred mainly between 2 am and 7 am.	Trains arrived/departed the terminal during the times of exceedance.

⁹ Liverpool average: The 24-hour average is the average of the 1-hour averages recorded for the day (i.e. between 01:00 and 24:00)

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁹	Analysis of exceedance	Train operation
29/06/2022	-	-	386.70	-	23.0	Exceedances occurred mainly between 2 am and 8 am.	Trains arrived/departed the terminal during the times of exceedance.
2/07/2022	-	-	56.97	-	6.2	Exceedances occurred mainly between 2 am and 4 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
11/07/2022	-	-	68.37	-	12.9	Exceedances occurred mainly between 7 pm and midnight.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
12/07/2022	-	-	80.97	-	22.4	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
16/07/2022	-	-	55.43	-	22.9	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
21/07/2022	-	-	69.32	-	9.5	Exceedances occurred mainly between 12 am and 6 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
22/07/2022	-	-	67.79	-	10.0	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
23/07/2022	-	-	266.05	-	9.7	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
24/07/2022	-	-	278.94	-	13.6	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
25/07/2022	-	-	183.97	-	16.9	Exceedances occurred mainly in the morning and evening periods.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
26/07/2022	-	-	68.81	-	11.5	Exceedances occurred mainly between 12 am and 9 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁹	Analysis of exceedance	Train operation
18/08/2022	-	-	67.91	-	33.5	Exceedances occurred mainly between 12 am and 4 am. The exceedance also coincided with a 'fair' value recorded at Liverpool.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
28/08/2022	-	-	177.69	-	13.8	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.
29/08/2022	-	-	408.75	-	22.6	Exceedances occurred throughout much of the day.	Trains arrived/departed the terminal on this day, with two trains arriving/departing during the times of exceedance.
30/08/2022	-	-	419.70	-	15.0	Exceedances occurred mainly between 12 am and 9 am.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
16/09/2022	-	-	324.96	-	9.2	Exceedances occurred mainly between 12 am and 7 am.	Trains arrived/departed the terminal on this day, with three trains arriving/departing during the times of exceedance.
23/09/2022	-	-	65.44	-	14.9	Exceedances occurred throughout the day, however highest in the morning.	Trains arrived/departed the terminal on this day, with six trains arriving/departing during the times of exceedance.
24/09/2022	-	-	277.48	-	12.9	Exceedances occurred mainly in the morning and evening.	Trains arrived/departed the terminal on this day, with four trains arriving/departing during the times of exceedance.
25/09/2022	-	-	473.36	-	10.1	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day, with one train arriving/departing during the times of exceedance.
05/10/2022	-	-	56.80	-	14.7	Exceedances occurred mainly between 4 am and midnight.	Trains arrived/departed the terminal on this day, with four trains arriving/departing during the times of exceedance.
06/10/2022	-	-	63.82	-	10.6	Exceedances occurred mainly in the morning and late evening.	Trains arrived/departed the terminal on this day, with two trains arriving/departing during the times of exceedance.

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Date of exceedance	AQM01 µg/m ³	AQM02 µg/m ³	AQM03 µg/m ³	AQM04 µg/m ³	Liverpool average ⁹	Analysis of exceedance	Train operation
07/10/2022	-	-	108.01	-	11.9	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day, with two trains arriving/departing during the times of exceedance.
08/10/2022	-	-	77.59	-	8.6	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day, with two trains arriving/departing during the times of exceedance.
22/10/2022	-	-	66.51	-	14.0	Exceedances occurred mainly between 12 am and 8 am.	Trains arrived/departed the terminal on this day however none occurred during the times of exceedance.

<https://www.environment.nsw.gov.au/topics/air/monitoring-air-quality/sydney/monitoring-stations/liverpool>

Bold indicates a value other than good at the Liverpool air quality monitoring site

5 CONCLUSION

This six-monthly operational air quality report covers the period May 2022 to October 2022.

The following summarises the monitoring results for this reporting period:

- Monitor AQM03 exceeded the annual average criteria for PM_{2.5} or PM₁₀ throughout the reporting period. However, the average of all four monitors combined is below the annual average criteria of 8 µg/m³ for PM_{2.5} and 25 µg/m³ for PM₁₀.
- There were 17 exceedances (out of 184 days) of the PM_{2.5} 24-hour average criteria (25 µg/m³) during the reporting period (about 9%).
 - All exceedances were recorded at AQM03 which is the monitor located on the western boundary of MPW. Causes of the recorded exceedances may be attributed to construction activities relating to MLP Precinct West.
 - There was at least one exceedance every month, with numerous exceedance periods occurring on consecutive days.
 - Eleven exceedances corresponded to times when trains were entering/exiting MLP Precinct East, however noting that these exceedances were recorded at AQM03 located on the western side of MLP Precinct West.
 - Most exceedances coincided with higher readings overnight and during the early morning periods.
 - Investigations at MLP Precinct East upon receipt of the exceedances has not identified significant dust or emissions issues from MLP Precinct East.
- There were 35 exceedances (out of 184 days) of the PM₁₀ 24-hour average criteria (50 µg/m³) during the reporting period (about 19%).
 - As for PM_{2.5}, all exceedances, except for one (14/05/2022-AQM02), were recorded at AQM03.
 - There was at least one exceedance every month, with numerous exceedance periods occurring on consecutive days.
 - Twenty-six exceedances corresponded to times when trains were entering/exiting MLP Precinct East, however noting that these exceedances were recorded at AQM03 located on the western side of MLP Precinct West.
 - Most exceedances coincided with higher readings overnight and during the early morning periods.
 - Investigations at MLP Precinct East upon receipt of the exceedances has not identified significant dust or emissions issues from MLP Precinct East.
- Out of standard hours work, including works along Moorebank Avenue and fill importation at MPW, were occurring during times of PM_{2.5} and PM₁₀ exceedance in all months except for May 2022. These activities could potentially have influenced the high values recorded at AQM03, however further investigation is needed.
- The annual average criteria for NO₂ (0.03 ppm) were significantly and consistently exceeded from June 2021 to November 2021 (inclusive) at monitor AQM03. As of 31 October 2022, the rolling 12-month annual average for this monitor is 0.04 ppm which is marginally above annual average criteria of 0.03 ppm. Since AQM03 was recalibrated in the last reporting period, the data appears to be more consistent with the other monitors. Due to this the 12-month rolling annual average for

NO₂ for all four monitors to 31 October 2022 is 0.012 ppm, which is below the annual average criteria of 0.03 ppm.

- There were no exceedances of NO₂ 1-hour criteria (0.12 ppm / 120 ppb) during the 6-month reporting period.
- There were no exceedances of the CO criteria (9.0 ppm) at AQM02 and AQM04.
- There were no exceedances of the dust deposition (insoluble solids) 2 g/m²/month (incremental) or 4 g/m²/month (cumulative) criteria during the reporting period.
- Data from the Wattle Grove weather monitor was used for May 2022 to July 2022 report. From August 2022 to October 2022 the weather monitor appeared to be faulty (wind direction and speed were the same each month) when referenced to the Bankstown AWS. It is recommended that the monitor should be checked for damage or malfunction.
- There has been variability in monitor availability throughout this reporting period for all locations except for AQM01. In order to maintain accurate data for reporting, monitors should be checked regularly for damage or faults and repaired or replaced promptly.
- It is recommended that the operation of monitor AQM03 is investigated to determine whether there is a malfunction, incorrect calibration, vandalism, or isolated source of exceedance in proximity to the monitor. If there is an issue with the monitor, it should be rectified as soon as possible as to not impede air quality results for MPE. AQM03 is consistently higher than the other monitors and may be influenced by works at MPW.

APPENDIX A

Appendix A 1: Rolling 12-month particulate data (PM_{2.5})


Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	
November 2021	0.8	3.4	9.1	2.4	3.9	3.7	8.0	No exceedance of annual average criteria. AQM03 was only operational for 39% of November. The monitor was removed from site on 13 November 2021 for maintenance and/or calibration.
December 2021	0.5	2.5	2.4	2.1	1.9	3.3	8.0	No exceedance of annual average criteria. AQM03 was only operational for 37% of December. The monitor started recording data from 20 December 2021.
January 2022	0.8	3.6	8.5	3.1	4.0	3.4	8.0	No exceedance of annual average criteria.
February 2022	0.8	3.3	8.5	3.1	3.9	3.4	8.0	No exceedance of annual average criteria. AQM03 was not operational from 16 February 2022.
March 2022	0.6	2.8	No reading	2.8	2.1	3.3	8.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.
April 2022	0.4	2.0	No reading	2.1	1.5	3.2	8.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.
May 2022	0.1	1.6	No reading	0.7	0.8	3.2	8.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	
June 2022	0.0	0.8	12.8	0.2	3.5	3.2	8.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February and 7 June 2022. No exceedance of annual average criteria.
July 2022	0.1	Malfunction	15.8	0.4	5.4	3.0	8.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. No exceedance of annual average criteria.
August 2022	0.0	0.9	12.3	0.3	3.4	3.1	8.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. No exceedance of annual average criteria.
September 2022	0.1	1.7	17.6	0.6	5.0	3.3	8.0	No exceedance of annual average criteria.
October 2022	0.1	1.8	10.1	No reading	4.0	3.3	8.0	No exceedance of annual average criteria.
Rolling 12 month average	0.4	2.2	10.8	1.6	-	-	8.0	The average annual criteria has been exceeded at AQM03, however the annual average criteria for all four stations has not been exceeded.
All months^	1.0	4.0	6.8	2.7	3.6	-	8.0	No exceedance of annual average criteria.

Bold/grey indicates an exceedance of the criteria.

^ All months since May 2020



Monthly PM_{2.5} over 12 months including the 6-months for this report

Appendix A 2: Rolling 12-month particulate data (PM₁₀)


Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	µg/m ³	
November 2021	1.2	8.6	29.3	3.0	10.5	11.2	25.0	No exceedance of annual average criteria. AQM03 was only operational for 39% of November and was removed from site on 13 November 2021 for maintenance and/or calibration
December 2021	1.3	6.0	3.5	2.8	3.4	10.2	25.0	No exceedance of annual average criteria. AQM03 was only operational for 37% of December. The monitor started recording data from 20 December 2021.
January 2022	1.3	9.4	25.1	4.2	10.0	10.4	25.0	No exceedance of annual average criteria.
February 2022	1.4	8.4	27.3	4.8	10.5	10.5	25.0	No exceedance of annual average criteria. AQM03 was not operational from 16 February 2022.
March 2022	1.2	7.1	No reading	4.2	4.2	10.0	25.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.
April 2022	1.1	5.9	No reading	4.1	3.7	9.9	25.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.
May 2022	0.2	5.3	No reading	1.1	2.2	9.9	25.0	No exceedance of annual average criteria. AQM03 has not been operational since 16 February 2022.
June 2022	0.0	2.0	91.4	0.2	23.4	10.4	25.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. No exceedance of annual average criteria.

MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	µg/m³	
July 2022	0.1	7.0	48.6	0.4	14.0	9.4	25.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. No exceedance of annual average criteria.
August 2022	0.1	2.1	47.4	0.3	12.5	9.9	25.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. No exceedance of annual average criteria.
September 2022	0.1	4.9	56.0	0.6	15.4	10.6	25.0	No exceedance of annual average criteria.
October 2022	0.1	4.9	28.1	No reading	11.0	10.5	25.0	No exceedance of annual average criteria.
Rolling 12 month average	0.7	6.0	39.6	2.3	-	-	25.0	The average annual criteria has been exceeded at AQM03, however the annual average criteria for all four stations has not been exceeded.
All months [^]	2.9	12.7	24.6	5.5	11.3	-	25.0	No exceedance of annual average criteria.

Bold/grey indicates an exceedance of the criteria.

[^] All months since May 2020



Monthly PM₁₀ over 12 months including the 6-months for this report

Appendix A 3: Rolling monthly and annual particulate data (NO₂)

Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	ppb	ppb	ppb	ppb	ppb	ppb	ppm / ppb*	
November 2021	7.7	8.3	238.1	9.0	65.8	38.7	0.03 / 30.0	The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
December 2021	7.6	8.7	3.9	9.2	7.4	38.6	0.03 / 30.0	The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
January 2022	6.6	7.5	3.5	8.2	6.5	38.0	0.03 / 30.0	The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
February 2022	4.8	5.0	5.6	8.5	6.0	37.3	0.03 / 30.0	AQM03 was not operational from 16 February 2022. The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
March 2022	2.1	0.4	No reading	5.7	2.7	37.1	0.03 / 30.0	AQM03 has not been operational since 16 February 2022. The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
April 2022	1.6	0.5	No reading	7.6	3.2	36.8	0.03 / 30.0	AQM03 has not been operational since 16 February 2022. The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
May 2022	2.2	0.9	No reading	11.3	4.8	37.2	0.03 / 30.0	AQM03 has not been operational since 16 February 2022. The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.


MLP Precinct East Operational Air Quality Six Monthly Compliance Report #5 – May 2022 to October 2022

Month	Average AQM01	Average AQM02	Average AQM03	Average AQM04	Months Average All stations	Rolling annual average All stations	Annual average criteria	Comments
	ppb	ppb	ppb	ppb	ppb	ppb	ppm / ppb*	
June 2022	2.7	1.3	15.8	12.8	8.2	32.7	0.03 / 30.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February to 7 June 2022. The annual average criteria for all sites has been exceeded. AQM03 has exceeded the rolling 12-month average.
July 2022	2.5	0.9	14.1	11.0	7.1	27.4	0.03 / 30.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. AQM03 has exceeded the rolling 12-month average.
August 2022	2.8	1.5	17.8	12.9	8.8	22.3	0.03 / 30.0	AQM03 was reinstated to site on 7 June 2022. The monitor was damaged in floods in February 2022 and was not operational between 16 February 2022 and 7 June 2022. AQM03 has exceeded the rolling 12-month average.
September 2022	4.6	1.3	18.2	12.9	9.3	17.2	0.03 / 30.0	AQM03 has exceeded the rolling 12-month average.
October 2022	4.7	1.0	16.9	No reading	7.5	12.1	0.03 / 30.0	AQM03 has exceeded the rolling 12-month average.
Rolling 12 month average	0.004 ppm / 4.2 ppb	0.003 ppm / 3.1 ppb	0.037 ppm / 37.1 ppb	0.010 ppm / 9.9 ppb	-	-	0.03 / 30.0	No exceedance of annual average criteria for all sites. AQM03 has exceeded the rolling 12-month average.
All months^	0.005 ppm / 4.8 ppb	0.006 ppm / 5.6 ppb	0.060 ppm / 58.7 ppb	0.011 ppm / 11.3 ppb	0.019 ppm / 19.4 ppb	-	0.03 ppm / 30.0 ppb	No exceedance of average criteria for all sites for all months. However, AQM03 has exceeded the annual average for the period since monitoring began.


Bold/grey indicates an exceedance of the criteria.

*Results are shown in ppb due to reporting output, however the criteria is set in ppm and therefore the equivalent criteria in ppb is also shown.

^ All months since May 2020



Monthly NO₂ over 12 months including the 6-months for this report





APPENDIX D – NOISE MONITORING REPORTS



APPENDIX E - B106/B43 REPORT

**MOOREBANK PRECINCT EAST STAGE 2:
BIODIVERSITY MONITORING IN ANZAC CREEK
SPRING 2022 SURVEY**



**Draft Report Prepared for
ARCADIS**

20 January 2023

 **BIO-ANALYSIS Pty Ltd**
Marine, Estuarine & Freshwater Ecology
2/1 Botham Close, Charmhaven, NSW 2263
[REDACTED]; (Email) info@bioanalysis.com.au

Document Information

Project Name	Moorebank Precinct 2 East Stage 2: Biodiversity Monitoring in Anzac Creek (Spring 2022 Survey)
Prepared for	Arcadis Australia Pacific
Prepared by	Dr Sharon Cummins
File Name:	MPES2 B106 Anzac Creek Monitoring Report Spring 2022
Citation	BIOANALYSIS (2022). MPES2 B106 Anzac Creek Monitoring Report- Spring 2022. Report for Arcadis Author: Cummins, S. P., BIOANALYSIS Pty Ltd, Charmhaven.
Cover Photo	Anzac Creek @ Site AQ14, 30 November 2022

Contact Information

██████████
Telephone: ██████████

Email: ██████████

██████████
Telephone: ██████████

Email: ██████████

Document Control

Version	Date Issued
Draft Version 01	22/12/2022
Final Version	20/01/2023

Acknowledgements

██████████ and ██████████ are thanked for assistance in the field and laboratory. ██████████
██████████ (BIOANALYSIS), ██████████ (Arcadis) and ██████████ (Tactical) are thanked for management support.

EXECUTIVE SUMMARY

Introduction

The Sydney Intermodal Terminal Alliance (SIMTA) received approval for the construction and operation of Stage 2 (the Project) of the Moorebank Precinct East (MPE) Project, which comprises the second stage of development under the MPE Concept Approval (MP10_0193) and approved under Development Approval SSD 7628.

The MPE site, including the Project site, is located approximately 27 km south-west of the Sydney Central Business District (CBD) and approximately 26 km west of Port Botany and includes the former Defence National Storage and Distribution Centre (DNSDC) site. The MPE site is situated within the Liverpool Local Government Area (LGA), in Sydney's South West subregion, approximately 2.5 km from the Liverpool City Centre.

The MPE Project involves the development of an intermodal facility including warehouse and distribution facilities, freight village (ancillary site and operational services), stormwater infrastructure, landscaping, servicing and associated works on the eastern side of Moorebank Avenue. Stage 2 of the MPE Project (MPES2) involves the construction and operation of warehousing and distribution facilities on the MPE site and upgrades to approximately 2.1 kilometres of Moorebank Avenue.

A Baseline Aquatic Ecological Monitoring Program (BAEMP) was developed by Biosis Pty Ltd for Arcadis in March 2018, to address CoC B106. The purpose of the BAEMP was to establish baseline stream health and water quality conditions within selected sites along Anzac Creek prior to commencement of Early Works. This was undertaken in autumn 2018.

The baseline monitoring forms the basis for the ongoing Biodiversity Monitoring Strategy (BMS) to assess stream health in accordance with CoC B106, to determine any change in stream health or water quality throughout the life of the Project and to ascertain whether these changes can be attributed to the Project works. The BMS outlines monitoring requirements and includes the Stormwater Monitoring Strategy required by CoC B43 and B44.

BIO-ANALYSIS Pty Ltd was commissioned by Arcadis on behalf of Tactical Group to assess stream health and water quality at six monitoring sites along Anzac Creek (the Study Area) in spring 2022, in accordance with the BMS to satisfy the CoC B43, B44 and B106.

Methods

The BMS required that stream health monitoring focus on four main indicators:

- Aquatic habitat, including riparian habitat, aquatic macrophytes and fish habitat;
- Surface water quality and sediment characteristics;
- Aquatic macroinvertebrates sampled using the Australian River Assessment System (AUSRIVAS) protocol;
- Fish sampled using a backpack electro-fisher.

The results of the spring 2022 monitoring events were compared with those obtained in autumn 2018 (baseline), spring 2018, autumn 2019, spring 2019, autumn 2020, spring 2020, autumn 2021, spring 2021 and autumn 2022 (during construction). After construction of Warehouses 1, 3, 4 and 5, the location of Warehouses 6-8¹ was left as compacted pads in December 2020. Warehouses 6 and 7 earthworks commenced on 9/06/22. Water during construction will be managed in accordance with the currently approved Construction Environmental Management Plan (CEMP) and will be discharged into the sediment (SED) Basins and into Anzac Creek (via DP5 and DP7).

Results

Within the study area, Anzac Creek is mostly ephemeral with the exception of a relatively large pool downstream of the Project area (Site AQ12), opposite Wattle Grove. Sites downstream of the refuge pool have appeared to be in a more degraded state than those further upstream. At the time of the spring 2022 monitoring events, the condition of aquatic habitat appeared similar to that observed by previous surveys, in that the majority of the creek appeared stable and not subject to significant erosional processes. Water visibility was good.

¹ Following a redesign of MPE, only Warehouses 6 and 7 will be constructed within the area designated for Warehouses 6-8. Warehouse 8 will no longer be constructed.

The noxious plant, Alligator Weed, continues to be abundant at the most upstream site (Site AQ1). The popular aquarium plant, *Egeria densa* (Egeria), collected within the large refuge pool (Site AQ12) in spring 2020, has not been observed by subsequent surveys.

Reduced dissolved oxygen levels, elevated nitrogen, aluminium and copper measured at the refuge pool within the study area, including prior to commencement of the Project, have consistently suggested that aquatic habitat and biota within Anzac Creek are influenced by various types of anthropogenic disturbance. The data collected to date indicate that there has been no further degradation of water quality since the Project related construction work began.

Concentrations of lead in sediments collected at the most upstream site sampled on Anzac Creek (Site AQ1) continue to exceed the guideline value (50 mg/kg) but not the baseline value measured by the BAEMP survey (91 mg/kg). Importantly, the levels of lead recorded at Site AQ1 have not increased since commencement of the Project.

Heavy metals bound in sediments collected at sites sampled downstream of the Project area (i.e. Sites AQ4 and AQ14) were not identified as specific contaminants of concern by this survey or the BAEMP for the MPES2 Project, so no additional testing of heavy metals is considered necessary at this stage.

PFOA (perfluoro-octanoic acid) and PFOS (perfluorooctane sulphonate) have been detected in water and sediment samples collected throughout the survey period, but concentrations remain similar to baseline values and within the recommended Australian-derived guidelines for water and soil.

Low diversity of aquatic macroinvertebrates, Australian River Assessment System (AUSRIVAS) and Stream Invertebrate Grade Number Average Level (SIGNAL2) scores were also indicative of a site suffering from one or more forms of human impact. Despite this, some pollution tolerant taxa have commonly been identified, including dragonfly, caddis fly and mayfly families. Comparison of the AUSRIVAS and SIGNAL2 scores between the baseline and construction phase indicate an overall stability in aquatic health.

Altogether, nine species of fish have been collected from within the refuge pool: three native species of gudgeon, two native species of eel, one native galaxiid species and three introduced species (Gambusia, Goldfish and Oriental weatherloach), confirming that the creek does provide some habitat for native species of fish. All of the species caught are common within NSW. No threatened species of fish listed under the *NSW Fisheries Management Act, 1994* or the *Environment Protection and Biodiversity Conservation Act, 1999* have been recorded.

Conclusions

Examination of the results from the spring 2022 monitoring event found no evidence of changes in the indicator variables (bed and bank stability, water quality, assemblages of aquatic macroinvertebrates and fish) that could be attributed to the Project works. Thus, in accordance with the Biodiversity Monitoring Strategy, no adaptive management contingency measure was triggered.

Recommendations

It is recommended that Land managers focus on containment and on-going suppression of the Alligator Weed infestation at Site AQ1. Signage and public information at popular points of entry by the public to the creek and other local waterways may reduce the chance of unintentional human-assisted introductions (e.g. by using live bait, or by being released by aquaria).

TABLE OF CONTENTS

EXECUTIVE SUMMARY.....	3
1.0 INTRODUCTION.....	9
2.0 METHODS.....	10
2.1 Study Area.....	10
2.2 Sampling Dates	12
2.3 Performance Measures and Indicators	13
2.4 Field Methods.....	16
2.4.1 Visual Stream Assessments.....	17
2.4.2 Surface Water Quality & Sediment Monitoring	18
2.4.3 Aquatic Macroinvertebrates	19
2.4.5 Data Analysis	20
2.4.6 Quality Assurance/Quality Control (QA/QC).....	21
3.0 RESULTS.....	22
3.1 Aquatic Habitat Characteristics.....	22
3.2 Water & Sediment Characteristics	30
3.2.1 Water Quality	30
3.2.2 Sediment Characteristics	40
3.3 Aquatic Macroinvertebrates	50
3.4 Fish.....	53
5.0 DISCUSSION	56
5.1 Aquatic Habitat & Environmental Conditions	56
5.2 Biological Monitoring.....	58
6.0 CONCLUSION & RECOMMENDATIONS	59
7.0 REFERENCES.....	60
APPENDICES.....	63
Appendix 1 - GPS positions (UTMs) for stream monitoring sites (spring 2022).....	64
Appendix 2 – Visual Assessment Scores	65
Appendix 3 - Macroinvertebrate taxa collected at Site AQ12 in spring 2022 using the NSW AUSRIVAS protocol.....	67

List of Tables

Table 1. Date and information on aquatic ecology monitoring completed for the Project.	12
Table 2. Assessment types recommended for each monitoring site (Biosis, 2018).....	15
Table 3. Indicator variables and adaptive management contingency measures.....	15
Table 4. Mean (+ SE) physico-chemical water quality and nutrient values recorded at the time of the Baseline (autumn 2018, $n = 1$) and the spring 2022 ($n = 3$) surveys and the appropriate Default Trigger Values (DTV). Values highlighted in bold type indicate where results were outside the recommended DTV.....	32
Table 5. Summary of dissolved metal compound results for Site AQ12 in autumn 2018 (Baseline), autumn and spring 2019, autumn and spring 2020 and autumn and spring 2022 ($n = 1$).	33
Table 6. Summary of BTEX and perfluorinated compound results ($n = 1$).....	37
Table 10. Fish collected at Site AQ12 between autumn 2018 and spring 2019 [#] , spring 2020 and spring 2021.	54

List of Figures

Figure 1. Project Location.....	11
Figure 2. Rainfall (mm) measured at Bankstown Rainfall Station (66137) between 1 January and 30 November 2022.	23
Figure 3. OE50 Taxa Scores and their respective Band Scores (B-D) for AUSRIVAS samples collected from edge habitat at Site AQ12 since autumn 2018.	52
Figure 4. Quadrant diagram showing SIGNAL 2 results for Site AQ12 sampled in Anzac Creek since autumn 2018.	52

1.0 INTRODUCTION

The Sydney Intermodal Terminal Alliance (SIMTA) received approval for the construction and operation of Stage 2 (the Project) of the Moorebank Precinct East (MPE) Project, which comprises the second stage of development under the MPE Concept Approval (MP10_0193) and approved under Development Approval SSD 7628.

The MPE site, including the Project site, is located approximately 27 km south-west of the Sydney Central Business District (CBD) and approximately 26 km west of Port Botany and includes the former Defence National Storage and Distribution Centre (DNSDC) site. The MPE site is situated within the Liverpool Local Government Area (LGA), in Sydney's South West subregion, approximately 2.5 km from the Liverpool City Centre.

The MPE Project involves the development of an intermodal facility including warehouse and distribution facilities, freight village (ancillary site and operational services), stormwater infrastructure, landscaping, servicing and associated works on the eastern side of Moorebank Avenue. Stage 2 of the MPE Project involves the construction and operation of warehousing and distribution facilities on the MPE site and upgrades to approximately 2.1 kilometres of Moorebank Avenue. Warehouses 1, 3, 4 and 5 are now operational and the location of Warehouses 6-8² was left as compacted pads until earthworks for the construction of Warehouses 6 and 7 commenced on 9/06/22. Water during construction will be managed in accordance with the currently approved CEMP and will be discharged into the sediment (SED) Basins and discharged into Anzac Creek (via DP5 and DP7).

BIO-ANALYSIS Pty Ltd has been commissioned by Arcadis on behalf of Tactical Group to assess stream health and water quality along Anzac Creek (the Study Area) in spring 2022. Monitoring is to be done in accordance with a Biodiversity Monitoring Strategy (BMS) developed by Biosis (2018) to satisfy the Minister's Conditions of Consent (CoC) B106. The BMS also includes the Stormwater Monitoring Strategy required by CoC B43 and B44.

² Following a redesign of MPE, only Warehouses 6 and 7 will be constructed within the area designated for Warehouses 6-8. Warehouse 8 will no longer be constructed.

The primary aim of monitoring is to determine whether any change in stream health or water quality occur throughout the life of the MPE Stage 2 (MPES2) Project in accordance with the BMS and to ascertain whether these changes can be attributed to the Project works. Sampling commenced in autumn 2018 (Biosis, 2018).

2.0 METHODS

2.1 Study Area

Anzac Creek is a small tributary of the Georges River and lies entirely within the Liverpool Local Government Area. The catchment covers an area of approximately 10.6 km² (**Error! Reference source not found.**).

The headwaters of Anzac Creek lie within the Commonwealth Department of Defence Lands in Moorebank. The creek is approximately 4 km long and highly urbanised: it flows past the suburb of Wattle Grove, underneath the M5 and Heathcote Road intersection, through the Moorebank Industrial Area and underneath Newbridge Road.

While predominantly ephemeral, Anzac Creek has been noted to hold permanent water in isolated pools (Arcadis, 2016). An unnamed first order tributary of Anzac Creek flows from south to north along the eastern boundary of the MPE Project area (GHD, 2016).

Surface water from the MPES2 site is expected to enter Anzac Creek as licensed discharge between Site AQ4 and AQ8 (**Error! Reference source not found.**). It was also considered likely that runoff from some areas of the MPES2 site would be collected by a vegetated dam situated within Commonwealth Department of Defence land (Biosis, 2018). Flow from this dam enters Anzac Creek upstream of Site AQ14 via a culvert (**Error! Reference source not found.**).




Figure 1. Project Location

Date: 13/01/2023 Path: C:\Users\jornaz4\OneDrive\ARCADIS\1000\0279 - Moorebank - Environment - 02 (ISSA, Current) Maps\CEMP\Moorebank_CEMP_v2.aprx

2.2 Sampling Dates

The dates and phases of the stream health monitoring program for the MPES2 Project are outlined in Table 1.

Table 1. Date and information on aquatic ecology monitoring completed for the Project.

Project Phase	Event	Dates	Comments
Baseline	Autumn 2018	12&19 April 2018	Only one Baseline survey was able to be sampled in autumn 2018, due to the May 2018 bushfire.
Construction	Spring 2018	6&12 December 2018	
Construction	Autumn 2019	14&30 May 2019	Construction of culvert upstream of Site AQ1 largely completed on 30 May 2019. Site AQ12 was inaccessible to undertake Survey 2 due to restricted access.
Construction	Spring 2019	24 September 2019 21 November 2019	Warehouses 3 and 4 under construction. Moorebank Ave upgrade works ongoing.
Construction /Operation	Autumn 2020	25 May 2020 2 September 2020	Sampling required for the autumn 2020 survey season was unable to commence until late May 2020 due to COVID-19 related delays. The second survey was further delayed due to the time taken to receive parts required to repair the Electrofisher. Warehouses 3 and 4 were operational whilst Warehouse 5 was under construction. Moorebank Ave upgrade works ongoing.
Construction /Operation	Spring 2020	11&30 November 2020	Warehouses 3, 4 and 5 were operational. No further warehouses were being constructed at the time of monitoring
Construction /Operation	Autumn 2021	28 April 2021 11 June 2021	Warehouses 3, 4 and 5 are now operational and the location of Warehouses 6-8 have been left as compacted pads. Any water sheets off into the SED Basin and discharges into ANZAC Creek (via DP5 and DP7). No warehouses were being constructed at the time of monitoring.
Construction /Operation	Spring 2021	21 September 2021 8 November 2021	As above
Construction /Operation	Autumn 2022	5 & 31 May 2022	As above
Construction /Operation	Spring 2022	10 October 2022 30 November 2022	Warehouses 6&7 earthworks commenced on 9/06/22.

2.3 Performance Measures and Indicators

No instream or riparian works are being undertaken as part of the Project. Alteration to hydrology (increased stormwater inputs from both the stormwater network and surface flows from increases in non-permeable surfaces) and earthworks that have the potential to mobilise sediments into Anzac Creek were identified as potential impacts associated with the construction phase of the project (Biosis, 2018).

Biosis (2018) indicated that increased stormwater inputs to Anzac Creek could result in:

- Bed and bank scour as a result of increased volume and velocity of water during rainfall events;
- Alterations in vegetation structure as a result of altered hydrological regime;
- Introduction of sediments and pollutants via stormwater, with common pollutants including nitrogen, phosphorous, copper, aluminium and zinc.

Water Sensitive Urban Design (WSUD) measures such as onsite detention basins and rainwater gardens were incorporated into designs for the Project to mitigate impacts. A key outcome of this monitoring program was to determine whether these measures functioned as intended. Six monitoring sites (Sites AQ1, AQ4, AQ8, AQ12, AQ13 and AQ14; **Error! Reference source not found.**) are to be assessed in accordance with the BMS to satisfy the CoC B43, B44 and B106. The assessment types to be applied at each site are outlined in

Table 2.

Should an indicator variable deteriorate below the range for its baseline value, a stream health investigation protocol is to be initiated under the BAEMPs Adaptive Management Plan (

Table 3).

Baseline values are presented in Table 4, Table 5 and Table 6 (Section 3: Results).

Table 2. Assessment types recommended for each monitoring site (Biosis, 2018).

Assessment Type	Assessment Protocol/ Indicator Variable	AQ1	AQ4	AQ8	AQ12	AQ13	AQ14
Visual	DPI Classification	√	√	√	√	√	√
	NSW AUSRIVAS	√	√	√	√	√	√
	HABSCORE	√	√	√	√	√	√
	Ephemeral Stream Assessment	√	√	√	√	√	√
Surface Water & Sediment Quality Monitoring	<i>In situ</i> water quality				√		
	Nutrient, dissolved metal & PFAS				√		
	Sediment & PFAS	√	√				√
Aquatic Macroinvertebrates	NSW AUSRIVAS & Signal2				√		
Fish	Assemblage structure				√		

Table 3. Indicator variables and adaptive management contingency measures.

Result	Potential Problem	Contingency measure
Increases in results of water quality parameters	Introduction or exacerbation of pollutants entering Anzac Creek.	Identify source and undertake corrective measures.
Reduction in results of biological monitoring	Subtle effects of construction and operation are influencing stream health within Anzac Creek.	Identify components causing decline. Assess feasibility of suitable corrective actions. If corrective measures can be implemented, these aspects are to be the focus of future monitoring. If corrective measures cannot be implemented, regulatory authority to be notified of change.
Increase scour of bed and banks of waterways	Reduction in bed and bank stability or loss of instream vegetation.	Identify point source/s of increased flow velocities or changes in stream hydraulics and discuss with project engineers to determine best methods for flow reduction or rectification of stream hydraulics

2.4 Field Methods

To fulfil the requirements of the BMS, monitoring is to be undertaken at 6 sites along Anzac Creek (**Error! Reference source not found.**) four times annually during the pre-construction and construction phases of the Project, with the frequency reduced to twice annually during the operational phase of the Project. Surveys should take place during autumn and spring (Biosis, 2018). Sites are to be assessed using the methods outlined below, in accordance with

Table 2.

2.4.1 Visual Stream Assessments

A visual assessment was undertaken at each site regardless of the availability of aquatic habitat (i.e. wet or dry). The condition of aquatic habitat at each site was assessed according to the *NSW Department of Primary Industries Policy and Guidelines for Fish Habitat Conservation and Management* (DPI NSW, 2013). The two key indices were habitat *type* and *class*.

Information on stream characteristics was recorded at each site in accordance with the New South Wales (NSW) Australian River Assessment System (AUSRIVAS) protocol (Turak et al., 2004). Characteristics recorded included a visual assessment of surrounding landforms, instream features, presence, extent and type of aquatic vegetation, stream substratum, potential areas of refuge during low flow periods, presence of fish habitat, presence of barriers to fish movement, indicators of point source and diffuse pollution.

HABSCORE assessments were also completed at each site, based on the presence and condition of pool substrate characteristics, pool variability, channel flow status, bank vegetation and stability, width of riparian zone, and epifaunal substrate/cover. The *CSIRO Ephemeral Stream Assessment* guideline was also used to provide an assessment of the geomorphic integrity of each site and to identify the processes operating within each site.

Each site was photographed and the locations recorded with a hand-held GPS (satellite-based Global Positioning System).

2.4.2 Surface Water Quality & Sediment Monitoring

Where sufficient amounts of water are present, *in situ* water quality was measured using a Yeo-Kal 611 probe. Physico-chemical properties measured included electrical conductivity ($\mu\text{S}/\text{cm}$), dissolved oxygen (% saturation and mg/L), pH (pH units), temperature ($^{\circ}\text{C}$) and turbidity (NTU). Three replicate measures of each variable were collected from just below the water surface at each site.

Alkalinity was also determined in the field at Site AQ12, using a CHEMetrics' total alkalinity field kit.

As required by the BMS, water chemical and sediment sampling were undertaken for a range of nutrients, metals and hydrocarbons:

- Total Phosphorus (surface water only);
- Total Kjeldahl Nitrogen (TKN) (Total Organic Nitrogen + Total Ammonia) (surface water only);
- Total Nitrogen (TKN + (Nitrate + Nitrite) (surface water only);
- Dissolved metals (standard 19 relevant to aquatic assessment) (surface water);
- Total metals (standard 19 relevant to aquatic assessment) (sediment only);
- Total petroleum hydrocarbons, BTEX (benzene, toluene, ethylbenzene, trimethylbenzenes and three xylene isomers) hydrocarbons;
- PFAS: Poly-fluoroalkyl substances (including Perfluorohexane sulfonate PFHxS).

Samples were sent to the National Measurement Institute (NMI) laboratory (a NATA accredited laboratory) for analysis.

Construction Discharges

Construction discharge records (i.e. dewatering permits) were requested from contractors from the MPES2 Project in order to assess water quality and quantity performance for construction discharges, as required by the Stormwater Monitoring Program, CoC B44(a)). Records were requested for the time period between 1 June and 30 November 2022.

2.4.3 Aquatic Macroinvertebrates

Aquatic macroinvertebrates were required to be collected by the BMS at Site AQ12 (Biosis, 2018) using the NSW AUSRIVAS protocol (Turak et al., 2004). Biosis (2018) considered this large pool provides reliable and valuable aquatic habitat.

Stream edge habitats were sampled using a 250 µm dip net.

The contents of each net sample were placed into a white sorting tray and animals collected for a minimum period of 30 minutes. Thereafter, removals were done in 10-minute periods, up to a total of one hour (Turak et al., 2004). If no new taxa were found within a 10-minute period, removals ceased (Turak et al., 2004).

The animals collected were placed inside a labelled container and preserved with 70 % alcohol.

In the laboratory, taxa were identified to family level with the exception of Acarina (to order), Chironomidae (to sub-family), Nematoda (to phylum), Nemertea (to phylum), Oligochaeta (to class), Ostracoda (to subclass) and Polychaeta (to class). Some families of Anisoptera (dragonfly larvae) were identified to species, because they could potentially include threatened aquatic species.

2.4.4 Fish Community Survey

Fish sampling is done at Site AQ12 using a Smith Root LR-24 backpack electrofisher. The Electrofisher is used to stun fish in open water, around the edge of the pool, around snags and aquatic vegetation and any overhanging banks. All fish caught are identified and the length of up to 30 individuals of each species measured. Incidental observations such as evidence of disease are also noted before native fish species are subsequently returned to the water.

2.4.5 Data Analysis

Water quality measurements were used to assess health of the aquatic ecosystem by comparison with guideline values recommended by ANZECC³ and ARMCANZ⁴ (2000) for the protection of lowland streams (i.e. systems at < 150 m altitude) in south-east Australia.

For aquatic macroinvertebrates, data was analysed using the appropriate AUSRIVAS predictive models developed for NSW. The ecological health of a waterway is assessed by comparing the macroinvertebrates collected at a site (i.e. Observed) to those predicted to occur (Expected) if the site is in an undisturbed or ‘reference’ condition.

The principal outputs of the AUSRIVAS model include:

- Observed to Expected ratio (OE50): the ratio of the number of macroinvertebrate families collected at a site which had a predicted probability of occurrence of greater than 50 % (i.e. Observed) to the sum of the probabilities of all of the families predicted with greater than a 50 % chance of occurrence (i.e. Expected) (Ransom et al., 2004);
- BAND: for each model, the OE50 taxa ratios are divided into bands representing different levels of impairment. Band X represents a more diverse assemblage of macroinvertebrates than control sites; Band A is considered equivalent to reference condition; Band B represents sites below reference condition (i.e. significantly impaired); Band C represents sites well below reference condition (i.e. severely impaired); and Band D represents impoverished sites (i.e. extremely impaired) (Ransom et al., 2004).

The SIGNAL2 biotic index (Stream Invertebrate Grade Number Average level) developed by Chessman (2003) was also used to give an indication of water quality at the sites sampled.

The SIGNAL score for a macroinvertebrate sample is calculated by averaging the pollution sensitivity grade numbers of the families present, which may range from 10 (most sensitive) to 1 (most tolerant). The SIGNAL2 scores from samples collected between autumn 2018 and spring 2022 are presented graphically to provide an indication of changes over time.

³ ANZECC – Australian and New Zealand Environment and Conservation Council

⁴ ARMCANZ – Agriculture and Resource Management Council of Australia and New Zealand

2.4.6 Quality Assurance/Quality Control (QA/QC)

Data collected in the field was checked for accuracy and completeness before leaving each site. In the office, field data and other records were incorporated into appropriate excel data sheets and checked. Spreadsheets were locked prior to analysis to prevent accidental overwrites or corruption.

In the laboratory, macroinvertebrate samples were identified by an appropriately qualified staff member. Data for each sample were entered into an excel spreadsheet and then checked.

3.0 RESULTS

For the spring 2022 monitoring event, sites were sampled on 10 October 2022 (Survey 1) and 30 November 2022 (Survey 2). Each site was approximately 100 m in length with their GPS co-ordinates listed in Appendix A. Collections of fish and macroinvertebrates were completed in accordance with Section 37 of the *NSW Fisheries Management Act 1994* using Scientific Collection Permit Number P03/0032(B) and NSW Agriculture, Animal Research Authority Care and Ethics Certificate of Approval Number 03/2445.

3.1 Aquatic Habitat Characteristics

The section of Anzac Creek within the study area is not mapped as Key Fish Habitat (KFH) under the NSW DPI Key Fish Habitat mapping for the Sydney LGA (DPI 2007; Appendix A). Nevertheless, this section of Anzac Creek is ranked as TYPE 1 KFH according to the DPI (2013) classification scheme due to the presence of native aquatic plants and snags.

According to the waterway CLASS scheme, a permanent pool with freshwater aquatic vegetation situated at Site AQ12 is considered CLASS 2 KFH. The remaining reaches of Anzac Creek within the Study Area are considered to be CLASS 3 KFH despite the presence of aquatic vegetation, due to the ephemeral nature of any pools that are present (DPI, 2013).

Vegetation within the channel and banks of Anzac Creek has been classified as Parramatta Red Gum woodland in high condition (GHD, 2016).

Within the two months prior to the 2022 spring Survey 1 (10 October 2022) and 2022 spring Survey 2 (30 November 2022), a total of 216 mm and 231 mm rainfall was recorded respectively by the meteorological station situated near Bankstown Airport (Station ID: 66137) (Figure 2).

After construction of Warehouses 1, 3, 4 and 5, the location of Warehouses 6-8 was left as compacted pads in December 2020 (Table 1). Earthworks for construction of Warehouses 6&7 earthworks commenced on 9/06/22. Any water discharges will be managed in accordance with the approved CEMP for MPE and will be discharged into the sediment (SED) Basins and discharged into Anzac Creek (via DP5 and DP7).




Figure 2. Rainfall (mm) measured at Bankstown Rainfall Station (66137) between 1 January and 30 November 2022.

Site AQ1

Site AQ1 is situated approximately 750 m downstream of the source of Anzac Creek (**Error! Reference source not found.**), and approximately 100 m downstream of a culvert built across Anzac Creek as part of the MPE Stage 1 project (Plate 1). The culvert is composed of box culverts to a length of 15 m and supports one rail track and a maintenance access footway. Construction of the culvert was completed by CPB and handed over to the proponent, Qube, in July 2019.

Flow was apparent at the time of the spring 2022 surveys and the channel was almost full-to-bank (up to approximately 0.4 m deep) (Plates 1&2). The active channel zone at this site (up to approximately 5 m wide) remains stable (i.e. no signs of active erosion), mostly due to dense cover of the shallow, relatively narrow stream channel by aquatic plants and the

relatively intact woody riparian vegetation (Appendix 2). The channel consisted of fine sediment.

At the time of the spring 2022 surveys, the stream channel at Site AQ1 was mostly colonised by the noxious plant, Alligator Weed (*Alternanthera philoxeroides*), and the native species, Slender knotweed (*Persicaria decipiens*) (Plates 1&2). Other species of aquatic plant observed at Site AQ1 included Marsh Club-rush (*Bolboschoenus fluviatilis*) and Typha (*Typha* sp.). The tree canopy was mostly comprised by *Melaleuca* spp. and *Eucalyptus* spp. (Plates 1&2). *Myriophyllum variifolium* Hook.f., a species of water milfoil native to eastern Australia, was found growing in shallow water near the stream bank.



Plate 1: AQ1 – View up-stream (30/11/22)



Plate 2: AQ1 – View downstream (30/11/22)

Site AQ4

Site AQ4 is situated approximately 400 m downstream of Site AQ1 (**Error! Reference source not found.**).

The stream channel at Site AQ4 has occasionally been dry, including at the time of the Baseline survey (i.e. autumn 2018). Since the autumn 2020 surveys, surface water has been observed along the study reach (up to approximately 0.4 m deep), including in spring 2022 (Plates 3&4). Water clarity was considered good at the time of the spring 2022 surveys.

Since the baseline survey, stands of the emergent macrophyte, Jointed Twig Rush (*Baumea articulata*) and Twig Rush (*Baumea rubiginosa*) have formed across the downstream reaches of stream channel (Plate 4). Jointed Twig Rush, Slender Knotweed and Frog's Mouth (*Philydrum lanuginosum*) continue to be common in the upstream reaches (Plate 4).

The active channel zone, composed of fine sediments, was up to approximately 4 m wide (Plates 3&4). No indicators of significant erosion were observed suggesting that Anzac Creek continues to be relatively stable at this site, particularly since colonisation of the stream channel by emergent macrophytes (Plate 3&4, Appendix 2).



Plate 3: AQ4 – View downstream (30/11/22)



Plate 4: AQ4 – View upstream (30/11/22)

Site AQ8

Site AQ8 is situated approximately 1 km downstream of Site AQ4 (**Error! Reference source not found.**). At the time of Surveys 1 and 2, surface water (up to 20 cm deep) was present.

Similar to previous surveys, the study reach was mostly colonised by Heron Bristle Sedge (*Chorizandra cymbaria*), Jointed Twig Rush and Tall Spikerush (*Eleocharis sphacelata*), with occasional Frogmouth (*Philydrum lanuginosum*), Slender Knotweed and the introduced species, Umbrella Sedge (*Cyperus eragrostis*), present throughout (Plates 5&6). Riparian vegetation was dominated by *Casuarina* trees. Common Reed/Phragmites (*Phragmites australis*) was present at the downstream end of the site (Plate 6).

The stream channel at Site AQ8 (up to approximately 20 m wide) continues to be classified as stable, mostly due to dense cover by emergent macrophytes in addition to a relatively intact, woody riparian zone (Appendix 2).



Plate 5: Site AQ8 – view upstream (30/11/22)



Plate 6: Site AQ8 – view downstream (30/11/22)

Site AQ12

Site AQ12 is situated approximately 750 km downstream of Site AQ8 (Figure 1). Similar to the findings of biodiversity surveys done since autumn 2018, a large pool (approximately 20 m wide) and a relatively diverse assemblage of aquatic plants, including submerged species, were present (Plates 7&8). The pool substratum was composed primarily of fine sediment with a considerable cover of detritus.

Water level in the pool was up to approximately 0.9 m deep and flow was apparent at the relatively narrow, downstream end of the pool at the time of both surveys. Water clarity was considered good. Extensive cover by vegetation within the riparian zone contributes stability to the pool edges at Site AQ12, although an area of active erosion has been apparent at the downstream end of the pool since the autumn 2020 surveys, associated with heavy rainfall and bank overflows. Much of the scouring observed by Survey 1 (10 October 2022) had been re-colonised by exotic plants and emergent macrophytes by Survey 2 (30 November 2022).

The submerged macrophyte species, Ribbonweed (*Vallisneria* sp.) and *Potamogeton ochreatus* were common, in addition to Slender Knotweed and dense stands of Typha, Phragmites and Tall Spike Rush (Plate 7). *Nymphoides geminata* (Entire Marshwort), with mostly floating leaves and accumulations of green filamentous algae were abundant in areas close to the shore (Plates 7&8). Also noted during spring 2022 was the native perennial, *Utricularia* sp., that floats submerged. *Egeria* (*Egeria densa*), which was collected close to the left-bank (facing downstream) of the pool in spring 2020, has not been collected subsequently.

Riparian vegetation included Casuarina, Eucalyptus and Melaleuca trees and Spiny-head Mat-rush/Basket Grass (*Lomdandra longifolia*) (Plates 7&8).



Plate 7: Site AQ12 – view downstream (30/11/22)



Plate 8: Site AQ12 – view upstream (30/11/22)

Site AQ13

Site AQ13 is situated approximately 200 m downstream of Site AQ12 (**Error! Reference source not found.**). This site is located approximately 150 m downstream from an overflow channel that enters the creek from Wattle Grove. Water to a depth of approximately 0.4 m was present at Site AQ13 at the time of Survey 2, and flow was apparent (Plates 9&10). Unlike the findings of surveys done prior to autumn 2022, there was no apparent iron floc or anoxic layer covering the stream substratum. A large proportion of the stream channel and edges were colonised by Typha and Slender Knotweed. River Clubrush (*Schoenoplectus validus*) was also common. The stream channel appeared stable (Appendix 2).



Plate 9: Site AQ13 – view downstream (10/10/22)



Plate 10: Site AQ13 – view upstream (10/10/22)

Site AQ14

Site AQ14 is situated approximately 150 m downstream of Site AQ13 and immediately downstream of the culvert that links the dam within Commonwealth Department of Defence Lands to Anzac Creek (Figure 1). Flow was apparent at the time of both spring 2022 surveys and water clarity was good (Plates 11&12).

Typha, Slender Knotweed, River Clubrush and Whorled Pennywort/Shield Pennywort were common (Plates 11&12). This section of Anzac Creek remains mostly stable due to dense instream vegetation and vegetated banks (Appendix 2). Water visibility was good at the time of Survey 2 (Plates 11&12).



Plate 11: Site AQ14 – view downstream (30/11/22)



Plate 12: Site AQ14 – view of the stream substratum and a Short-finned eel (30/11/22)

3.2 Water & Sediment Characteristics

3.2.1 Water Quality

Physico-chemical measurements were collected at Site AQ12 in accordance with the requirements of the BMS (cf Biosis, 2018) and at sampling sites where sufficient water was present to submerge a water quality instrument probe. The data were compared to the default trigger values (DTVs) recommended by ANZECC/ARMCANZ (2000) for the protection of slightly disturbed lowland river ecosystems in southeast Australia (Table 4).

Results from this investigation (2022 spring survey 1 and 2022 spring survey 2) indicated that:

- Water temperature ranged from 14.6 to 20.7 °C
- pH (range = 6.2 to 7.3) was below the recommended DTV at site AQ1 during Survey 2 but within range during Survey 1
- Conductivity (range = 95 to 316 µS/cm) was within the recommended DTVs at all of the sites sampled
- Dissolved oxygen (DO) measurements (range = 31 to 80 % saturation) were below the lower DTV;
- Turbidity levels exceeded the recommended DTVs at Sites AQ1 and AQ4 during spring 2022 (range = 6 to 82.4 NTU)
- Concentrations of total phosphorous (range = <0.05 mg/L) were within the recommended DTV (0.05 mg/L) at Site AQ12
- Total nitrogen marginally exceeded the upper DTV (0.5 mg/L) at Site AQ12 at the time of Survey 1 (0.54 mg/L) but not Survey 2 (0.27 mg/L)
- Total Kjeldahl Nitrogen (TKN) (Total Organic Nitrogen + Ammonia) measured at AQ12 during both surveys was similar to the Total Nitrogen (TKN + (Nitrate + Nitrite) values, indicating that the source of nitrogen within the refuge pool was most likely organic (e.g. algae or decomposing plant material) rather than inorganic (e.g. fertilizer) (Table 4).

Most notably, the dissolved oxygen measurements collected at Site AQ12 were below the lower limit of the ANZECC/ARMCANZ (2000) range, including at the time of the baseline survey (Table 4). Nitrogen levels have commonly exceeded the upper limit, including at the time of the baseline survey (Table 4).

A range of toxicants have also been measured in water between autumn 2018 (baseline) and spring 2022 (during construction) within the vicinity of Site AQ12 (Table 5&6) in accordance with the BMS (cf Biosis, 2018).

Results indicate that:

- Aluminium has commonly exceeded the DTV (80 µg/L) (i.e. 12 of 16 surveys), including at the time of the baseline survey (260 µg/L) and during spring 2022 (Survey 1: 1,400 µg/L; Survey 2: 93 µg/L) (Table 5)
- Cadmium exceeded the DTV (0.4 µg/L) at Site AQ12 in autumn 2019 (Survey 1: 0.49 µg/L; Survey 2: 0.41 µg/L) and autumn 2021 Survey 1 (3.8 µg/L), but not subsequently (Table 5)
- Copper has commonly exceeded the DTV (1.8 µg/L) (i.e. 10 of 16 surveys, including the baseline survey: 2 µg/L), including during spring 2022 (Survey 1: 2.6 µg/L; Survey 2: <1 µg/L) (Table 5)
- Zinc exceeded the DTV during autumn 2021 (Survey 2: 20 µg/L) but not subsequently (Table 5)
- BTEX compounds and total recoverable hydrocarbons have not been detected (Table 6)
- PFOA (perfluoro-octanoic acid) and PFOS (perfluorooctance sulphonate) have occasionally been detected (Table 6): PFOA was not detected during autumn or spring 2022 (Table 6). PFOS was detected during autumn 2022 (Survey 1: 0.047 µg/L; Survey 2: 0.054 µg/L) and spring 2022 (Survey 1: 0.030 µg/L; Survey 2: 0.044 µg/L) but continues to be within the recommended DTVs (Table 6).

Table 4. Mean (\pm SE) physico-chemical water quality and nutrient values recorded at the time of the Baseline (autumn 2018, $n = 1$) and the spring 2022 ($n = 3$) surveys and the appropriate Default Trigger Values (DTV). Values highlighted in bold type indicate where results were outside the recommended DTV.

Indicator Variable	DTV*	Baseline ^A	Survey 1 (10/10/22)					
			AQ1	AQ4	AQ8	AQ12	AQ13	AQ14
Temperature °C ($n = 3$)	-	-	15.3 (0.0)	15.4 (0.2)	15.1 (0.0)	14.6 (0.0)	14.9 (0.0)	14.8 (0.0)
pH ($n = 3$)	6.5-8.0	7.01	7.2 (0.0)	7.0 (0.0)	6.7 (0.0)	6.8 (0.0)	6.8 (0.0)	7.3 (0.0)
Conductivity (μ S/cm) ($n = 3$)	125-2200	354	168.0 (0.0)	130.0 (0.0)	95.0 (2.5)	110.0 (0.0)	103.0 (0.0)	112.0 (0.0)
Dissolved Oxygen (%) ($n = 3$)	85-110	62	51.0 (2.2)	30.7 (0.1)	75.9 (5.8)	71.0 (0.3)	80.8 (0.1)	80.2 (0.1)
Turbidity (NTU) ($n = 3$)	6-50	91	82.4 (2.2)	71.5 (0.1)	30.2 (5.8)	33.3 (0.3)	38.1 (0.1)	32.4 (0.1)
Alkalinity (mg/L) ($n = 1$)	-	-	N/R	N/R	N/R	30	N/R	N/R
Total Phosphorous (mg/L) ($n = 1$)	0.05	0.58	N/R	N/R	N/R	<0.05	N/R	N/R
Total Nitrogen (mg/L) ($n = 1$)	0.5	8.2	N/R	N/R	N/R	0.54	N/R	N/R
Total Kjeldahl (mg/L) ($n = 1$)	-	-	N/R	N/R	N/R	0.53	N/R	N/R
Indicator Variable	DTV*	Baseline	Survey 2 (30/11/22)					
			AQ1	AQ4	AQ8	AQ12	AQ13	AQ14
Temperature °C ($n = 3$)	-	-	20.7 (0.0)	20.2 (0.0)	18.2 (0.0)	20.1 (0.0)	19.9 (0.0)	19.9 (0.0)
pH ($n = 3$)	6.5-8.0	7.01	6.2 (0.1)	6.6 (0.0)	6.9 (0.1)	6.5 (0.0)	6.6 (0.0)	6.4 (0.0)
Conductivity (μ S/cm) ($n = 3$)	125-2200	354	224.3 (0.7)	316.0 (0.0)	289.7 (0.4)	291.7 (0.3)	285.3 (0.3)	281.7 (0.3)
Dissolved Oxygen (%) ($n = 3$)	85-110	62	37.0 (1.0)	30.0 (0.1)	68.3 (0.4)	44.3 (0.1)	61.1 (0.6)	63.0 (0.2)
Turbidity (NTU) ($n = 3$)	6-50	91	6.1 (1.0)	11.9 (0.1)	6.4 (0.4)	6.0 (0.1)	14.1 (0.6)	4.4 (0.2)
Alkalinity (mg/L) ($n = 1$)	-	-	N/R	N/R	N/R	35	N/R	N/R
Total Phosphorous (mg/L) ($n = 1$)	0.05	0.58	N/R	N/R	N/R	<0.05	N/R	N/R
Total Nitrogen (mg/L) ($n = 1$)	0.5	8.2	N/R	N/R	N/R	0.27	N/R	N/R
Total Kjeldahl (mg/L) ($n = 1$)	-	-	N/R	N/R	N/R	0.26	N/R	N/R

*ANZECC/ARMCANZ (2000) – slightly disturbed systems

^A Baseline values for pH, conductivity, dissolved oxygen and turbidity were obtained from Site AQ12, whilst baseline data for phosphorous and total nitrogen were obtained from Site AQ11 (Biosis, 2018)

I/A: Insufficient Aquatic Habitat; N/R: Not Required

Table 5. Summary of dissolved metal compound results for Site AQ12 in autumn 2018 (Baseline), autumn and spring 2019, autumn and spring 2020 and autumn and spring 2022 ($n = 1$).

Indicator Variable	DTV* ($\mu\text{g/L}$)	Baseline Site AQ11	Autumn 2019 Site AQ12		Spring 2019 Site AQ12	
		April 2018	14/05/19	30/05/19	24/09/19	21/11/19
Aluminium pH >6.5	80	260	150	68	2730	280
Aluminium pH <6.5	-	-	-	-	-	-
Arsenic Total ($\mu\text{g/L}$)	42	<1	<1	<1	1.1	<1
Barium	-	2	55	34	21	32
Beryllium	-	<1	<1	<1	<1	<1
Boron	680	<50	20	17	14	14
Cadmium ($\mu\text{g/L}$)	0.4	<0.1	0.49	0.41	<0.1	<0.1
Chromium	6	<1	<1	<1	2.3	<1
Cobalt	-	<1	<1	<1	<1	<1
Copper ($\mu\text{g/L}$)	1.8	2	2	1.1	3	2.3
Iron	-	450	300	100	1650	900
Lead ($\mu\text{g/L}$)	5.6	<1	<1	<1	2.6	<1
Manganese	2500	3	33	6.2	60	47
Mercury ($\mu\text{g/L}$)	1.9 ^A	<0.1	<0.1	<0.1	0.12	<0.1
Molybdenum	-	<1	<1	<1	<1	<1
Nickel ($\mu\text{g/L}$)	13	<1	<1	N/R	1.7	1.1
Selenium Total	18	<10	<2	<1	<1	<1
Strontium	-	52	120	120	73	53
Vanadium	-	<10	<1	<1	3.8	1.4
Zinc ($\mu\text{g/L}$)	15	<5	6.8	N/R	13	14

*ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection)

^A = inorganic mercury; N/R: not recorded

Table 5 (Cont'd). Summary of dissolved metal compound results for Site AQ12 ($n = 1$).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Autumn 2020 Site AQ12		Spring 2020 Site AQ12	
		April 2018	25/05/20	2/09/20	11/11/20	30/11/20
Aluminium pH >6.5	80	260	230	70	230	100
Aluminium pH <6.5	-	-	-	-	-	-
Arsenic Total (µg/L)	42	<1	<1	<1	<1	<1
Barium	-	2	31	19	36	39
Beryllium	-	<1	<1	<1	<1	<1
Boron	680	<50	21	<5	32	31
Cadmium (µg/L)	0.4	<0.1	<0.1	<0.1	<0.1	<0.1
Chromium	6	<1	<1	<1	<1	<1
Cobalt	-	<1	<1	<1	<1	<1
Copper (µg/L)	1.8	2	1.9	<1	2	1.3
Iron	-	450	620	270	460	280
Lead (µg/L)	5.6	<1	1.5	<1	<1	<1
Manganese	2500	3	19	8.8	6.9	12
Mercury (µg/L)	1.9 ^A	<0.1	<0.1	<0.1	<0.1	<0.1
Molybdenum	-	<1	1.3	<1	<1	1.1
Nickel (µg/L)	13	<1	1.1	<1	1.1	<1
Selenium Total	18	<10	<1	<1	<1	<1
Strontium	-	52	120	140	120	130
Vanadium	-	<10	<1	<1	<1	<1
Zinc (µg/L)	15	<5	8.5	3.6	5.7	2.9

*ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection)

^A = inorganic mercury; N/R: not recorded

Table 5 (Cont'd). Summary of dissolved metal compound results for Site AQ12 (*n* = 1).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Autumn 2021 Site AQ12		Spring 2021 Site AQ12	
		April 2018	28/04/21 ⁵	11/06/21	21/9/21	8/11/21
Aluminium pH >6.5	80	260	150	1260	62	200
Aluminium pH <6.5	-	-				
Arsenic Total (µg/L)	42	<1	<1	<1	<1	<1
Barium	-	2	29	<1	31	13
Beryllium	-	<1	<1	<1	<1	<1
Boron	680	<50	20	10	20	15
Cadmium (µg/L)	0.4	<0.1	3.8	<0.1	<0.1	<0.1
Chromium	6	<1	<1	1.5	<1	<1
Cobalt	-	<1	<1	<1	<1	<1
Copper (µg/L)	1.8	2	2.1	3.3	1.7	3.2
Iron	-	450	160	420	150	180
Lead (µg/L)	5.6	<1	<1	<1	<1	<1
Manganese	2500	3	6.9	4.7	10	2
Mercury (µg/L)	1.9 ^A	<0.1	<0.1	<0.1	<0.1	0.15
Molybdenum	-	<1	<1	<1	<1	<1
Nickel (µg/L)	13	<1	1.1	<1	<1	<1
Selenium Total	18	<10	<1	<1	<1	<1
Strontium	-	52	130	46	110	40
Vanadium	-	<10	<1	2.7	<1	1.9
Zinc (µg/L)	15	<5	9	20	8.3	12

*ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection)

^A = inorganic mercury; N/R: not recorded

⁵ NB Data reported here for autumn 2021 Survey 1 and Survey 2 differ from those reported in the autumn 2021 report. Data had been entered incorrectly in the autumn 2021 report but have since been corrected.

Table 5 (Cont'd). Summary of dissolved metal compound results for Site AQ12 ($n = 1$).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Autumn 2022 Site AQ12		Spring 2022 Site AQ12	
		April 2018	5/05/22	31/05/22	10/10/2022	30/11/2022
Aluminium pH >6.5	80	260		200	1400	93
Aluminium pH <6.5	-	-	70			
Arsenic Total (µg/L)	42	<1	<1	<1	<1	<1
Barium	-	2	18	19	15	28
Beryllium	-	<1	<1	<1	<1	<1
Boron	680	<50	21	18	26	29
Cadmium (µg/L)	0.4	<0.1	<0.1	0.13	<0.1	<0.1
Chromium	6	<1	<1	<1	1.1	<1
Cobalt	-	<1	<1	<1	<1	<1
Copper (µg/L)	1.8	2	1.4	1.5	2.6	<1
Iron	-	450	560	320	1500	350
Lead (µg/L)	5.6	<1	<1	<1	2.3	<1
Manganese	2500	3	99	5.9	9.1	16
Mercury (µg/L)	1.9 ^A	<0.1	<0.1	<0.1	<0.1	<0.1
Molybdenum	-	<1	<1	<1	<1	<1
Nickel (µg/L)	13	<1	<1	<1	<1	<1
Selenium Total	18	<10	<1	<1	<1	<1
Strontium	-	52	93	56	35	99
Vanadium	-	<10	<1	<1	2.2	<1
Zinc (µg/L)	15	<5	8	6.7	12	5.2

*ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection)

^A = inorganic mercury; N/R: not recorded

Table 6. Summary of BTEX and perfluorinated compound results ($n = 1$).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Spring 2018 Site AQ12		Autumn 2019 Site AQ12	
		April 2018	6/12/18	12/12/18	14/05/19	30/05/19
BTEXN (µg/L)						
Benzene (µg/L)	1300	<1	<1	<1	<1	<1
Toluene (µg/L)	-	<2	<1	<1	<1	<1
Ethylbenzene (µg/L)	-	<2	<1	<1	<1	<1
Ortho-Xylene (µg/L)	470	<2	<1	<1	<1	<1
Perfluorinated Compounds (µg/L)						
PFHxS (µg/L)	-	0.02	0.02	0.12	0.039	0.039
PFOS (µg/L)	0.13	0.03	0.043	0.070	0.068	0.069
PFOA (µg/L)	220	<0.01	<0.01	0.011	0.011	0.010
Sum of PFHxS and PFOS	-	0.05	0.063	0.19	0.107	0.108
Sum of PFAS (WA DER List)^B	-	0.05	0.128 ^C	0.185 ^C	0.188 ^C	0.19 ^C
Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Spring 2019 Site AQ12		Autumn 2020 Site AQ12	
		April 2018	24/9/19	21/11/19	25/5/20	2/9/20
BTEXN (µg/L)						
Benzene (µg/L)	1300	<1	<1	<1	<1	<1
Toluene (µg/L)	-	<2	<1	<1	<1	<1
Ethylbenzene (µg/L)	-	<2	<1	<1	<1	<1
Ortho-Xylene (µg/L)	470	<2	<1	<1	<1	<1
Perfluorinated Compounds (µg/L)						
PFHxS (µg/L)	-	0.02	0.091	0.025	0.044	0.068
PFOS (µg/L)	0.13	0.03	0.084	0.057	0.055	0.076
PFOA (µg/L)	220	<0.01	<0.01	0.013	<0.01	<0.01
Sum of PFHxS and PFOS	-	0.05	0.175	0.082	0.099	0.144
Sum of PFAS (WA DER List)^B	-	0.05	0.252 ^C	0.164 ^C	0.178 ^C	0.219 ^C

*BTEXN: ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection); PFAS suite: DEE (2016) – Freshwater (95 % species protection – slightly to moderately disturbed ecosystems).

^B = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS.

^C For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01).

Table 6 (Cont'd).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Spring 2020 Site AQ12		Autumn 2021 Site AQ12	
		April 2018	11/11/20	30/11/20	28/04/21	11/06/21
Benzene (µg/L)	1300	<1	<1	<1	<1	<1
Toluene (µg/L)	-	<2	<1	<1	<1	<1
Ethylbenzene (µg/L)	-	<2	<1	<1	<1	<1
Ortho-Xylene (µg/L)	470	<2	<1	<1	<1	<1
PFHxS (µg/L)	-	0.02	0.026	0.041	0.065	0.011
PFOS (µg/L)	0.13	0.03	0.054	0.062	0.065	<0.02
PFOA (µg/L)	220	<0.01	0.005 ^C	0.014	<0.01	<0.01
Sum of PFHxS and PFOS	-	0.05	0.080	0.103	0.13	0.021 ^C
Sum of PFAS (WA DER List) ^B	-	0.05	0.151 ^C	0.196 ^C	0.222 ^C	0.086 ^C
Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Spring 2021 Site AQ12		Autumn 2022 Site AQ12	
		April 2018	21/9/21	8/11/21	5/05/22	31/05/22
BTEXN (µg/L)						
Benzene (µg/L)	1300	<1	<1	<1	<1	<1
Toluene (µg/L)	-	<2	<1	<1	<1	<1
Ethylbenzene (µg/L)	-	<2	<1	<1	<1	<1
Ortho-Xylene (µg/L)	470	<2	<1	<1	<1	<1
PFHxS (µg/L)	-	0.02	0.037	<0.01	0.044	0.039
PFOS (µg/L)	0.13	0.03	0.032	0.021	0.047	0.054
PFOA (µg/L)	220	<0.01	0.013	<0.01	<0.01	<0.01
Sum of PFHxS and PFOS	-	0.05	0.069	0.026 ^C	0.091	0.093
Sum of PFAS (WA DER List) ^B	-	0.05	0.169 ^C	0.091 ^C	0.166	0.176

*BTEXN: ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection); PFAS suite: DEE (2016) – Freshwater (95 % species protection – slightly to moderately disturbed ecosystems).

^B = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS.

^C For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01).

Table 6 (Cont'd).

Indicator Variable	DTV* (µg/L)	Baseline Site AQ11	Spring 2022 Site AQ12			
		April 2018	30/10/22	30/11/22		
Benzene (µg/L)	1300	<1	<1	<1		
Toluene (µg/L)	-	<2	<1	<1		
Ethylbenzene (µg/L)	-	<2	<1	<1		
Ortho-Xylene (µg/L)	470	<2	<1	<1		
PFHxS (µg/L)	-	0.02	0.031	0.026		
PFOS (µg/L)	0.13	0.03	0.030	0.044		
PFOA (µg/L)	220	<0.01	<0.01	<0.01		
Sum of PFHxS and PFOS	-	0.05	0.061	0.070		
Sum of PFAS (WA DER List)^B	-	0.05	0.126 ^C	0.135 ^C		

*BTEXN: ANZECC/ARMCANZ (2000) – slightly disturbed systems (90% species protection); PFAS suite: DEE (2016) – Freshwater (95 % species protection – slightly to moderately disturbed ecosystems).

^B = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS.

^C For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01).

3.2.2 Sediment Characteristics

Sediment samples have been collected at Site AQ1, AQ4, AQ14 between autumn 2018 (baseline) and spring 2022 (during construction) (Table 7&8).

Results indicate that:

- The majority of measurements of lead at AQ1 (range = 21 to 130 mg/kg) have exceeded the threshold limit (50 mg/kg) detailed in the Interim Sediment Quality Guidelines (ISQG) (ANZECC/ARMCANZ 2000), including at the time of the baseline (91 mg/kg) survey (discussed further in Section 5.1). Concentrations of lead measured at Site AQ1 during spring 2022 (Survey 1: 79 mg/kg; Survey 2: 62 mg/kg) also exceeded the guideline value, but below the baseline value
- Concentrations of mercury measured at AQ1 exceeded the recommended trigger level during autumn 2022 (Survey 1: <0.2 mg/kg; Survey 2: 0.29 mg/kg) but not during spring 2022 (Table 7). Given that Site AQ1 is situated upstream of the Project area, it was considered unlikely that elevated levels of mercury were related to Project activities
- Concentrations of lead (56 mg/kg), nickel (23 mg/kg) and zinc (220 mg/kg) measured at AQ4 marginally exceeded the ANZECC/ARMCANZ (2000) guideline levels during Survey 1 in autumn 2022, but not during spring 2022 (Table 7)
- A spike in barium was detected at Site AQ14 in autumn 2019 (Survey 1: 902 mg/kg) but not subsequently. There are no guideline criteria for barium in sediments or water (ANZECC/ARMCANZ 2000)
- Nickel measured in sediments at Site AQ1 during spring 2022 (25 mg/kg) marginally exceeded the upper ANZECC/ARMCANZ (2000) guideline level for the first time since sampling commenced. Given that Site AQ1 is situated upstream of the MPES2 construction activities, this result is not attributable to the Project works
- PFOS has consistently been detected at the sites sampled (range = <0.002 to 0.044 mg/kg) but concentrations continue to be below the recommended guideline value for Urban Residential/Public Open Spaces (32 mg/kg) as well as National Parks/Areas with High Ecological Values (6.6 mg/L)

- PFAS (range = <0.001 to 0.0483 mg/kg) measured at each site continues to be similar to baseline values and below the recommended guideline value for Urban Residential/Public Open Spaces (29 mg/kg) and National Parks/Areas with High Ecological Values (1.0 mg/L) (Tables 7&8).

Table 7. Mean (\pm SE) sediment metal results (mg/L) for surveys done between autumn 2018 ($n = 1$) and spring 2022 ($n = 2$).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Autumn 2019			Spring 2019		
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Aluminium	-	-	-	-	26,800	24,300 (700)	2,295 (365)	-	-	-
Antimony	-	-	-	-	<0.5	<0.5 (0)	<0.5 (0)	-	-	-
Arsenic	20	<5	<5	<5	4	6 (0.9)	1 (0.2)	3.90 (0.6)	2.75 (0.5)	2.65 (0.3)
Barium	-	110	60	<10	100	66 (4.5)	455 (447)	135 (15)	76.5 (7.5)	29.5 (1.5)
Beryllium	-	<1	1	<1	0.96	1.2 (0.0)	<0.5 (0)	1.20 (0.1)	1.01 (0.1)	<0.5 (0.00)
Boron	-	<50	<50	<50	2.9	0.8 (0.3)	<1 (0)	<1.0 (0.0)	<1.0 (0.0)	<1.0 (0.0)
Cadmium	1.5	<1	<1	<1	<0.5	<0.5 (0)	<0.5 (0)	0.43 ^A (0.2)	<0.5 (0.0)	<0.5 (0.0)
Chromium	80	23	21	3	21	23 (2.0)	3 (0.4)	21.0 (2.0)	13.5 (0.5)	6.3 (0.7)
Cobalt	-	8	6	<2	9	8 (1.9)	1 (0.1)	-	-	-
Copper	65	31	12	<5	28	11 (2.1)	2 (0.3)	30.0 (5.0)	6.1 (1.7)	9.0 (1.0)
Lead	50	91	44	<5	72	35 (0.0)	4 (0.2)	78.0 (32.0)	21.5 (0.5)	12.0 (1.0)
Manganese	-	45	69	16	32	80 (2.0)	7 (0.8)	85.0 (55.0)	50.0 (15.0)	32.5 (12.5)
Mercury	0.15	<0.1	<0.1	<0.1	<0.2	<0.2 (0)	<0.2 (0)	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)
Molybdenum	-	-	-	-	2.2	1.0 (0.4)	<0.5 (0)	-	-	-
Nickel	21	14	9	<2	16	9 (0.0)	1 (0.0)	20.5 (0.5)	10.6 (1.4)	3.85 (0.2)
Selenium Total	-	<5	<5	<5	1	1 (0.0)	<0.5 (0)	2.65 (1.4)	1.59 (0.9)	0.63 ^A (0.4)
Strontium	-	-	-	-	23	17 (4.5)	1 (0.1)	-	-	-
Vanadium	-	48	54	10	36	60 (9.5)	9 (0.9)	-	-	-
Zinc	200	93	96	17	100	64 (4.0)	14 (1.5)	119 (61.5)	29 (17.5)	74 (17.0)

*Interim Sediment Quality Guideline – Low (Trigger value) (ANZECC/ARMCANZ 2000)

^AFor any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01)

NB Aluminium, Antimony, Molybdenum, Strontium and Vanadium were not tested for by the Spring 2019 surveys because they were not required by the BMS (cf Biosis, 2018)

Table 7 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Autumn 2020			Spring 2020		
		AQ1	AQ4	AQ1	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Aluminium	-	-	-	-	-	-	-	-	-	-
Antimony	-	-	-	-	-	-	-	-	-	-
Arsenic	20	<5	<5	<5	1.90 (0.2)	3.4 (0.4)	5.1 (3.1)	1.90 (0.4)	3.4 (1.2)	2.4 (0.3)
Barium	-	110	60	<10	83 (15)	63.5 (3.5)	41.3 (31.7)	87.0 (33.0)	69.5 (9.5)	37.5 (9.5)
Beryllium	-	<1	1	<1	0.72 (0.1)	0.98 (0.0)	0.5 (0.3)	0.71 (0.2)	0.79 (0.1)	<0.5 (0.0)
Boron	-	<50	<50	<50	0.85 (0.4)	0.5 (0.0)	0.5 (0.0)	1.95 (0.4)	1.25 (0.2)	0.75
Cadmium	1.5	<1	<1	<1	0.25 (0.0)	0.25 (0.0)	0.3 (0.0)	<0.05 (0.0)	<0.5 (0.0)	1.0 ^B (0.5)
Chromium	80	23	21	3	14.5 (0.5)	18.5 (0.5)	12.9 (8.2)	13.5 (3.5)	13.0 (0.0)	6.2 (0.3)
Cobalt	-	8	6	<2	-	-	-	-	-	-
Copper	65	31	12	<5	16.5 (0.5)	11.0 (2.0)	16.7 (12.3)	16.5 (6.5)	7.9 (0.2)	7.2 (1.2)
Lead	50	91	44	<5	71 (5.0)	33.5 (3.5)	23.5 (15.6)	53.5 (10.5)	26.0 (1.0)	11.5 (0.5)
Manganese	-	45	69	16	38.5 (0.5)	66.5 (10.5)	49.5 (38.5)	56.5 (16.5)	52.5 (4.5)	31.0 (3.0)
Mercury	0.15	<0.1	<0.1	<0.1	0.10 (0.0)	0.10 (0.0)	0.1 (0.0)	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)
Molybdenum	-	-	-	-	-	-	-	-	-	-
Nickel	21	14	9	<2	10.7 (1.3)	8.65 (0.5)	5.4 (3.3)	11.5 (2.6)	6.5 (0.5)	2.8 (0.6)
Selenium Total	-	<5	<5	<5	0.70 (0.0)	0.44 (0.2)	0.6 (0.4)	0.63 ^B (0.4)	0.40 ^B (0.2)	<0.5 (0.0)
Strontium	-	-	-	-	-	-	-	-	-	-
Vanadium	-	48	54	10	25 (1.0)	41 (2.0)	36.0 (21)	23 (5.0)	32 (5.5)	19.0 (1.0)
Zinc	200	93	96	17	78 (6.0)	144 (46.5)	111.0 (79)	86 (24)	58 (6.0)	45.5 (19.5)

*Interim Sediment Quality Guideline – Low (Trigger value) (ANZECC/ARMCANZ 2000)

^A For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (eg. <0.02 taken as 0.01)

NB Aluminium, Antimony, Molybdenum, Strontium and Vanadium were not tested for by the Spring 2019 surveys because they were not required by the BMS (cf Biosis, 2018)

Table 7 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Autumn 2021			Spring 2021		
		AQ1	AQ4	AQ1	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Aluminium	-	-	-	-	-	-	-	-	-	-
Antimony	-	-	-	-	-	-	-	-	-	-
Arsenic	20	<5	<5	<5	3.65 (1.3)	6.10 (0.0)	4.30 (0.8)	14.55 (9.5)	3.5 (2.6)	2.85 (0.7)
Barium	-	110	60	<10	116.5(23.5)	99.5 (10.5)	68.0 (5.0)	74.5 (18.5)	48.0 (41.0)	84.5 (11.5)
Beryllium	-	<1	1	<1	1.20 (0.2)	0.87 (0.1)	0.50 ^A (0.2)	0.81 (0.2)	0.38 (0.4)	0.44 ^A (0.4)
Boron	-	<50	<50	<50	2.00 (0.9)	1.75 ^A (1.3)	1.40 ^A (0.9)	0.80 ^A (0.3)	<1 (0.0)	0.95 ^A (0.5)
Cadmium	1.5	<1	<1	<1	0.41 ^A (0.2)	<0.5 (0.0)	<0.5 (0.0)	<0.5 (0.0)	<0.5 (0.0)	<0.5 (0.0)
Chromium	80	23	21	3	24 (7.0)	24.5 (1.5)	13.0 (2.0)	17.5 (0.5)	12.7 (10.3)	12.0 (1.0)
Cobalt	-	8	6	<2	-	-	-	-	-	-
Copper	65	31	12	<5	23 (8.0)	13.5 (1.5)	12.8 (3.3)	13.0 (2.0)	6.55 (5.5)	12.3 (2.8)
Lead	50	91	44	<5	80 (50)	31.5 (2.5)	27.5 (7.5)	25.5 (4.5)	16.2 (12.9)	27.0 (7.0)
Manganese	-	45	69	16	28 (8)	150 (40)	46 (5)	95 (75)	57.1 (53)	27.5 (13.5)
Mercury	0.15	<0.1	<0.1	<0.1	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)	<0.2 (0.0)
Molybdenum	-	-	-	-	-	-	-	-	-	-
Nickel	21	14	9	<2	17.5 (3.5)	9.75 (2.3)	5.85 (1.4)	10.5 (3.6)	4.1 (3.4)	7.3 (2.8)
Selenium Total	-	<5	<5	<5	1.20 (0.00)	0.88 (0.00)	0.41 (0.2)	0.88 (0.3)	0.44 ^A (0.4)	1.18 ^A (0.9)
Strontium	-	-	-	-	-	-	-	-	-	-
Vanadium	-	48	54	10	10 (13)	56 (2.0)	31 (3.0)	34 (7.0)	32 (22.4)	26 (2.0)
Zinc	200	93	96	17	92 (68)	77 (14.0)	94.5 (35.5)	46 (22.0)	35 (28.2)	43 (16.0)

*Interim Sediment Quality Guideline – Low (Trigger value) (ANZECC/ARMCANZ 2000)

^A For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (eg. <0.02 taken as 0.01)

NB Aluminium, Antimony, Molybdenum, Strontium and Vanadium were not tested for by the Spring 2019 surveys because they were not required by the BMS (cf Biosis, 2018)

Table 7 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Autumn 2022 (5/5/22)			Autumn 2022 (31/5/22)		
		AQ1	AQ4	AQ1	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Aluminium	-	-	-	-	-	-	-	-	-	-
Antimony	-	-	-	-	-	-	-	-	-	-
Arsenic	20	<5	<5	<5	4.3	10	6	2.9	3.6	4.6
Barium	-	110	60	<10	140	150	61	87	71	52
Beryllium	-	<1	1	<1	1.2	1.7	0.61	0.84	0.83	<0.5
Boron	-	<50	<50	<50	3.7	5	1.8	2	1.8	1
Cadmium	1.5	<1	<1	<1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	80	23	21	3	23	49	11	17	20	9.9
Cobalt	-	8	6	<2	-	-	-	-	-	-
Copper	65	31	12	<5	24	32	14	19	14	13
Lead	50	91	44	<5	54	56	30	55	29	17
Manganese	-	45	69	16	28	320	66	25	110	41
Mercury	0.15	<0.1	<0.1	<0.1	<0.2	<0.2	<0.2	0.29	<0.2	<0.2
Molybdenum	-	-	-	-	-	-	-	-	-	-
Nickel	21	14	9	<2	17	23	5.1	13	8.8	4.2
Selenium Total	-	<5	<5	<5	3.4	3	1.3	1.1	0.68	0.57
Strontium	-	-	-	-	-	-	-	-	-	-
Vanadium	-	48	54	10	37	99	31	35	46	33
Zinc	200	93	96	17	48	220	73	76	96	56

*Interim Sediment Quality Guideline – Low (Trigger value) (ANZECC/ARMCANZ 2000)

^A For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (eg. <0.02 taken as 0.01)

NB Aluminium, Antimony, Molybdenum, Strontium and Vanadium were not tested for by the Spring 2019 surveys because they were not required by the BMS (cf Biosis, 2018)

Table 7 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2022 (10/10/22)			Spring 2022 (30/11/22)		
		AQ1	AQ4	AQ1	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Aluminium	-	-	-	-	-	-	-	-	-	-
Antimony	-	-	-	-	-	-	-	-	-	-
Arsenic	20	<5	<5	<5	1.9	3.6	9.8	6.1	4.1	2.1
Barium	-	110	60	<10	100	80	61	110	61	71
Beryllium	-	<1	1	<1	0.86	1	1.2	1.1	1.2	0.65
Boron	-	<50	<50	<50	4.4	2.6	4.2	1.7	<1	<1
Cadmium	1.5	<1	<1	<1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	80	23	21	3	19	24	22	56	14	7.3
Cobalt	-	8	6	<2	-	-	-	-	-	-
Copper	65	31	12	<5	20	15	25	36	6.7	5.4
Lead	50	91	44	<5	79	32	44	62	23	12
Manganese	-	45	69	16	57	130	62	53	78	74
Mercury	0.15	<0.1	<0.1	<0.1	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Molybdenum	-	-	-	-	-	-	-	-	-	-
Nickel	21	14	9	<2	14	11	9.9	25	6.3	3.4
Selenium Total	-	<5	<5	<5	0.62	0.61	1.1	1	0.54	<0.5
Strontium	-	-	-	-	-	-	-	-	-	-
Vanadium	-	48	54	10	24	48	67	35	40	21
Zinc	200	93	96	17	93	110	160	84	45	23

*Interim Sediment Quality Guideline – Low (Trigger value) (ANZECC/ARMCANZ 2000)

^A For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (eg. <0.02 taken as 0.01)

NB Aluminium, Antimony, Molybdenum, Strontium and Vanadium were not tested for by the Spring 2019 surveys because they were not required by the BMS (cf Biosis, 2018)

Table 8. Mean (\pm SE) sediment results for perfluorinated compounds between autumn 2018 ($n = 1$) and spring 2022 ($n = 2$).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2018			Autumn 2019		
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14	AQ1 ^C	AQ4	AQ14
Perfluorinated compound (mg/kg)										
PFHxS	-	0.0036	0.0007	<0.0002	0.0023 (0.00)	<0.001 (0.00)	<0.001 (0.00)	0.0037	<0.001 (0.00)	<0.001 (0.00)
PFOS	32	0.0444	0.0061	0.0005	0.0310 (0.01)	0.0049 (0.00)	<0.002 (0.00)	0.0220	0.0085 (0.01)	<0.002 (0.00)
PFOA	29	-	-	-	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001	<0.001 (0.00)	<0.001 (0.00)
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005	0.0333 (0.01)	0.0055 ^B (0.00)	0.002 ^B (0.00)	0.0257	0.0090 ^B (0.01)	0.0015 ^B (0.00)
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005	0.0369 ^B (0.01)	0.0096 ^B (0.00)	0.0058 ^B (0.00)	0.0329	0.0150 ^B (0.01)	0.0075 ^B (0.00)
Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2019			Autumn 2020		
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
Perfluorinated compound (mg/kg)										
PFHxS	-	0.0036	0.0007	<0.0002	0.0016 (0.00)	<0.001 (0.00)	<0.001 (0.00)	0.0005 (0.00)	0.0005 (0.00)	0.0005 (0.00)
PFOS	32	0.0444	0.0061	0.0005	0.0075 (0.01)	0.0062 (0.00)	0.0028 (0.00)	0.0115 (0.00)	0.0015 (0.00)	0.0052 (0.00)
PFOA	29	-	-	-	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005	0.0231 (0.08)	0.0067 ^B (0.00)	0.0033 ^B (0.00)	0.0120 (0.00)	0.0020 (0.00)	0.0057 (0.00)
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005	0.0281 ^B (0.08)	0.0117 ^B (0.00)	0.0083 ^B (0.00)	0.0170 (0.00)	0.0070 (0.00)	0.0107 (0.00)

*DEE (2016) - Urban residential/public open spaces

^A = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS

^B For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01), the Sum of PFHxS and PFOS and the Sum of PFAS.

^C Only one survey was undertaken at Site AQ1 in autumn 2019.

Table 8 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2020			Autumn 2021		
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14	AQ1 ^C	AQ4	AQ14
Perfluorinated compound (mg/kg)										
PFHxS	-	0.0036	0.0007	<0.0002	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 ^B (0.00)	<0.001 (0.00)	<0.001 (0.00)
PFOS	32	0.0444	0.0061	0.0005	0.0070 (0.00)	0.0022 ^B (0.00)	<0.002 (0.00)	0.016 (0.004)	0.006 (0.002)	0.004 (0.003)
PFOA	29	-	-	-	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005	0.0075 ^B (0.00)	0.0032 ^B (0.00)	0.0015 ^B (0.00)	0.0164 ^B (0.003)	0.0069 ^B (0.002)	0.0042 ^B (0.003)
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005	0.0125 ^B (0.00)	0.0082 ^B (0.00)	0.0065 ^B (0.00)	0.021 ^B (0.003)	0.0119 ^B (0.002)	0.0090 ^B (0.003)
Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2021			Autumn 2022		
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14	AQ1	AQ4	AQ14
PFHxS	-	0.0036	0.0007	<0.0002	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	0.0015 (0.0010)	<0.001 (0.00)	<0.001 (0.00)
PFOS	32	0.0444	0.0061	0.0005	0.0090 (0.00)	0.0030 ^B (0.00)	0.009 ^B (0.01)	0.0265 (0.0075)	0.0056 (0.0014)	0.0038 (0.0033)
PFOA	29	-	-	-	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005	0.0075 ^B (0.00)	0.0032 ^B (0.00)	0.0015 ^B (0.00)	0.0280 (0.01)	0.0056 (0.00)	0.0036 (0.0036)
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005	0.0168 ^B (0.01)	0.0089 ^B (0.00)	0.0148 ^B (0.01)	0.034 ^B (0.0075)	0.0111 ^B (0.0014)	0.0096 ^B (0.0031)

*DEE (2016) - Urban residential/public open spaces

^A = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS

^B For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01), the Sum of PFHxS and PFOS and the Sum of PFAS.

^C Only one survey was undertaken at Site AQ1 in autumn 2019.

Table 8 (Cont'd).

Indicator Variable	Trigger Value*	Baseline (Autumn 2018)			Spring 2022					
		AQ1	AQ4	AQ14	AQ1	AQ4	AQ14			
PFHxS	-	0.0036	0.0007	<0.0002	<0.0005 (0.00)	<0.0005 (0.00)	<0.0005 (0.00)			
PFOS	32	0.0444	0.0061	0.0005	0.0134 (0.01)	0.0008 ^B (0.00)	<0.003 (0.00)			
PFOA	29	-	-	-	<0.001 (0.00)	<0.001 (0.00)	<0.001 (0.00)			
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005	0.0139 ^B (0.01)	0.0013 ^B (0.00)	0.0038 ^B (0.00)			
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005	0.0035 ^B (0.00)	0.0046 ^B (0.00)	0.0091 ^B (0.00)			
Indicator Variable	Trigger Value*	Baseline (Autumn 2018)								
		AQ1	AQ4	AQ14						
PFHxS	-	0.0036	0.0007	<0.0002						
PFOS	32	0.0444	0.0061	0.0005						
PFOA	29	-	-	-						
Sum of PFHxS and PFOS	-	0.0480	0.0068	0.0005						
Sum of PFAS (WA DER List) ^{A,B}	-	0.0483	0.0068	0.0005						

*DEE (2016) - Urban residential/public open spaces

^A = PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTS and 8:2 FTS

^B For any site, where a value has been recorded as less than the detection limit, it was assigned a value of half the detection limit in order to calculate the mean (e.g. <0.02 taken as 0.01), the Sum of PFHxS and PFOS and the Sum of PFAS.

^C Only one survey was undertaken at Site AQ1 in autumn 2019.

3.3 Aquatic Macroinvertebrates

A total of 15 taxon were identified from edge habitat samples collected at Site AQ12 in spring 2022 (Survey 1: 12 taxon; Survey 2: 9 taxon) (Table 11, Appendix 3). Six taxa, Acarina (Water mites), Chironominae (True flies), Coenagrionidae (Damselflies), Chrysomelidae (Leaf beetles), Leptoceridae (Caddis flies) and Ostracods (Seed shrimp) were collected on both sampling occasions (Appendix 3).

Site AQ12 obtained an OE50 score of 0.30 (Survey 1) and 0.40 (Survey 2) during spring 2022 (Table 11, Figure 3), indicating that the macroinvertebrate assemblage at Site AQ12 was severely impaired (Band C) relative to reference sites selected by the AUSRIVAS model. The most recent OE50 scores were within the range of scores obtained since the baseline survey (Figure 3).

Similar to the findings of the previous survey, taxon with > 0.80 probability of occurrence but not collected at the Anzac Creek site were the true fly sub-family, Tanypodinae, and the aquatic bug family, Veliidae, on both sampling occasions. Notably, the mayfly family, Leptophlebiidae, which is commonly expected but not collected, was present at the time of Survey 2.

The SIGNAL2 scores obtained by the current survey ranged from 3.25 (Survey 1) to 4.74 (Survey 2) (Table 4). The presence of Leptophlebiidae during Survey 2 is likely to have contributed to the higher score obtained than for previous surveys (Table 4, Figure 4). In summary, SIGNAL 2 scores obtained for Site AQ12 have changed little over time and indicate that the macroinvertebrate assemblage at AQ12 has commonly been dominated by pollution-tolerant taxa since the commencement of sampling in autumn 2018 (Table 11, Figure 4).

Table 9. Total number of taxa, AUSRIVAS & SIGNAL 2 outputs for Site AQ12 ($n = 1$).

Survey	No Taxa	SIGNAL-2	OE50	Band
Autumn 2018	13	4.00	0.49	B
Spring 2018 – Survey 1	9	3.25	0.39	C
Spring 2018 – Survey 2	5	3.07	0.10	D
Autumn 2019 – Survey 1	10	2.69	0.41	C
Autumn 2019 – Survey 2	8	3.41	0.20	C
Spring 2019 – Survey 1	11	2.09	0.38	C
Spring 2019 – Survey 2	11	2.18	0.19	D
Autumn 2020 – Survey 1	19	3.00	0.68	B
Autumn 2020 – Survey 2	13	3.33	0.49	B
Spring 2020 – Survey 1	10	3.10	0.40	C
Spring 2020 – Survey 2	13	3.33	0.40	C
Autumn 2021 – Survey 1	13	3.38	0.49	B
Autumn 2021 – Survey 2	12	3.64	0.41	C
Spring 2021 – Survey 1	10	2.41	0.30	C
Spring 2021 – Survey 2	6	3.00	0.30	C
Autumn 2022 – Survey 1	13	3.86	0.49	B
Autumn 2022 – Survey 2	7	4.58	0.31	C
Spring 2022 – Survey 1	12	3.25	0.30	C
Spring 2022 – Survey 2	9	4.74	0.40	C




Figure 3. OE50 Taxa Scores and their respective Band Scores (B-D) for AUSRIVAS samples collected from edge habitat at Site AQ12 since autumn 2018.




Figure 4. Quadrant diagram showing SIGNAL 2 results for Site AQ12 sampled in Anzac Creek since autumn 2018.

3.4 Fish

Six species of fish were observed while electro-fishing at Site AQ12 in spring 2022 (Table 10). *Gambusia* (*Gambusia holbrooki*) were common and also caught in dip nets used to sample aquatic macroinvertebrates in spring 2022 (Table 6). Other species collected during spring 2022 included Short-finned (*Anguilla australis*) and Long-finned eels (*Anguilla reinhardtii*) (<30cm in length), small numbers of Common galaxias (*Galaxias maculatus*) and Striped gudgeon (*Gobiomorphus australis*), and the introduced species, Oriental waterloach (*Misgurnus anguillicaudatus*) and Goldfish (*Carassius auratus*) (Table 10).

In total, nine species of fish, including three introduced species, have been collected since sampling commenced in autumn 2018 (Table 10). All of the species caught are common within NSW (McDowall, 1996; DPI 2006; Howell and Creese, 2010). No threatened species of fish listed under the *NSW Fisheries Management Act, 1994* or the *Environment Protection and Biodiversity Conservation Act, 1999* were recorded.



Plate 13: Striped gudgeon collected at Site AQ12 (10/10/2022).

Table 7. Fish collected at Site AQ12 between autumn 2018 and spring 2019[#], spring 2020 and spring 2021.

Species	Common Name	Aut-18 (Biosis, 2018)	Sp-18	Aut-19	Sp-19	Sp-20	Aut-21	Sp-21	Aut-22	Sp-22
<i>Anguilla reinhardtii</i>	Long-finned eel	2	3	2	-	4	1	2	1	1
<i>Anguilla australis</i>	Short-finned eel	-	13	-	9	13	2	4	2	4
<i>Gobiomorphus australis</i>	Striped gudgeon	28	8	3	2	-	-	-	2	2
<i>Galaxias maculatus</i>	Common galaxias								8	
<i>Carassius auratus</i> *	Goldfish	-	2	-	-	-	1	-	-	1
<i>Gambusia holbrooki</i> *	Gambusia	328	100's	10's	10's	100's	100's	100's	10's	100's
<i>Hypseleotris compressa</i>	Empire gudgeon	13	-	-	-	-	-	-	-	-
<i>Misgurnus anguillicaudatus</i> *	Oriental weatherloach	-	-	-	1	-	-	-	2	1
<i>Hypseleotris cf galii</i>	Firetail gudgeon	-	-	-	1	1	-	-	-	-
<i>Unidentified sp.</i>								1	-	-

*Introduced species; [#]Fish were unable to be sampled at Site AQ12 within the autumn 2020 survey period due to instrument malfunction.

3.5 Limitations

- Only one Baseline survey was able to be sampled in autumn 2018, due to the May 2018 bushfire (Biosis, 2018);
- Due to restricted access through the construction worksite, it was not possible to access Site AQ1 on 30 May 2019 to undertake the 2019 autumn survey 2. Whilst the collection of replicate samples at each site provides important measures of variability in habitat characteristics and concentrations of toxicants, the results from Survey 1 and subsequent surveys were within the range of results collected by the Baseline survey. Therefore, it is considered that the missing sample did not detract from being able to interpret the findings of the 2019 autumn sampling event, and that the intent and outcomes of the MPES2 monitoring survey were achieved;
- Sampling required for the 2020 autumn event was unable to commence until late May 2020 due to COVID-19 related delays. The 2020 autumn survey 2 was further delayed due to repairs required to the Electrofisher;
- Water quality measurements collected during the biological sampling only provide a snapshot of quality at the time of sampling under the prevailing flow conditions;
- In the absence of external reference sites (i.e. similar sites but in systems not subject to the Project activities), it is not possible to account for changes in the variable examined that may occur naturally at a broader regional scale.

5.0 DISCUSSION

After construction of Warehouses 1, 3, 4 and 5, the location of Warehouses 6-8 was left as compacted pads in December 2020. Warehouses 6 and 7 earthworks commenced on 9/06/22. Since construction has commenced, water is managed in accordance with the approved CEMP and water is discharged via the sediment (SED) Basins and into Anzac Creek (via DP5 and DP7).

5.1 Aquatic Habitat & Environmental Conditions

Extensive cover by vegetation within the riparian zone and stream channel contributes stability to the majority of Anzac Creek. Recent heavy rain and bank overflows have caused some areas of active erosion, particularly at the downstream end of the refuge pool⁶, where large stands of Typha impeded flow, resulting in the overflow of water. Much of the scouring observed by Survey 1 (10 October 2022) had been re-colonised by exotic and native grasses and emergent macrophytes by Survey 2 (30 November 2022).

The noxious plant, Alligator Weed, is once again abundant at the most upstream site (Site AQ1) sampled on Anzac Creek. Large gaps in the Alligator Weed canopy were noted at Site AQ1 during spring 2020, coinciding with the presence of large numbers of Flea Beetles (*Arcola malloi*) seen feeding on the plants. Flea Beetles have commonly been used to control floating mats of Alligator Weed in some areas of Australia and overseas however, the beetles are unable to establish in terrestrial habitats (Julien and Bourne, 1988; van Oosterhout, 2007; DPI, 2019). It is likely that Alligator Weed has re-established the stream channel at Site AQ1 from plants that were able to maintain their position along the creek bank. Due to its highly invasive nature, Alligator weed is considered one of the greatest threats to waterways, wetlands, floodplains and irrigation systems in Australia (DPI, 2019). Long-term management of large infestations of Alligator Weed requires ongoing suppression and depletion.

Several indicators of water quality (reduced dissolved oxygen levels, elevated nitrogen, aluminium and copper) measured within the refuge pool continue to be outside recommended guideline values for the protection of aquatic life. Past studies done within the creek attributed

⁶ Flooding and erosion were noted at the downstream end of the refuge pool during autumn 2020

these impacts to historical contributions from Commonwealth Department of Defence Lands, industrial and urban run-off, among others (ALS, 2011; Biosis, 2018). While the Project may also be influencing water quality within the creek, measures of water quality sampled, including by this survey, continue to be comparable to those measured previously, including prior to the commencement of the Project. Additional degradation of water quality does not appear to have occurred since the Project related construction work began.

Concentrations of lead in sediments collected at the most upstream site sampled on Anzac Creek (Site AQ1) continue to exceed the guideline value (50 mg/kg) but not the baseline value measured by the BAEMP survey (91 mg/kg). Importantly, the levels of lead recorded at Site AQ1 have not increased since commencement of the Project.

Nickel measured in sediments at Site AQ1 during spring 2022 (25 mg/kg) marginally exceeded the upper ANZECC/ARMCANZ (2000) guideline level for the first time since sampling commenced. Given that heavy metals bound in sediments are not identified as specific contaminants of concern for the MPES2 Project (Biosis, 2018), and that Site AQ1 is situated upstream of potential inputs from the Project, no additional testing of heavy metals at Site AQ1 is considered necessary at this stage.

Notably, elevated concentrations of lead, nickel and zinc measured in sediments collected at Site AQ4 (situated immediately downstream of the Project area) were measured in sediments collected by one of the two surveys carried out during autumn 2022. Sediment metal results for samples collected at Site AQ4 during spring 2022 were within the ANZECC/ARMCANZ (2000) guideline values and BAEMP survey results.

Concentrations of PFOA (perfluoro-octanoic acid) and PFOS (perfluorooctane sulphonate) remain similar to baseline values and within the recommended Australian-derived guidelines for water and soil.

5.2 Biological Monitoring

The OE50 Taxa Scores and Bands continue to be indicative of a macroinvertebrate assemblage that is less diverse compared to reference sites selected by the AUSRIVAS model. Low values of the SIGNAL 2 score and the number of macroinvertebrate types were also indicative of a site suffering from one or more forms of human impact.

Lower than expected macroinvertebrate indices were not unexpected given exposure to multiple stressors (e.g., flow alteration, sedimentation, elevated levels of nitrogen and excessive algal and aquatic plant growth) that can adversely affect the condition of aquatic habitat. Anzac Creek is situated in a heavily disturbed and modified catchment, which has experienced substantial stress due primarily to historic and current activities. Dissolved oxygen levels within the refuge pool have consistently been below the ANZECC/ARMCANZ (2000) guideline, which is a sign of degradation.

Also notable was that several individuals (10's to 100's) of the introduced fish, *Gambusia* (*Gambusia holbrooki*), have consistently been observed within the refuge pool. *Gambusia* commonly thrive in disturbed habitats and still waters (McDowall 1996). Predation by *Gambusia* is listed as a Key Threatening Process by the NSW *Biodiversity Conservation Act 2016*, because of known effects on frogs, freshwater fishes and aquatic macroinvertebrates, among others.

Nevertheless, some pollution sensitive taxa were identified (including caddis fly, mayfly and dragonfly larvae) and nine species of fish, including six native species, have been collected, indicating that the creek continues to provide important habitat for aquatic species. Of the species collected, all are common within NSW.

6.0 CONCLUSION & RECOMMENDATIONS

Examination of the results from the spring 2022 monitoring event found no evidence of changes in the indicator variables (bed and bank stability, water quality, assemblages of aquatic macroinvertebrates and fish) that could be attributed to the Project works. Thus, in accordance with the Biodiversity Monitoring Strategy, no adaptive management contingency measure was triggered.

Recommendations include:

- Sampling of the stream health monitoring program is repeated in autumn 2023
- Land managers focus on containment and on-going suppression of the Alligator Weed infestation at Site AQ1 and programs such as public education to reduce the chance of unintentional human-assisted introductions of aquatic plants or fish (e.g. by using live bait, or by being released by aquaria).

7.0 REFERENCES

ALS (2011). *Assessment of the Sydney Intermodal Transport Hub, Moorebank*. Aquatic Ecology. Report prepared for Hyder Consulting Pty Ltd by Ecowise Australia Pty Ltd trading as ALS Water Resources Group.

Arcadis (2016). *Moorebank Precinct East – Stage 2 Proposal. Biodiversity Assessment Report prepared for SIMTA: Sydney Intermodal Terminal Alliance*. Part 4, Division 4.1, State Significant Development.

Australian and New Zealand Environment Conservation Council and Agriculture and Resource Management Council of Australia and New Zealand (2000). *National Water Quality Management Strategy: Australian and New Zealand Water Quality Guidelines for Fresh and Marine Water Quality*. Canberra, Australia.

Biosis (2018). *Baseline Aquatic Ecological Monitoring Autumn 2018*. Report for Arcadis Authors: Stone, L. & Cable, A., Biosis Pty Ltd, Sydney. Project no. 26648.

Boulton, A. J. (2003). Parallels and contrasts in the effects of drought on macroinvertebrate assemblages. *Freshwater Biology* 48: 1173–1185.

Chessman, B. (2003). *SIGNAL 2 – A Scoring System for Macroinvertebrates ('Water Bugs') in Australian Rivers*. Monitoring River Health Initiative Technical Report No. 31. Commonwealth of Australia, Canberra.

Chessman, B.C. (2003). New sensitivity grades for Australian river macroinvertebrates. *Marine and Freshwater Research*, 2003, 54: 95-103.

DEE (2016). *Commonwealth Environmental Management Guidance on Perfluorooctane Sulfonic Acid (PFOS) and Perfluorooctanoic Acid (PFOA)*. Department of the Environment and Energy.

DPI NSW (2007). *Key Fish Habitat Maps Sydney LGA*. Website:
https://www.dpi.nsw.gov.au/data/assets/pdf_file/0009/634347/PortStephens.pdf (Accessed November 2020).

DPI NSW (2013). *Policy and Guidelines for Fish Habitat Conservation and Management*. NSW Department of Primary Industries.

DPI NSW (2017). Leafy elodea (*Egeria densa*). Website:
<https://weeds.dpi.nsw.gov.au/Weeds/LeafyElodea> (Accessed February 2021).

DPI NSW (2019). *NSW WeedWise*. NSW Department of Primary Industries. Website:
<https://weeds.dpi.nsw.gov.au/Weeds/Alligator>. (Accessed February 2020)

GHD (2016). *Moorebank, NSW Environmental Management Plan*. Prepared for Department of Defence Former DNSDC.

Golder (2015). *Moorebank Precinct West (MPW): Site Contamination Summary Report - Stage 2 State Significant Development*. Prepared for Tactical Group on behalf of Sydney Intermodal Terminal Alliance.

Howell, T. and Creese, B. (2010). *Freshwater Fish Communities of the Hunter, Manning, Karuah and Macquarie-Tuggerah Catchments: a 2004 Status Report*. Industry and Investment New South Wales, Cronulla, New South Wales.

JBS&G Australia Pty Ltd (2016). *Moorebank Precinct East (MPE) - Stage 2 Proposal: Contamination Summary Report*. Prepared for Tactical Group on behalf of Sydney Intermodal Terminal Alliance.

Julien, M., Bourne, A. (1988) Alligator weed is spreading in Australia. *Plant Protection Quarterly* 3(3):91–95.

McDowall, R. M. (1996). *Freshwater Fishes of South-Eastern Australia*. 2nd.Edition. Reed Books, Chatswood, NSW.

- Ransom, G., Coysh, J., Nichols, S. (2004). AUSRIVAS User Manual. Website: <http://ausrivas.canberra.edu.au/Bioassessment/Macroinvertebrates/Manuals> and Datasheets/User Manual. Date Retrieved: 27 November 2006.
- Sainty, G., McCorkelle, G., Julien, M. H. (1998). Control and Spread of alligator weed, *Alternanthera philoxeroides*, in Australia: lessons for other regions. *Wetlands Ecology Management* 5: 195–201.
- Sainty, G. R., Jacobs, S. W. L. (2003). *Waterplants in Australia: A Field Guide*. 4th Edn. Sainty & Associates Pty Ltd, Potts Point.
- Stanford, J. A., Ward, J. V., Liss, W. J., Frissell, C. A., Williams, R. N., Lichatowich, J. A., Coutant, C. C. (1996). A general protocol for restoration of regulated rivers. *Regulated Rivers: Research & Management* 12: 391-413.
- Turak, E., Waddell, N., Johnstone, G. (2004). *New South Wales Australian River Assessment System (AUSRIVAS) Sampling and Processing Manual*. Department of Environment and Conservation, Sydney, Australia.
- van Oosterhout, E. (2007). *Alligator Weed Control Manual: Eradication and suppression of Alligator Weed (*Alternanthera philoxeroides*) in Australia*. NSW Primary Industries, Orange, Australia.
- Vilas, M. P., Marti, C. L., Adams, P., Oldham, C. E., Hipsey, M. R. (2017). Invasive macrophytes control the spatial and temporal patterns of temperature and dissolved oxygen in a shallow lake: A proposed feedback mechanism of macrophyte loss. *Frontiers in Plant Science* 8: 2097. doi: 10.3389/fpls.2017.02097

APPENDICES

Appendix 1 - GPS positions (UTMs) for stream monitoring sites (spring 2022).

Site Code	Easting	Northing
AQ1	308116	6240233
AQ4	308557	6240282
AQ8	309220	6240814
AQ12	309385	6241601
AQ13	309383	6241735
AQ14	309365	6241881

Datum: WGS 84, Zone 56H

Appendix 2 – Visual Assessment Scores

Appendix 2a – Ephemeral stream assessment results

	Autumn 2018		Spring 2018		Autumn 2019	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	88	Very Stable	75	Stable	80	Stable
AQ4	88	Very Stable	75	Stable	78	Stable
AQ8	91	Very Stable	93	Very Stable	93	Very Stable
	Spring 2019		Autumn 2020		Spring 2020	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	88	Very Stable	90	Very Stable	90	Very Stable
AQ4	80	Stable	88	Very Stable	89	Very Stable
AQ8	92	Very Stable	93	Very Stable	93	Very Stable
	Autumn 2021		Spring 2021		Autumn 2022	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	80	Very Stable	90	Very Stable	92	Very Stable
AQ4	89	Very Stable	89	Very Stable	90	Very Stable
AQ8	93	Very Stable	93	Very Stable	93	Very Stable
	Spring 2022					
Site	Score (%)	Category				
AQ1	92	Very Stable				
AQ4	92	Very Stable				
AQ8	94	Very Stable				

Appendix 2b – HABSCORE assessment results

	Autumn 2018		Spring 2018		Autumn 2019	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	27	Marginal	29	Marginal	32	Marginal
AQ4	28	Marginal	25	Marginal	25	Marginal
AQ8	41	Marginal	38	Marginal	38	Marginal
AQ12	55	Suboptimal	51	Suboptimal	53	Suboptimal
AQ13	21	Poor	23	Poor	21	Poor
AQ14	22	Poor	23	Poor	22	Poor
	Spring 2019		Autumn 2020		Spring 2020	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	30	Marginal	32	Marginal	27	Marginal
AQ4	26	Marginal	29	Marginal	28	Marginal
AQ8	41	Marginal	41	Marginal	41	Marginal
AQ12	51	Suboptimal	50	Suboptimal	53	Suboptimal
AQ13	19	Poor	21	Poor	22	Poor
AQ14	21	Poor	22	Poor	23	Poor
	Autumn 2021		Spring 2021		Autumn 2022	
Site	Score (%)	Category	Score (%)	Category	Score (%)	Category
AQ1	29	Marginal	31	Marginal	31	Marginal
AQ4	36	Marginal	38	Marginal	40	Marginal
AQ8	41	Marginal	41	Marginal	41	Marginal
AQ12	55	Suboptimal	55	Suboptimal	50	Suboptimal
AQ13	23	Poor	23	Poor	25	Poor
AQ14	24	Poor	24	Poor	25	Poor
	Spring 2022					
Site	Score (%)	Category				
AQ1	31	Marginal				
AQ4	39	Marginal				
AQ8	41	Marginal				
AQ12	53	Suboptimal				
AQ13	21	Poor				
AQ14	25	Poor				

Appendix 3 - Macroinvertebrate taxa collected at Site AQ12 in spring 2022 using the NSW AUSRIVAS protocol.

Taxa	Survey 1 (10 October 2022)	Survey 2 (30 November 2022)
Acarina	3	6
Chironomidae - Chironominae	7	14
Coenagrionidae	2	2
Chrysomelidae	1	1
Cyclopoida	1	0
Glossiphoniidae	1	0
Pleidae	1	0
Hydrobiidae	0	7
Hydroptilidae	0	1
Leptoceridae	1	12
Leptophlebiidae	0	1
Libellulidae	5	0
Lymnaeidae	1	0
Staphylinidae	1	0
Ostracod	1	2
Number of Taxa	12	9



APPENDIX F – MPE OPERATIONS INCIDENT REGISTER

Date of complaint	Complainant	Nature of complaint	Complaint status
Complaints as at 31 December 2022			
31/12/2022	Community member	Development impacts: Resident raised concern about the height of MPW warehousing and its impact on his views. Resident was advised of initiatives to reduce impacts for community and was advised of the public consultation that occurred related to the increased height of warehousing.	Closed
14/11/2022	CCC member	Construction schedule & upcoming works: CCC member (Casula resident) complained about helicopter lifting work continuing past standard construction hours. The project team investigated the incident with the relevant contractor, who has been instructed to implement measures to ensure that any future helicopter lifts do not exceed construction hours. Further, the team notified the complainant of upcoming helicopter lifting work in December.	Closed
10/10/2022	Local business	Flooding: Water entered the premises of a site neighbour during a heavy rainfall event. Site contractors have undertaken remediation works to repair, regrade and lift the bund to drain the area, pump out remaining water and revegetate the area to stabilise the bund. Contractors will continue to monitor the area to pump excess water as required.	Closed
20/09/2022	Community member	General project and noise: A Wattle Grove resident complained about noise and hours of operation at the site, and about the project more broadly. The complainant was advised further additional attended noise monitoring will be undertaken.	Closed
21/08/2022	Community member	Noise: A Wattle Grove resident complained about noise and hours of operation at the site, including out of hours works helicopter activity undertaken on site. The complainant was advised the works were an approved activity under the approved MPE Stage 2 Construction Noise and Vibration Management Plan (CNVMP) and noise monitoring undertaken as required by out of hours work consent identified noise levels were under the predicted levels outlined in the CNVMP. The complainant was also advised their observations of noise at other days/times are being investigated further through additional noise monitoring. The complainant was advised further additional attended noise monitoring will be undertaken.	Closed
18/8/2022	Community member	Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring. The complainant was advised further additional attended noise monitoring will be undertaken.	Closed

17/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
16/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
13/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
13/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
12/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
12/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
11/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed

10/8/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
31/7/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
30/7/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
29/7/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise and hours of operation at the site. The complainant was advised their observations are being investigated further through additional noise monitoring.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
28/7/2022	Community member	<p>Noise: A Wattle Grove resident made a complaint about truck and container movement noise at the site. The complainant was advised the project has approval to operate 24/7 within limits of the Operational Noise and Vibration Management Plan and the project undertakes ongoing noise management and monitoring, including permanent noise monitors. Further, the team notified the complainant that staged commencement of automated electric crane operations later this year which are expected to result in more environmentally friendly operations on site.</p> <p>The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
19/7/2022	Community member	<p>Noise: A Wattle Grove resident complained about noise emanating from the site, particular trucks and container movement noise. The complainant was advised the project has approval to operate 24/7 within limits of the Operational Noise and Vibration Management Plan and the project undertakes ongoing noise management and monitoring, including permanent noise monitors. Further, the team notified the complainant that staged commencement of automated electric crane operations later this year which are expected to result in more environmentally friendly operations on site.</p> <p>The complainant was advised further additional attended</p>	Closed

		noise monitoring will be undertaken.	
4/7/2022	Local business	<p>Flooding: Water entered the premises of a site neighbour during a heavy rainfall weather event (300mm +). Following an investigation, SIMTA contractors undertook cleaning of the site and repair to verges. Further work will be undertaken to repair swale damage.</p>	Closed
18/06/2022	Community member	<p>Noise: A resident in Wattle Grove made a complaint relating to container movement noise. The project team investigated and noise monitoring at the time described included some container noise which was within approved noise parameters for the site. As a result of the community member's observations, attended noise monitoring will be undertaken in the area to further explore (in addition to permanent noise monitoring already in place at locations determined by DPE). The complainant was advised further additional attended noise monitoring will be undertaken.</p>	Closed
10/06/2022	Community member	<p>Noise: A resident in Wattle Grove made a complaint about container movement noise. The project team investigated and noise monitoring at the time described included some container noise which was within approved noise parameters for the site. As a result of the community member's observations, attended noise monitoring will be undertaken in the area to further explore (in addition to permanent noise monitoring already in place at locations determined by DPE).</p>	Closed
26/04/2022	CCC member	<p>Noise: Complainant noted sound from a water pump has been operating 24/7 near the Georges River at the north of the site for about a week. The project team investigated the complaint and discovered the water level within the excavation works area had recently receded, causing the pump to function incorrectly. The complainant was informed acoustic blankets would be installed for additional noise attenuation and the pump would only be running during standard construction hours until they are in place. Further noise modelling will be undertaken before overnight pumping resumes.</p>	Closed
19/02/2022	CCC member	<p>Noise: Complainant noted weekend work was being carried out after 1pm Saturday. The complainant was advised a new extended weekend construction hours order had been issued by the NSW Minister for Planning and was supplied a copy of the order.</p>	Closed
11/01/2022	CCC member	<p>Noise: Complainant noted heavy vehicle noise late at night. No work was being undertaken on our project at that time, which complainant was advised.</p>	Closed
25/11/2021	Road user	<p>Condition of road: A motorist complained about potholes on Moorebank Avenue between East Hills railway line and Cambridge Avenue. The project team advised the motorist that the potholes are within the section of the road owned and</p>	Closed

		managed by the Department of Defence and was not related to the project. The complainant was directed to contact Department of Defence. (Issue not related to project).	
05/11/2021	Road user	Condition of road: A road user complained about the condition of Anzac Road. The project team investigated the specific location of Anzac Road and discovered this is an area of Anzac Road currently being upgraded by Liverpool City Council. This upgrade is unrelated to the project.	Closed
04/11/2021	CCC member	Dust: A CCC member reported dust coming from the southern end of Moorebank Precinct West. The project team reminded all contractors to ensure mitigation strategies continue to be implemented appropriately. Further discussions about dust management from active stockpiles were conducted with the overall project team. The complaint occurred on a day where the wind was 80-90km/hr – while water carts were suppressing dust on the day, it was impossible to eliminate the dust due to these high wind speeds.	Closed
01/11/2021	Community member	Noise: A resident in Wattle Grove complained about night works noise coming from Anzac Road. The project team discovered that these works are undertaken by Liverpool City Council and advised the resident to contact council. (Issue not related to project).	Closed
28/10/2021	Road user via Liverpool City Council	Condition of road: Liverpool City Council on behalf of road users complained about the condition of Bapaume Road, Moorebank. The project team is investigating ways to temporary remedy potholes and conditions of the road where possible. Please note this is a local controlled council road.	Closed
25/10/2021	Community member	Noise: A resident complained about noise coming from the Moorebank Intermodal Terminal direction. The project team acknowledged the complainant's concerns and requested more information about the noise so the team could carry out further investigation to identify the source. No further information was provided by the complainant, and project teams confirmed that no out of hours works were undertaken at the time by Moorebank Intermodal Terminal.	Closed
16/10/2021	Community member	Noise: A resident in Wattle Grove complained about night works noise. The project team investigated the complaint and discovered that night works (asphalting) were undertaken by nearby Holsworthy Army Barrack. Stakeholder was advised and encouraged to provide additional detail for future noise issues. (Issue not related to project.)	Closed
09/09/2021	CCC member	Noise: A CCC member complained about trucks beeping noise from a heavy vehicle in the early hours. The project team investigated the noise and discovered that it came from a Fire & Rescue NSW truck inspecting a local business premises. (Issue not related to project.)	Closed
07/09/2021	Community member	General project: A resident in Glenfield complained about the height of warehousing on MPW hindering his cityscape view. The project team provided information to assist complainant understanding of works currently underway and those planned and approved for the near future.	Closed

17/07/2021	Road user	Vehicle Damage: A motorist reported a pothole on Anzac Road, east of Anzac Creek. The project team advised that the pothole was within the section of the road owned and managed by the Department of Defence and was not related to the project. The complainant was directed to DoD. (Issue not related to project.)	Closed
14/07/2021	Road user	Vehicle Damage: A motorist reported windscreen damaged by a rock from a truck on Moorebank Avenue. The project team investigated the claim and discovered the truck was not working on the project on the day of the incident. The motorist was directed to contact the truck company directly. (Issue not related to project.)	Closed
14/05/2021	Road user	Driver behaviour: Site neighbour advised that vehicle leaving site failed to completely stop moving at a stop sign. SIMTA contractors issued road safety to relevant team members.	Closed
13/05/2021	Community member	Noise: A resident from East Moorebank complained of OOH excavator noise during a one-month period. Further information was requested from the complainant, but no response was provided. Investigations indicated the noise was not related to the project.	Closed
06/05/2021	Local Business	Water/Flooding: Site neighbour advised that water was flowing from SIMTA property into culvert situated along fence line on private property. SIMTA introduced measures to help prevent runoff during heavy rainfall.	Closed
13/04/2021	Road user	Traffic lights: A road user complained about traffic congestion on Moorebank Avenue causing major delays. Roads and Maritime Services advised the light sequencing system was faulty. The project team had also directly reported the issue to TfNSW. (Issue not related to project.)	Closed
08/04/2021	Local Business	Water/Flooding: Advised by site neighbour that a water hose situated on SIMTA property was leaking. The project team inspected the hose and repaired it.	Closed
29/03/2021	Road user	Traffic lights: A road user complained about traffic congestion on Moorebank Avenue causing major delays. Roads and Maritime Services advised the light sequencing system was faulty. (Issue not related to project.)	Closed
29/03/2021	Road user	Traffic lights: A road user complained about traffic congestion on Moorebank Avenue causing major delays. Roads and Maritime Services advised the light sequencing system was faulty. (Issue not related to project.)	Closed
22/03/2021	Local Business	Water/Flooding: Water entered the premises of a site neighbour during heavy rainfall. As a gesture of goodwill, SIMTA offered to pay for the clean-up.	Closed

09/01/2021	CCC member	Noise: A CCC member complained about trucks tailgates making noise during the delivery of material to the site. The project team investigated the complaint and noted that the complaint related to trucks operating during standard construction hours and within approval conditions.	Closed
12/12/2020	CCC member	Noise: A CCC member complained about noise from night work. The project team acknowledge the CCC member's concerns and informed that they have amended the work methodology in response to previous complaints. The team advised they have moved the out-of-hours work to a section of the site located further away from homes in Casula, endeavouring to ensure all plant and machinery on MPW uses non-tonal reversing sounders. Furthermore, the project team also introduced several initiatives to reduce the impact of night works. Noise monitoring indicates that these initiatives appear to be working in helping reduced noise impacts from night works.	Closed
10/12/2020	Community member	Dust: A community member complained about dust impacts on her home. The project team outlined the measures used to mitigate the impact of dust; including frequent use of dust suppression vehicles, continually monitoring dust levels and work practices being altered during strong winds. The project team apologised the community member for any impacts.	Closed
09/11/2020	CCC member	Noise: A CCC member visited BMD gate on MPW and complained about noisy night work. The site supervisor discussed new noise mitigation measures had been put in place for the night work and the CCC member agreed the noise level had dropped. The supervisor also explained to the CCC member that ongoing toolbox talks with contractors/drivers on the need to keep noise levels down, especially with the use of horns and closing tailgates. The CCC member agreed that everyone was doing their best to keep noise levels down.	Closed
04/11/2020	Road user	Truck driver behaviour: A road user complained about an interaction with a truck driver on Moorebank Avenue. The project team investigated the complaint and dashcam footage was inconclusive in terms of the account of the incident. The project team also discussed with the truck driver the importance of always ensuring road safety and road rules are adhered to when entering and leaving site. The project team apologised the road user for any concerns caused by the incident.	Closed

22/10/2020	CCC member	<p>Noise:</p> <p>A CCC member complained about noisy night work. The project team acknowledge the CCC member's concerns and advised that they have amended the work methodology in response to his expressing dissatisfaction with the level of out-of-hours work noise. The team advised they have moved the out-of-hours work to a section of the site located further away from homes in Casula. In addition, the project team also introduced additional noise monitoring to help confirm noise sources. Feedback from the CCC member indicated that this eliminated the noise issues he had been experiencing.</p>	Closed
20/10/2020	CCC member	<p>Dust:</p> <p>A CCC member complained about dust coming up from the northern end of MPW. The project team investigated the complaint and informed the CCC member they could not conclusively identify any work that caused the dust complaint reported. The project team organised additional street sweeping and dust suppression vehicles to mitigate any possible dust issues.</p>	Closed
15/10/2020	Community member	<p>A resident in Casula complained about construction noise. The project team acknowledge the resident's concerns and advised that they have amended the work methodology in response to residents expressing dissatisfaction with the level of out-of-hours work noise. The team did this by relocating the out-of-hours work to a section of the site located further away from homes in Casula. In addition, the project team also introduced additional noise monitoring to help confirm noise sources.</p>	Closed

14/10/2020	Community member	<p>Noise:</p> <p>Two residents in Casula complained that they could hear loud metallic bangs at night. The project team acknowledged the residents' concerns and advised that the "banging" noises were determined to be caused by tipper trucks' tailgates delivering crushed sandstone to the site during extended hours. The team reiterated to drivers that they should take care to ensure their tailgates closed as quietly as possible after they deposited their load on-site. In addition, the project team relocated the out-of-hours work to a section of the site further away from homes in Casula and introduced additional noise monitoring. Feedback from</p>	Closed
------------	------------------	---	--------

		the community indicated that this eliminated the noise issues they had been experiencing.	
09/10/2020	Community member	Noise: A resident in Wattle Grove complained that he could hear hydraulic excavator or similar making loud noises at night. The project team investigated the complaint and informed the resident that there had not been any night-time activity on the site other than out-of-hours deliveries of crushed sandstone to Moorebank Precinct.	Closed
24/09/2020	Neighbour	Traffic lights: A representative of the Department of Defence complained about the traffic light timing at the intersection of Moorebank Ave and Frank Partridge Drive. Roads and Maritime Services advised that the signals operate on an auto-sensor system. Complainant was provided RMS details to advise of traffic delays that may require adjustment to the signalling.	Closed
24/09/2020	Community member	Noise: A resident in Casula complained about the noise generated by nightworks. The project team investigated and informed the resident that the noise was caused by trucks delivering crushed sandstone to the site during extended hours. The project team apologised for the inconvenience caused and reminded the contractor of the importance of minimising the noise created by this work.	Closed
21/09/2020	CCC member	Noise: A CCC member complained about noisy night work, including jackhammering. The project team investigated and confirmed that no work of high-impact nature caused the excessive noise claimed. The only work which used plant machinery and a bulldozer was the ongoing importation of materials to site.	Closed
15/09/2020	Community member via DPIE	Dust: A community member complained via DPIE about rubbish and sand on Moorebank Avenue. The project team organised additional street sweeping and dust suppression.	Closed
02/09/2020	Community member	Noise: A resident in Casula complained that he could hear loud metallic bangs at night. The project team investigated the complaint and informed the resident that the noise was likely caused by a truck's tailgate closing after it delivered crushed sandstone to the site during extended hours. The project team apologised for the inconvenience caused and reminded the contractor of the importance of minimising the noise created by this work.	Closed

02/09/2020	Community member	<p>Vehicle Damage:</p> <p>A motorist reported that a pothole on Moorebank Avenue caused damaged to her car. The project team investigated the complaint and discovered that the pothole was within the section of the road owned and managed by the Department of Defence. The complainant was directed to DoD to discuss further.</p>	Closed
26/08/2020	CCC member	<p>Noise:</p> <p>A CCC member complained about loud metallic bangs from trucks' tailgate while unloading crushed sandstone to site. The project team investigated the complaint and believed that the noise might have been caused by a truck's tailgate closing after it had tipped its load. The project team reminded the contractor of the importance of this work being carried out more quietly in future and has also been carrying out noise monitoring of this work.</p>	Closed
25/08/2020	Community member	<p>Environmental impacts:</p> <p>A resident in Casula complained about the height of the proposed Woolworths warehousing on MPW affecting the view from his backyard. The project team advised the resident the proposal was open for public consultation and directed him to the online information link to provide a submission detailing his concerns.</p>	Closed
24/08/2020	Community member	<p>Condition of road:</p> <p>A member of the community complained about her vehicle being damaged by the pothole in Moorebank Avenue south of the East Hills rail line. The project team investigated the complaint and discovered that the pothole is in the area owned and managed by Department of Defence and advised her to raise her concerns with DoD.</p>	Closed
18/08/2020	CCC member via DPIE	<p>Environmental impacts:</p> <p>CCC member complained via DPIE that the colour scheme of the IMEX crane located on the Moorebank Precinct East site is considered visually intrusive. The project team confirmed to the complainant that this is the final colour scheme of the equipment.</p>	Closed
17/08/2020	Community member	<p>Condition of road:</p> <p>A community member complained about a pothole in Moorebank Avenue. The project team investigated the location of the pothole and found that it is in the area owned and managed by Department of Defence and advised the resident to contact the DoD.</p>	Closed
27/05/2020	CCC member	<p>Noise:</p> <p>CCC member noted that noise was audible until 8.30 pm on 26/5 as trucks delivered materials to the worksite. Project team confirmed that this is permitted by project approvals.</p>	Closed
20/04/2020	CCC member	<p>Lighting:</p> <p>CCC member asked that on-site lighting be trimmed down as one unit is directing light towards his home. Project team adjusted the relevant lighting, including light shields and further engaged with complainant to ensure temporary lighting units were not placed in locations that directed light towards his home.</p>	Closed
13/03/2020	Community member via DPIE	<p>Vegetation:</p> <p>Resident claimed that Aboriginal Scar trees were being removed from site. Project team confirmed and provided evidence that this had not occurred.</p>	Closed
10/03/2020	Community member via Liverpool City Council	<p>Condition of road:</p> <p>Local resident observed potholes on Moorebank Ave near Anzac Avenue and wanted the potholes repaired. Project team worked with LCC to identify and repair potholes.</p>	Closed

24/02/2020	Community member	Environmental impacts: Request that traffic controllers stop feeding bread to the cockatoos. Personnel ceased doing so immediately.	Closed
18/02/2020	Local business	General construction: Noting runoff of water from site detention basins following 450mm rainfall storm event. Project team confirmed that this is in line with project approvals.	Closed
22/01/2020	Community member	General construction: Stacked containers wall fell during supercell storm. Project team reduced height of stack and altered stacking method to further reinforce the noise wall.	Closed
22/01/2020	Community member	General construction: Stacked containers wall fell during supercell storm. Project team reduced height of stack and altered stacking method to further reinforce the noise wall.	Closed
2019 Complaints			
27/11/2019	RAID via DPIE	Dust: RAID member claimed dust that had settled on outdoor furniture was produced by project construction. No further evidence was able to be supplied.	Closed
25/11/2019	Local business	Condition of road: Roadside bollards damaged by turning truck. Project team repaired bollards.	Closed
25/10/2019	Community member via DPIE	Dust: Resident noted dust issues affecting his home and pool, as well as Moorebank Avenue. Project team noted dust mitigation and management protocols that are in place.	Closed
11/10/2019	Road user	Condition of road: Three pot holes on the road approaching the bridge on Cambridge Ave, Moorebank. Project team reported potholes to road owner.	Closed
7/09/2019	Road user	Vehicle damage: Road user reported that her vehicle was damaged by site fencing during heavy wind. Investigation by relevant insurance agency determined that the damage had been existing on the vehicle.	Closed
2/09/2019	Community member	Dust: Resident noted dust issues affecting his home. Project team noted dust mitigation and management protocols that are in place.	Closed
21/08/2019	Community member	Noise: Complainant reported excessive night-time noise over three nights, which they believed to have been caused by project construction. Project team confirmed that construction took place on only two of the three dates, and that the activities reported as occurring around 2am had concluded by midnight. Project team was able to ascertain that M5 Motorway roadworks were also carried out on the dates in question.	Closed
21/08/2019	Community member	Noise: Complainant reported excessive night-time noise, which they believed to have been caused by project construction. Project team confirmed that construction took place on the reported date, with M5 Motorway roadworks also carried out on the date in question.	Closed
20/08/2019	Community member	Noise: Complainant reported excessive night-time noise, which they believed to have been caused by project construction. Project team confirmed that construction took place on the	Closed

		reported date, with M5 Motorway roadworks also carried out on the date in question.	
17/08/2019	Community member	Noise: Complainant reported excessive night-time noise, which they believed to have been caused by project construction. Project team confirmed that construction took place on the reported date, with M5 Motorway roadworks also carried out on the date in question.	Closed
16/08/2019	Community member	Noise: Complainant reported excessive night-time noise, which they believed to have been caused by project construction. Project team confirmed that construction took place on the reported date, with M5 Motorway roadworks also carried out on the date in question.	Closed
18/07/2019	Community member	Water use: Repeat of 9/7/19 complaint, project team reiterated that water use was legal, approved, paid for and only took place when captured rainwater was unavailable.	Closed
16/07/2019	Community member	Truck movements: Resident noted heavy vehicle use of Anzac Road in exceedance of weight limit. Was unable to provide any registration number or other identifying features of the vehicles he witnessed.	Closed
9/07/2019	Community member	Water use: Complainant witnessed project water suppression tankers filling up from Sydney Water pumping station and alleged water was being stolen. Project team confirmed that this was approved under licence by Sydney Water, that the water was paid for and that mains refilling only took place when project water basins were empty.	Closed
2/07/2019	Local business	Condition of road: Complainant noted dirt "tracking" from worksite onto Bapaume Road and dirt in drains from site runoff. Project team cleaned Bapaume Road with street sweeper, improved site features to reduce tracking, cleaned gutters and pumped out roadside drains.	Closed
28/06/2019	Community member	Water use: Complainant witnessed project water suppression tankers filling up from Sydney Water pumping station. Project team confirmed that this was approved under licence by Sydney Water and that mains refilling only took place when project water basins were empty.	Closed
20/05/2019	Community member via DPIE	Noise: Complainant reported hearing an 'evacuation warning siren'. Project team was unable to identify a source of the noise within the worksite.	Closed
9/04/2019	Road user via Transport for NSW	Condition of road: Road user reported a "lip" in the road surface above the new rail underpass. Project team confirmed this was not the final road surface and that a weekend road closure to apply the final surface was upcoming.	Closed
3/04/2019	RAID via Liverpool City Council	Condition of road: Complainant reported localised flooding on the road along Moorebank Ave and its effect on road users. Project team worked with Liverpool City Council to clear drains, and confirmed that a new drainage system delivered with the Moorebank Ave upgrade would resolve this issue.	Closed
5/03/2019	Community member	Consultation:	Closed

		Complaint about lack of notification for upcoming helicopter movements. Project team confirmed that a letterbox notification was delivered across an area twice the size of that required by approval condition and the complainant resided outside that area. Also advised that all project notifications are made available on the project website.	
15/02/2019	Community member	Noise: Complainant reported noise being produced on-site before 7am start of works. Project team reminded contractors about noise requirements and ensuring staff arrival noise was minimised.	Closed
2018 Complaints			
23/11/2018	Road user	Condition of road: Road user reported a near-miss on Moorebank Avenue attributed to vehicle swerving to avoid a pothole. Project team arranged repair of pothole.	Closed
6/11/2018	Community member	Worker behaviour: Complainant reported contractor parking on property. Project team reminded work crews of respectful interface with neighbours and community.	Closed
5/11/2018	Community member	Truck movements: Resident noted heavy vehicle use of Anzac Road in exceedance of weight limit. Provided vehicle details and subcontractor was reminded of approved truck travel routes.	Closed
25/10/2018	Road user	Vehicle damage and condition of road: Road user reported that two tyres on his vehicle were burst by Moorebank Ave pothole. Project team arranged reimbursement of the cost of two new tyres.	Closed
22/10/2018	Road user via Liverpool City Council	Vehicle damage: Liverpool City Council received advice of damage to two vehicles caused by Moorebank Ave road surface. Project team referred complainants to relevant insurance agency.	Closed
19/10/2018	Community member via Sydney Trains	Truck movements: Trucks producing dust and blocking entry to Sydney Trains maintenance facility. Project team met with Sydney Trains, erected signage advising trucks not to stop in designated areas and increased dust suppression on entry road.	Closed
3/10/2018	Road user	Condition of road: Cyclist advised of dissatisfaction with arrangements for cyclists on Moorebank Avenue during construction and identified safety hazard of damaged signposts. Project team confirmed that footpath that had closed was not a cycle path and use by cyclists was not legally permitted. Project team advised of the approved method for cyclists to navigate during construction, including using road traffic lanes as permitted by the road rules, and ensured dangerous signposts were removed.	Closed
21/9/2018	Local business	Condition of road: Roadside bollards damaged by turning truck. Project team repaired bollards.	Closed
10/9/2018	Community member	General project: Complainant expressing disgust in the SIMTA project and asking to see proof of approvals from the Land and Environment Court. Project team provided relevant approvals.	Closed
27/8/2018	Community member	Dust: Reiteration of earlier complaint.	Closed
24/8/2018	Community member via DPIE	Environmental impacts:	Closed

		Resident raised concerns about vegetation clearing beside Moorebank Avenue and asked whether approval had been sought. Project team confirmed this work had been approved and provided relevant approval documents.	
23/8/2018	Road user	Condition of road: Complaint about dust and debris on Moorebank Ave. Project team advised of systems in place to manage dust/dirt and regular sweeping of the road surface. Project team reviewed dust suppression measures as a result of this and two other complaints and introduced an additional mitigation measure – spraying a polymer binder to seal dirt that would remain exposed long-term.	Closed
23/8/2018	Community member	Condition of road: Complaint about dust and debris on Moorebank Ave. Project team advised of systems to manage dust/dirt and regular sweeping. Project team reviewed suppression measures as a result of this and two other complaints and introduced an additional mitigation measure – spraying a polymer binder to seal dirt that would remain exposed long-term.	Closed
21/8/2018	Community member	Dust: Complainant reported his house and car were being regularly made dirty by dust caused by construction and sought compensation for cleaning that he had been carrying out. Project team reviewed dust suppression measures as a result of this and two other complaints and introduced an additional mitigation measure – spraying a polymer binder to seal dirt that would remain exposed long-term.	Closed
8/8/2018	Road user	Traffic: Complainant reporting delays on Moorebank Ave caused by the management of project's traffic control. Traffic controllers were advised to ensure priority was given to vehicles travelling on Moorebank Ave during peak periods.	Closed
6/8/2018	Community member	Damage to property: Concrete slurry was left. Construction team cleaned this.	Closed
12/7/2018	Community member	Noise: Casula resident complaint about beeping noises before 7am. Project team confirmed no site vehicles have reversing "beepers" fitted, and reminded crews to arrive quietly.	Closed
2/7/2018	Community member	Condition of road: Resident advised on Moorebank Ave potholes. Project team organised for road to be repaired.	Closed
26/6/2018	Community member via Liverpool City Council	General construction: Temporary reinstatement of footpath with asphalt viewed by pedestrian as insufficient. Requested better permanent surface. This was provided after construction was completed in the area.	Closed
17/6/2018	Community member	Truck movements: Resident had observed trucks parking alongside Anzac Road so drivers could frequent take-away food store. Also noted exceedance of Anzac Rd weight limit and claimed vehicles were parking in a No Stopping zone. Project team investigated and confirmed that roadside parking in the relevant section of Anzac Rd was legal, but ensured truck drivers were reminded not to block footpath when parking and that Anzac Rd past fire station carried a weight limit.	Closed
28/5/2018	Community member	General project: General Concerns around the amount of trucks that will be on local roads in the coming years. Complainant commented that the trucks are too noisy, and she believes they are	Closed

		speeding, especially on her street. Project team advised of project benefits around reduction of heavy vehicle movements and investigated claim re truck speeding on complainant's street. Complainant lives on the northern side of Moorebank in an area not used by project vehicles.	
28/5/2018	Community member	General project: Caller advised that she received a letter re Moorebank Intermodal Terminal Facility and she would like more information. Resident lives on Junction Rd, Moorebank, and has many concerns around traffic and project works impacting on Junction Rd. Project team provided additional information on project.	Closed
24/5/2018	Local business	Truck movements: Complaint about trucks parking on nature strip outside business's premises. Nature strip was fenced off to ensure trucks were unable to park at that location.	Closed
16/5/2018	Road user	Vehicle damage: Complainant's vehicle was sprayed with a substance from a project vehicle. Project team arranged repair of the vehicle.	Closed
4/4/2018	Community member	General project: Complainant generally opposes the project. Project team noted the complaint.	Closed
2/3/2018	Community member	Dust: Caller advised of large plume of dust going high into the air, viewed from Casula. Project team spoke with demolition crews and was unable to identify cause or confirm this was related to the project.	Closed
1/3/2018	Community member	Environmental impacts: A resident advised they had provided EPA with photos of what they say is a sediment control incident. Project team liaised with EPA to resolve matter.	Closed
21/2/2018	Community member	Lighting: Report that temporary traffic lights are left on all night. Project team resolved.	Closed
16/2/2018	Community member via DPIE	Noise: Resident alleged that loud banging noise was audible at 5am. Project team confirmed no work was underway on site at that time.	Closed
8/2/2018	Community member	General project: Complaint made about ignoring community feedback. Project team noted this complaint.	Closed
5/2/2018	Community member	Traffic: Complainant reporting delays on Moorebank Ave caused by the management of project's traffic control. Traffic controllers were advised to ensure priority was given to vehicles travelling on Moorebank Ave during peak periods.	Closed
19/1/2018	Community member via DPIE	Noise: Resident alleged that loud banging noise was audible at 4.25am. Project team confirmed no work was underway on site at that time.	Closed



APPENDIX G - COMPLIANCE REPORT DECLARATION FORM

COMPLIANCE REPORT DECLARATION

Project Name	Moorebank Logistics Park (MLP) – East Precinct
Project Application Number	SSD 6766 & SSD 7628
Description of Project	Moorebank Logistics Park aims to streamline the freight logistics supply chain from port to store, deliver savings to businesses and consumers, and help service the rapidly growing demand for imported goods in south-west Sydney. It is located approximately 27 kilometres (km) south-west of the Sydney Central Business District and approximately 26 km west of Port Botany within the Liverpool Local Government Area. The MLP is divided into an East Precinct and a West Precinct, located east and west of Moorebank Avenue respectively. The East Precinct includes the 24/7 operation of an import-export terminal (IMEX), rail link connecting to the South Sydney Freight Line (SSFL), warehousing and distribution facilities and freight village.
Project Address	Moorebank Logistics Park, Moorebank, NSW, 2170
Proponent	Qube Holdings Limited (ACN: 149 723 053)
Title of Compliance Report	Moorebank Logistics Park East Precinct – Operation Compliance Report
Date	Friday, 24 February 2023

I declare that I have reviewed relevant evidence and prepared the contents of the attached Compliance Report and to the best of my knowledge:

- the Compliance Report has been prepared in accordance with all relevant conditions of consent;
- the Compliance Report has been prepared in accordance with the Compliance Reporting Post Approval Requirements;
- the findings of the Compliance Report are reported truthfully, accurately and completely.
- due diligence and professional judgement have been exercised in preparing the Compliance Report; and
- the Compliance Report is an accurate summary of the compliance status of the development.

Notes:

- Under section 10.6 of the Environmental Planning and Assessment Act 1979 a person must not include false or misleading information (or provide information for inclusion in) a report of monitoring data or an audit report produced to the Minister in connection with an audit if the person knows that the information is false or misleading in a material respect. The proponent of an approved project must not fail to include information in (or provide information for inclusion in) a report of monitoring data or an audit report produced to the Minister in connection with an audit if the person knows that the information is materially relevant to the monitoring or audit. The maximum penalty is, in the case of a corporation, \$1 million and for an individual, \$250,000; and
- The Crimes Act 1900 contains other offences relating to false and misleading information: section 307B (giving false or misleading information – maximum penalty 2 years' imprisonment or 200 penalty units, or both).

COMPLIANCE REPORT DECLARATION

Name of Authorised Reporting Officer	██████████
Title	MD Possum Environmental Consulting
Signature	████████████████████
Qualification	Bachelor of Science – Environmental Science
Company	Possum Environmental Consulting
Company Address	2 Carole Avenue, Baulkham Hills NSW 2153